



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27243



WO #: 27243

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11324

Stock Desc: 2027 TT KZ-RV SPORTSMEN 291BHK

Model: 291BHK

Serial #: 4EZTS2921V5053791

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 02 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: LOTS OF METAL DEBRIS ON BOTH BUNK BED MATTRESS. THESE PIECES ARE STUCK INTO THE MATTRESS AND VERY SHARP

CAUSE: NOTED ON DAF

CORRECTION: REMOVE BOTH MATTRESS TO VACUUM AND PICK THE METAL OFF, CLEAN BUNK AREA BEFORE PUTTING MATTRESS BACK  
LABOR .50

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: BLACK STAINS ON CABINET DOOR NEXT TO TABLE AND WALL

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREAS AND COLOR BLEND TO MATCH  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: SCREW HOLE ON WALL IN BATHROOM SHOWING AT THE TOWEL HANGER. AS WELL AS THE TOWEL HANGER HAS A STAIN ON IT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE TOWEL HANGER, FILL HOLE, COLOR AND BLEND AREA, REINSTALL TOWEL HANGER.  
CLEAN AND COLOR BLEND THE STAINED AREA ON THE TOWEL HANGER  
LABOR FOR BOTH .40

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: 2 STAINS ON BATHROOM CEILING AND MOLDING

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THE AREAS  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: CORNER MOLDING NOT FLUSH ON WALL AND STICKING OUT

CAUSE: NOTED ON DAF

CORRECTION: CORNER TRIM WILL NEED TO BE MADE LAY CORRECT ON CORNER  
ADD PIN NAILS TO TRIM  
LABOR .40

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: SCRATCH ON KITCHEN CABINET ABOVE THE TABLE

CAUSE: NOTED ON DAF

CORRECTION: FIIL, COLOR AND BLEND AREA  
LABOR .20

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: SCRATCH AND DENT ON THE LEFT STILE ON SLIDE OUT AT SEATING

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA TO MATCH  
LABOR .20

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: SCRATCH ON RIGHT SIDE OF THE SLIDE OUT IN THE KITCHEN

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA  
LABOR .20

Subtotal for Job #8: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 02 Jun 2026



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

