

WORK ORDER # 65714

Completed : 30 NOV 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10684 Description : 2021 TT COACHMEN CATALINA 323BHDSCK
Tag : Date In : 03 NOV 21 Mileage :
Author : BH Promised :
Location : 1207 CHECK WITH DAV Date Sched :
Serial# : 5ZT2CAXB4MX022009 Chassis# : 5ZT2CAXB4MX022009
Warr. Date : 31 MAR 21 Cust PO# :
Print Date : 08 DEC 21

```

*****
Job #   Description   JOB INFORMATION   Type Bill To
*****
3      COMPLAINT:    WALL IN BEDROOM BOWED- MAY BE ANOTHER      W      10024   FORES
        WALL ALSO
        CAUSE:       WALL IN BEDROOM BOWED. MAY BE ANOTHER
        WALL ALSO.
        CORRECTION:  Removed window valance and mini blind.
        Cut fit a trim strip and covered with
        matching wall covering. Attached to
        wall over joint in panelling. Filled
        brad nail holes with matching putty.
        Remounted mini blind and valance. No
        other walls bowed.
4      COMPLAINT:    BLINDS IN SLIDE WILL NOT LIFT      W      10024   FORES
        CAUSE:       BLINDS IN SLIDE WILL NOT LIFT.
        CORRECTION:  Blinds will not go up[ all the way.
        Removed valance on window over couch.
        Removed blind from mounting.
        Straightened strings. Remounted blind.
        Replaced broken bottom anchor.
        Tightened strings. Checked operation of
        blind. Blind goes upv with TWO hands.
        Remounted valance. On window by table,
        Removed bottom anchors and tightened
        strings. Remounted bottom anchors.
        Checked operation of blind. Goes up
        with TWO hands. Tightened strings on
        small window by couch.
5      COMPLAINT:    HINGE ON CABINET KITCHEN CABINET ABOVE      W      10024   FORES
        SINK
        CAUSE:       HINGE ON CABINET KITCHEC CABINET ABOVE
        SINK.
        CORRECTION:  Checked hinges on cabinet doors above
        kitchen sink. Top hinge on left door
        missing hinge pin. Removed door from
        cabinet. Removed damaged top hinge.

```

Work Order : 65714

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
6        COMPLAINT:  Installed new top hinge.  Remounted
                   cabinet door on cabinet.
                   HANDLE ON UNDER ENTERTAINMENT CENTER IN  W      10024  FORES
                   BUNKHOUSE MISSING SCREW
        CAUSE:      HANDLE ON ENTERTAINMENT CENTER IN
                   BUNKHOUSE MISSING SCREW.
        CORRECTION: Checked cabinet doors below
                   entertainment center. Left hand door
                   handle missing bottom screw. Replaced
                   missing screw.
WINT     COMPLAINT:  WINTERIZE UNIT AND DRAIN HOLDING TANKS.  E      51108  MUSGR
                   ***INCLUDES 2 GALLONS OF ANTI-FREEZE***
                   UNITS WITH WASHING MACHINE OR ICEMAKER
                   WILL BE EXTRA **DE-WINTERIZATION IS NOT
                   INCLUDED**
        CORRECTION: BRING IN UNIT, DRAIN WATER HEATER, RESET
                   BYPASS VALVES, BLOW OUT WATER LINES,
                   PUMP IN ATIFREEZE 3 GALOONS, DRAIN
                   TANKS, UNIT HAS OUT SIDE KITCHEN AND
                   OUT SIDE SHOWER, PUT BACK OUT ON LOT
8        COMPLAINT:  POWER CORD IS COMING OUT FROM THERE IT  W      10024  FORES
                   IT PLUGGED IN POWER CORD IS IN A STORAGE
                   COMPARTMENT
        CAUSE:      POWER CORD IS COMING OUT FROM WHERE IT
                   IS PLUGGED IN. CORD IS IN A STORAGE
                   COMPARTMENT.
        CORRECTION: Outer jacket on power cord has putted
                   out of male plug end. Stretched power
                   cord outer jack several times to get it
                   back insid male plug. Applied super
                   glue around outer jacket and plug to
                   hold together.
9        COMPLAINT:  THE BAD BED ROOM DOOR IS UNEVEN AND      W      10024  FORES
                   CATCHING ON THE BOTTOM
        CAUSE:      THE BACK BEDROOM DOOR IS UNEVEN AND
                   CATCHING ON THE BOTTOM.
        CORRECTION: Checked operation of sliding door. Door
                   is dragging on bottom guide. Adjuster
                   rollers at top to raise door up off of
                   guide. The door is uneven at top
                   because it is adjusted to close up
                   against wall and not have a gap.
10       COMPLAINT:  THE FRONT COMPARTMENT DOOR ON THE        W      10024  FORES
                   DRIVERS SIDE THE LOCK IS NOT WORKING
                   RIGHT
        CAUSE:      THE FRONT COMPARTMENT DOOR ON THE
                   DRIVERS SIDE THE LOCK I NOT WORKING
                   RIGHT.
        CORRECTION: Checked operation of compartment door

```

Continued on page 3

Work Order : 65714

lock. Key hard to turn. Lubricated
lock. Key still does not want to turn.
Removed lock from door. Installed new
key lock. New lock turns easy and locks
door.

11 COMPLAINT: LED LIGHT ON THE AWNING LOOK LIKE THEY W 10024 FORES
ARE PULLING AWAY AND NOW WHEN YOU TURN
THEM ON THEY DO A QUICK FLASH AND THEN
SHUT DOWN
CAUSE: LED LIGHT ON THE AWNING LOOK LIKE THEY
ARE PULLING AWAY AND WHEN YOU TURN THEM
ON THEY DO A QUICK FLASH AND THEN SHUT
DOWN.
CORRECTION: Checked awning lights. Lights come on
with light switch but go back off.
Light strip has a section of lights that
are yellow and stay yellow all the time
lights are changing color. Also remote
is not working. 11/29/2021: Turned in
parts request for new remote and new
light strip.

12 COMPLAINT: SIDE CURTAIN HOLD DOWN ON SLIDEOUT IS W 10024 FORES
BROKEN AND MISSING
CAUSE: SIDE CURTAIN HOLD DOWN ON SLIDEOUT IS
BROKEN AND MISSING.
CORRECTION: Curtain hold down is missing. screws
are there. Installed new side curtain
hold down on slideout small window.

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
5	H240	H240 FREE SWINGING		W-10024	1	3.15	3.15
WINTE	24181	-50 RV ANTI-FREEZE GALLON		E-51108	2	4.49	8.98
10	L427	L427 7/8" COMPARTM		W-10024	1	6.50	6.50
12	A285	A285 SIDE CURTAIN		W-10024	1	2.85	2.85

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
3	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	1.00	130.00	130.00
3	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.26	130.00	33.80
4	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.50	130.00	65.00
5	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.10	130.00	13.00
6	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.05	130.00	6.50
INTER	Z990	WINTERIZE UNIT		JP	E-51108	0.00	130.00	0.00
INTER	Z990	WINTERIZE UNIT		JP	E-51108	1.00	130.00	130.00
8	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.00	130.00	0.00
8	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.20	130.00	26.00
9	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.40	130.00	52.00
9	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.00	130.00	0.00
10	Z990	MISC LABOUR CODE (EXTE	DKM		W-10024	0.10	130.00	13.00

Continued on page 4

Work Order : 65714

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   11 Z990      MISC LABOUR CODE (EXTE DKM  W-10024    0.50    130.00    65.00
   11 Z990      MISC LABOUR CODE (EXTE          W-10024    0.00    130.00     0.00
   11 Z990      MISC LABOUR CODE (EXTE DKM  W-10024    0.00    130.00     0.00
   12 Z990      MISC LABOUR CODE (EXTE DKM  W-10024    0.05    130.00     6.50

```

```

*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
INTER  SS      SHOP SUPPLIES          E-51108    1.00    13.00    13.00

```

 CUSTOMER COMMENTS

BH SENT IN PREAUTH 12-8 WAITING
 SAVED DRAFT
 BH GAVE PARTS SHEET BACK TO DKM FOR HIM TO GET MORE PICS
 BH TRIED TO SUMIT PREAUTH BUT NEEDED MORE PICS 12-06

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	51108	8.98	130.00	0.00	13.00	1.54	153.52
W	10024	12.50	410.80	0.00	0.00	0.00	423.30
Totals		21.48	540.80	0.00	13.00	1.54	576.82