



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 65760

CUSTOMER WORK ORDER

WO #: 65760

Customer: 51052 - MEFFORD, JOSHUA

A. - 812-604-8302

Tag:

Author: BH

Location: 1110 CHECK PREAUTH

Stock #: 10493

Stock Desc: 2021 TT FOREST RIVER

CHEROKEE GREY WOLF 26DBH

Chassis #: 4X4TCKB2XMK074030

Serial #: 4X4TCKB2XMK074030

Mileage:

Licence:

Invoice #:

Date In: 08 NOV 21

Promised:

Date Sched:

Completed: 10 NOV 21

Warr. Date: 26 MAR 21

Job #1 - Warranty

COMPLAINT: SEAL ABOVE THE SLIDE ROOM IS COMING APART

CAUSE: BULB SEAL CAME OFF

CORRECTION: PULLED SEAL OFF AND INSTALLED IT BACK AND SEALED IT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	39.00

Subtotal for Job #1: 39.00

Parts Total: 0.00

Labour Total: 39.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 39.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer #: 51052
MEFFORD, JOSHUA A.



Customer Signature : _____

Date: 10 Nov 2021



FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BAS EN RV CENTER INC		CLAIM	829076
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB2XMK074030
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	017 / 017C
		ITEM #	CCKT26DBH
Labor rate:	\$130.00	DEALER RO #	65760
OWNER INFORMATION		CLAIM START DATE	11/08/2021
JOSHUA MEFFORD		CLAIM END DATE	01/01/1900
5719 N NEW YORK AVE			
Evansville, IN 47711			
USA			
Retail Date of Purchase	03/27/2021	WARRANTY EXPIRATION DATE	03/27/2022

Claim Line Details

Labor					
Line# 1	Operation Code	Operational Description			
	10-11-01-00-000208	Slide Out Slip On D-Seal - Frame & Chassis/Slide Out System-Seals/ Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2021-11-08 10:25:52 :: SEAL ABOVE THE SLIDE ROOM IS COMING APART NEED TO REPLACE THE SEAL Additional Note : bhoffman@americanrvcenter.com, 2021-11-08 11:33:12 :: THE BULB SEAL IS TORN I NEED TO REPLACE IT NOT REATTACH IT Additional Note : bhoffman@americanrvcenter.com, 2021-11-10 13:59:14 :: DID NOT HAVE TO REPLACE SEAL JUST INSTALLED IT BACK AND SEALED IT				
	Model #	Dlr Sub Hrs	0.50	Sub Labor Amt	\$65.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt	\$39.00
	Notes				
	reattach bullb seal and seal it				

Submitted	Labor Amt	\$65.00	Approved	Labor Amt	\$39.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$65.00		Total	\$39.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	