

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65804

Completed : 30 DEC 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : Description : 2021 TT COACHMEN CATALINA 343BHTSLE
Tag : Date In : 11 NOV 21 Mileage : 0
Author : BJW Promised : 31 DEC 21
Location : 0103 GET WITH BH T O Date Sched :
Serial# : 5ZT2CAZB4MX021858 Chassis# : 5ZT2CAZB4MX021858
Warr. Date : 14 MAY 21 Cust PO# :
Print Date : 05 JAN 22

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: RECALL TSB# 205-1314 THE FRONT WALL W 10024 FORES
DIAMOND PLATE HAS FASTENERS THAT MAY NOT
HAVE BEEN SEALED PROPERLY FROM THE
FACTORY.
CORRECTION: THEY WERE SEALED RIGHT
2 COMPLAINT: THE PANELS ON BOTH SIDES OF THE DRESSER W 10024 FORES
IN THE BEDROOM HAVE COME LOOSE.
CORRECTION: REMOVED SEAM TAPE. STAPLED RIGHT SIDE OF
DRESSER WALL BACK. PUT TAPE BACK OVER
SEAM. LEFT SIDE OF DRESSER FOUND AFTER
REMOVEING SEAM TAPE THERE IS A SPLIT IN
THE PANEL.CUT AND REMOVED DAMAGED PANEL.
CUT AND INSTALLED NEW PANEL. PUT BATON
STRIPS ON SEAMS AND PUTTY HOLES
3 COMPLAINT: RECALL TSB# 51-1377 AS PER LIPPERT W 10024 FORES
COMPONENTS TECHNICAL SERVICE BULLETIN
11-004-21. THE SLIDE ROOM ACTUATOR WAS
ASSEMBLED INCORRECTLY, WHICH MAY CAUSE
THE ROOM TO BECOME STUCK IN THE OUT
POSITION AND PREVENT FROM FULLY
RETRACTING.
CORRECTION: TOOK PICS. CUT AD DROPPED MOTOR. IT IS
TUSON ASSEMBLLY. GOOD TO GO
4 COMPLAINT: CUSTOMER STATES THAT ONE OF THE WALL E 51342 KEYS
PANELS I SLOODE ON THE WALL ADJACENT TO
THE DRESSER IN THE BEDROOM.
CORRECTION: SECURED LOOSE PANEL AND STRIP PER
CUSTOMER REQUEST

Job # Part No Description PARTS Bill to Qty Price Total

2 F100130672 7/8" BATTEN VIPER W-10024 3 1.71 5.13
2 F100176333 WALL BOARD W-10024 32 0.76 24.32

Continued on page 2

Work Order : 65804

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
  1  Z990      MISC LABOUR CODE (EXTE BB  W-10024    0.00    130.00    0.00
  2  Z990      MISC LABOUR CODE (EXTE          W-10024    0.00    130.00    0.00
  2  Z990      MISC LABOUR CODE (EXTE BB  W-10024    0.00    130.00    0.00
  2  Z990      MISC LABOUR CODE (EXTE BB  W-10024    0.00    130.00    0.00
  2  Z990      MISC LABOUR CODE (EXTE BB  W-10024    1.50    130.00   195.00
  3  Z990      MISC LABOUR CODE (EXTE BB  W-10024    0.30    130.00    39.00
  3  Z990      MISC LABOUR CODE (EXTE BB  W-10024    0.00    130.00    0.00

```

```

*****
Job #  Excode   Description  EXTRAS      bill to    Qty    Price    Total
*****
  2  FRT        FREIGHT          W-10024    1.00    127.02   127.02
  4  SS         SHOP SUPPLIES    E-51342    1.00     0.00     0.00

```

```

*****

```

CUSTOMER COMMENTS

```

*****
CALLED CUSTOMER AND LEFT V-MAIL THAT THE UNIT IS COMPLETE AND TO GIVE US
A CALL TO FIGURE OUT A PICKUP TIME 1-6-22
PARTS IN 1A. 12-15-21
PARTS ORDERED PER BEN. 11-9-21
FOREST RIVER SAID JOB 1 WAS ALREADY DONE
BH GOT APPROVAL
BH SENT IN PREAUTH

```

```

*****

```

BILLINGS SUMMARY

```

Type Bill Id      Parts    Labour    Sublet    Extras      Tax    Total
*****
W      10024      29.45     234.00     0.00     127.02     0.00    390.47
      Totals      29.45     234.00     0.00     127.02     0.00    390.47

```