



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27236



WO #: 27236

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11315

Stock Desc: 2026 C FOREST RIVER FORESTER  
3051SF

Model: 3051SF

Serial #: 1FDXE4FN9VDD01081

Chassis #: 1FDXE4FN9VDD01081

Mileage: 1000

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 01 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: LIGHT SPOT ON CABINET DOOR UNDER TABLE BENCH

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: CABINET DOOR ABOVE BENCH HAS A SMALL CHIP

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: CABINET DOOR ABOVE THE ENTRY DOOR HAS A CHIP ON THE BOTTOM CORNER

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: STILE NEXT TO FRIDGE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: CABINET OVER STOVE IS CHIPPED IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA  
LABOR .20

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: BLACK STAIN ON BOTTOM RIGHT WALL CORNER GOING INTO THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND COLOR BLEND  
LABOR .20

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: WALL NEXT TO BATHROOM SINK LEFT OF MIRROR IS CUT AND PEELING

CAUSE: NOTED ON DAF

CORRECTION: FILL,SMOOTH, COLOR AND BLEND AREA  
LABOR .30

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: BOTTOM DRAWER IN BEDROOM IS SHORTER THAN THE TOP 2

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE BOTTOM DRAWER TO MATCH THE OTHER DRAWERS  
LABOR .30

Subtotal for Job #8: 0.00

**Job #9 - Warranty**

COMPLAINT: CEILING HAS SEVERAL BROWN SPOTS AT ENTRY AND A PLACE WHERE THE WHITE  
COLOR IS PEELED BACK

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA  
LABOR .30

Subtotal for Job #9: 0.00

**Job #10 - Warranty**

COMPLAINT: UNIT WAS VERY DIRTY WITH DEBRIS ON THE FLOOR, EXTRA WIRING THAT HAD  
BEEN CUT AND LOTS OF WOOD CHIPS. THIS WAS MOSTLY ON THE SLIDE FLOOR AREA

CAUSE: NOTED ON DAF

CORRECTION: SWEEP,VACUUM EDGES AND CORNERS TO REMOVE DEBRIS TO NOT DAMAGE  
THE FLOORING



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



LABOR .50

Subtotal for Job #10: 0.00

W/O: 27236

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>0.00</b>

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 01 Jun 2026



Customer Work Order

Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

