

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 65945

Completed : 08 DEC 21 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10719 Description : 2021 TT KEYSTONE SPRINGDALE 335BH
Tag : Date In : 22 NOV 21 Mileage : 0
Author : BJW Promised : 25 DEC 21
Location : 1208 CHECK STATUS Date Sched :
Serial# : 4YDT33526M3110133 Chassis# : 4YDT33526M3110133
Warr. Date : 08 MAY 21 Cust PO# :
Print Date : 08 DEC 21

Job # Description JOB INFORMATION Type Bill To

WINT COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS. I SPN SALES
 INCLUDES 2 GALLONS OF ANTI-FREEZE
 UNITS WITH WASHING MACHINE OR ICEMAKER
 WILL BE EXTRA **DE-WINTERIZATION IS NOT
 INCLUDED**
 CAUSE: winterize
1 CORRECTION: winterized unit and drained tanks
 COMPLAINT: CUSTOMER STATES THAT THE WATER PUMP W 1013 KEYST
 NEVER FULLY PRIMES. IT WOULD PRIME, SHUT
 OFF, AND THEN COME RIGHT BACK ON. IT
 NEVER STOPPED UNTIL CUSTOMER TURNED PUMP
 OFF.
 CAUSE: check pump function.
 CORRECTION: filled water tank. turned on pump. pump
 is cycling and not building pressure.
 cut open underbelly to see if water was
 running out since SHAWN JUST REPLACED
 THE FRESH TANK. checked all other
 fitting and water lines on all fixtures
 through the entire unit to see if there
 were any leaks. no signs of water
 leaking anywhere. went back to pump and
 noticed there isnt a filter on the pump.
 pump is probably full of debris and has
 damaged the inside of the pump. need to
 replace pump and install a filter to
 prevent further damage. replaced pump
 and installed filter
2 COMPLAINT: THERE IS SEVERAL CUTS IN THE UNDERBELLY I SPN SALES
 FROM THE PREVIOUS REPAIR. GM (CB) AGREED
 TO REPLACE THE UNDERBELLY
 CAUSE: REPLACE UNDERBELLY.
 CORRECTION: REMOVED RIVETS AND SELF TAPPING SCREWS
 FROM THE FRAME. REMOVED MAIN GAS SUPPLY

Continued on page 2

Work Order : 65945

 Job # Description JOB INFORMATION Type Bill To

LINE. REMOVED FRONT SCISSOR JACK. CUT
 AROUND OTHER GAS LINES. CUT AROUND
 PLUMBING. CUT AROUND BRAKE WIRES LOOMS.
 CUT UNDERBELLY IN THREE PIECES TO REMOVE
 SO I COULD TRACE AROUND THE OLD
 UNDERBELLY. ROLLED OUT NEW UNDERBELLY
 AND SET OLD ONE ON TOP. TRACED
 UNDERBELLY. CUT OUT UNDERBELLY.
 INSTALLEUNDERBELLY FROM FRONT TO BACK.
 SECURED UNDERBELLY TO FRAME WITH ALL NEW
 TECH SCREWS AND WASHERS.. ADDED A
 SUPPORT BEAM IN THE MIDDLE TO HOLD
 UNDERBELLY. SECURED MAIN GAS LINE TO
 FRAME. SECURED FRONT SCISSOR JACK.
 APPLIED FOAM TO GAPS WHERE I HAD TO CUT
 FOR PLUMBING. ADDED ONE COAT AND LET
 DRY. CAME BACK AND ADDED MORE FOAM.
 PAINTED FOAM BLACK.

3 COMPLAINT: CHECK WATER SYSTEM FOR LEAKS. CUSTOMER I SPN SALES
 WAS UNABLE TO USE PUMP ON LAST CAMPING
 TRIP AND WOULD LIKE TO HAVE UNIT LOOKED
 AT TO BE SURE IT IS NOT LEAKING.
 CAUSE: checked water system when diagnosing the
 pump. no leaks present
 CORRECTION: no correction needed

 Job # Part No Description PARTS Bill to Qty Price Total

 WINTE 24181 -50 RV ANTI-FREEZE GALLON I-SPN 2 4.49 8.98
 1 5830 Pump - Strainer Mini - Flo-Je W-1013 1 3.71 3.71
 1 28300 FLOJET WATER PUMP W-1013 1 92.79 92.79
 2 155219 CORRUGATED UNDERBE I-SPN 330 0.72 237.60

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 INTER Z990 WINTERIZE UNIT ZMS I-SPN 1.00 25.00 25.00
 1 Z990 MISCELLANEOUS REPAIR ZMS W-1013 0.00 130.00 0.00
 1 Z990 MISCELLANEOUS REPAIR ZMS W-1013 1.50 130.00 195.00
 1 Z990 MISCELLANEOUS REPAIR ZMS W-1013 0.00 130.00 0.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 1.11 25.00 27.75
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 0.61 25.00 15.25
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 0.50 25.00 12.50
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 1.68 25.00 42.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 4.12 25.00 103.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 3.74 25.00 93.50
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 4.12 25.00 103.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS I-SPN 3.80 25.00 95.00

Continued on page 3

Work Order : 65945

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
   2  Z990      MISC LABOUR CODE (EXTE ZMS I-SPN    1.89    25.00    47.25
   3  Z990      MISC LABOUR CODE (EXTE ZMS I-SPN    0.00    25.00     0.00

```

```

*****
Job #  Excode   Description  EXTRAS    bill to    Qty    Price    Total
*****
INTER  SS       SHOP SUPPLIES      I-SPN     1.00     9.70     9.70
   2  FRT       FREIGHT- -UNDERBELLY  I-SPN     1.00    72.45    72.45

```

```

*****
                        CUSTOMER COMMENTS
*****
UNDERBELLY IN 1A. 12-1-21
BH SENT IN PREAUTH FOR JOB 1 AND JOB RECALL 11-27
UNDERBELLY ORDERED 11-26-21...CAM

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I    SPN          246.58    564.25     0.00     82.15    23.01    915.99
W    1013          96.50    195.00     0.00      0.00     0.00    291.50

Totals          343.08    759.25     0.00     82.15    23.01    1,207.49

```