

WORK ORDER # 65983

Completed :	31 DEC 21	Customer :	10024 - FOREST RIVER TRAVEL TRAILER	
Licence # :		Invoice # :		
Stock No :	10561	Description :	(10561) 2021 COACHMEN CATALINA 263B	
Tag :		Date In :	26 NOV 21	Mileage :
Author :	BJW	Promised :	25 DEC 21	
Location :	0110 CHECK WORK	Date Sched :		
Serial# :	5ZT2CARB2MU039230	Chassis# :	5ZT2CARB2MU039230	
Warr. Date :	25 JUN 21	Cust PO# :		
Print Date :	08 JAN 22			

Job #	Description	JOB INFORMATION	Type	Bill To
1	COMPLAINT: THE WALL BETWEEN THE DINING AREA AND THE W BEDROOM (TOWARDS THE OFF DOOR SIDE) HAS A GAP WHERE IT MEETS THE EXTERIOR WALL. SEE BW FOR MORE DETAILS. CORRECTION: find unit and bring in, take pics of wall, remove batting strips from both sides of wall, pull staples, install batting strips fill holes with filler		W	10024 FORES
WINT	COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS. ***INCLUDES 2 GALLONS OF ANTI-FREEZE*** UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA **DE-WINTERIZATION IS NOT INCLUDED** CORRECTION: move custoer stuff to get to needed areas, reset bypass valves, drain water heater, drain tanks, blow out water lines, pump in atifreeze,		E	51561 JAMES
3	COMPLAINT: CUSTOMER STATES THAT WATER IS LEAKING BETWEEN THE COACH AND THE AWNING. THE CUSTOMER HAS ADDED CAULKING TO THE AREA THAT IS LEAKING. CAUSE: seam in gutters leaking CORRECTION: take pics of seam in gutter leaking, and seal with silacone, close up unit and pull out to lot to park		W	10024 FORES
4	COMPLAINT: THE FLOOR OF THE FREEZER POPPED UP AND HAS CRACKS IN EACH CORNER. CAUSE: foor of frezzer compartment is loose and back corners at walls and foot have holes and cracked liner needs new refer, turn in po CORRECTION: take pics and turn in po remove old refer, get and unpack, new refer has hinges on right side, have to remove		W	10024 FORES

Work Order : 65983

 Job # Description JOB INFORMATION Type Bill To

doors and do a hing swap, swap mounting
 bracket, bracket holes do not line up
 with new refer, cut holes to fit,
 mount the mount to refer install in
 unit, new refer M# GPV10FGNBBB S#
 GS550489 PULL OUT AND PUT ON LOT
 5 COMPLAINT: CUSTOMER STATES THAT HE NOTICED WATER W 10024 FORES
 LEAKING IN THE CABINET UNDER THE KITCHEN
 FAUCET.
 CAUSE: FOUND HOT AND COLD LINES LEAKING
 CORRECTION: INSTALLED CONE WASHERS

 Job # Part No Description PARTS Bill to Qty Price Total

 WINT 24181 -50 RV ANTI-FREEZE GALLON E-51561 2 4.49 8.98
 5 10-7150 CONE WASHER SWIVEL SEAL W-10024 2 0.24 0.48

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.00 130.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE JP W-10024 2.00 130.00 260.00
 1 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.00 130.00 0.00
 INTER Z990 WINTERIZE UNIT JP E-51561 1.00 130.00 130.00
 3 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.20 130.00 26.00
 4 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.00 130.00 0.00
 4 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.00 130.00 0.00
 4 Z990 MISC LABOUR CODE (EXTE JP W-10024 2.00 130.00 260.00
 5 Z990 MISC LABOUR CODE (EXTE JP W-10024 0.20 130.00 26.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 INTER SS SHOP SUPPLIES E-51561 1.00 9.70 9.70

 CUSTOMER COMMENTS

 REFER ARRIVED IN SHOP 1A 1-3-22...PER BEN...CAM
 PER AUBRA THEY ARE SENDING A FRIDGE AND PAYMENT TO US WITH OUR
 RO NUMBER ON IT
 PER BH:
 PER SDECKER @ FORESTRIVER. GE SHOULD BE CALLING ABOUT GETTING A
 NEW FRIDGE BUT WE HAVE TO WAIT FOR GE TO GET AHOLD OF US. SORRY
 NOT A GOOD ANSWER. I HAVE CALLED THEM 3 TIMES ALREADY AND STILL
 GET THE SAME ANSWER.
 PER FOREST THEY ARE SENDING A TECH OUT TO LOOK AT THE FRIDGE
 12-10

Continued on page 3

Work Order : 65983

BH SENT IN PREAUTH

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	51561	8.98	130.00	0.00	9.70	1.31	149.99
W	10024	0.48	572.00	0.00	0.00	0.00	572.48
	Totals	9.46	702.00	0.00	9.70	1.31	722.47