

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66020

Completed : 20 DEC 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 11074 Description : 2022 5W FOREST RIVER SABRE 38DBQ
Tag : Date In : 01 DEC 21 Mileage : 0
Author : CM Promised : 10 DEC 21
Location : 1220 CHECK PREAUTH Date Sched :
Serial# : 5ZT3SR3B8N6109706 Chassis# : 5ZT3SR3B8N6109706
Warr. Date : 10 DEC 21 Cust PO# :
Print Date :

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: PDI - NEW FIFTH WHEEL I PDI PRE-D
CAUSE: PDINFW - PDI NEW FIFTH WHEEL.

CORRECTION: Moved unit into shop from sales lot.
Installed second battery and made up
cables to connect together. Checked all
exterior lights and brakes. Checked lug
nuts and set tire pressure at 80 psi.
Recorded all tire serial numbers.
Operated auto leveling jacks. Checked
awning and roof. Checked both entrance
doors and all compartment doors.
Checked all windows and blinds. Checked
all cabinets and drawers. Checked all
electrical outlets and GFCI outlets.
Checked all USB outlets. Checked all
sliding doors. Recorded all serial
numbers and took pictures. Filled fresh
water tank. Flushed antifreeze from all
water lines and faucets. Opened by-pass
on water heater and filled. Purged air
from water lines and faucets. Checked
all water lines and faucets for leaks.
Filled all FIVE holding tanks and
checked monitor panel. Performed LP
drop test and set LP pressure at 11
in.wc. Checked all appliances. Checked
Fireplace, Ceiling Fan, Radio, TV
Antenna and TV.

FPDI COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS I PDI PRE-D
CAUSE: FPDINFW - FINAL PDI ON NEW FIFTH WHEEL.

CORRECTION: By-passed water heater. Blew out all
water lines and faucets. Added
antifreeze to all water lines and
faucets, including outside kitchen,

Work Order : 66020

Job #	Description	JOB INFORMATION	Type Bill To		

		outside shower and both bathrooms. Poured antifreeze in all drain traps. Drained all five holding tanks, water heater and fresh water tank. Moved unit to wash bay area.			
WALK	COMPLAINT:	WALK THRU	I	PDI	PRE-D
	CAUSE:	WALK THROUGH			
	CORRECTION:	WALK THROUGH WENT GOOD			
1	COMPLAINT:	20K COMPANION PUCK HITCH TO FIT 2022 CHEVY 2500 Z-71 4X4.	I	DO	DEALE
	CORRECTION:	INSTALLED AND SETUP 20K 5TH WHEEL HITCH.			
SPLE	COMPLAINT:	INSTALL VENTED SPLENDIDE COMBO	I	DO	DEALE
	CAUSE:	SPLENDIDE - INSTALL VENTED SPLENDIDE COMBO WASHER/DRYER.			
	CORRECTION:	Measured closet where Washer/Dryer combo will be installed. Found a location for dryer vent to outside. Drilled a 4 in. hole thru sidewall of unit. Installed dryer vent on outside and sealed with clear silicone. Mounted hole cover plate on inside. Mounted dryer vent elbow on outside exhaust vent. Installed vent hose to elbow and sealed with aluminum folit tape. Cut off portion of clothes hanger pole over washer. Disconnected bed lift shocks and held platform and mattress out of way. Set W/D in closet. Pushed close enough to final position to allow hoses and vent hose to be hooked up. Connected water hoses, drain hose and vent hose. Ran washer thru a cycle and checked for leaks. Secured drain hose in place to prevent coming out of drain pipe. Remounted bottom trim piece.			
3	COMPLAINT:	THE SCREWS PULLED OUT OF THE FRONT COMPARTMENT HOLD BACK.	W	10024	FORES
	CAUSE:	THE SCREWS PULLED OUT OF THE FRONT COMPARTMENT HOLD BACK.			
	CORRECTION:	The short mounting screws pulled out of compartment door. Painted long screws black to match trim. Secured holdback to compartment door with screws, washers and nuts.			
4	COMPLAINT:	THE MAIN TV WILL NOT PICK UP CHANNELS.	W	10024	FORES
	CAUSE:	THE MAIN TV WILL NOT PICK UP CHANNELS.			
	CORRECTION:	Main TV not picking up channels. Connected shop test TV to antenna outlet. Test TV not picking up			

Continued on page 3

Work Order : 66020

channels. Connected test TV to bedroom antenna outlet. Picked up 12 channels. TV Antenna working. Connected main TV to bedroom to antenna outlet. Picked up 12 channels. Main TV working. Antenna outlet not working. Removed fireplace from cabinet to trace coax cable. Switched coax going to radio and with coax going to tv. TV found 6 channels. Reinstalled coax outlet in wall. Remounted Fireplace in cabinet.

5 PARTS ADDED PER BRANDON I DO DEALE

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
FPDIN	SRM27	GROUP 27 DC BATTER		I-PDI	1	163.99	163.99
FPDIN	5516	A10-3050FHVP 30M-5		I-PDI	1	23.99	23.99
FPDIN	24181	-50 RV ANTI-FREEZE		I-PDI	4	4.99	19.96
1	RVK3710	RVK3710 20K 5TH WH		I-DO	1	1,100.00	1,100.00
SPLEN	07-0502	VENTED WASHER/DRYE		I-DO	1	1,412.00	1,412.00
SPLEN	07-0371	DRYER VENT KIT - B		I-DO	1	35.49	35.49
SPLEN	07-0808	SPLENDIDE 90 DEG.		I-DO	2	19.37	38.74
SPLEN	10-0578	90 DEGREE HOSE ELB		I-DO	2	7.99	15.98
SPLEN	110387	18-1052 FLOOR BRAC		I-DO	1	17.99	17.99
5	11-0018	39741 20' RHINOFLEX HOSE KIT		I-DO	1	59.99	59.99
5	44675	44675 12" 5W LUBE PLATE		I-DO	1	17.99	17.99

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
DINFW	Z991	PDI NEW FIFTH WHEEL (I	DKM	I-PDI		0.00	130.00	0.00
DINFW	Z991	PDI NEW FIFTH WHEEL (I	DKM	I-PDI		2.86	130.00	371.80
DINFW	Z991	PDI NEW FIFTH WHEEL (I	DKM	I-PDI		3.14	130.00	408.20
DINFW	Z991	PDI NEW FIFTH WHEEL (I	DKM	I-PDI		3.00	130.00	390.00
DINFW	PDINFW	FINAL PDI NEW FIFTH WH	DKM	I-PDI		2.00	130.00	260.00
WALK	Z990	MISC LABOUR CODE (EXTE	BAP	I-PDI		1.50	130.00	195.00
1	Z990	MISC LABOUR CODE (EXTE	GAH	I-DO		1.00	130.00	130.00
NDIDE	Z990	MISC LABOUR CODE (EXTE	DKM	I-DO		0.00	130.00	0.00
NDIDE	Z990	MISC LABOUR CODE (EXTE	DKM	I-DO		3.20	130.00	416.00
NDIDE	Z990	MISC LABOUR CODE (EXTE	DKM	I-DO		2.30	130.00	299.00
3	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.10	130.00	13.00
3	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.00	130.00	0.00
4	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.00	130.00	0.00
4	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.50	130.00	65.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
DINFW	SS	SHOP SUPPLIES		I-PDI	0.00	35.00	0.00
DINFW	LP20	20 LB. LP CYLINDER		I-PDI	2.00	14.00	28.00
NDIDE	SS	SHOP SUPPLIES		I-DO	0.00	0.00	0.00

Continued on page 4

Work Order : 66020

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
NDIDE  FRT     FREIGHT-  WASHER DRYER  I-DO    1.00  44.75  44.75
*****
```

CUSTOMER COMMENTS

```
*****
BH SENT IN PREAUTH- 12-14
REMAINING WASHER DRYER ITEMS ARRIVED AND GIVEN TO DAVE MILLER.
12-3-21. MAB
FLOOR BRACKETS IN BACK ROOM. 12-3-21
5W HITCH IN SHOP BY LIFT 12-2-21....CAM
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I   DO           2698.18  845.00  0.00   44.75  0.00  3,587.93
I   PDI           207.94  1625.00  0.00   28.00  0.00  1,860.94
W   10024          0.00    78.00  0.00    0.00  0.00    78.00

Totals           2906.12  2548.00  0.00   72.75  0.00  5,526.87
*****
```