



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 27257



WO #: 27257

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11321

Stock Desc: 2027 TT KZ-RV CONNECT 271RL

Model: 271RL

Serial #: 4EZTL2821V4053472

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 04 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: DOOR SIDE COMPARTMENT DOOR HAS CHIPS ON THE INSIDE, SMALL HOLES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR AND RESEAL AREA IF NEEDED  
LABOR .50

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: SLIDE OUT STILE HAS SEVERAL NAIL HOLES ACROSS IT

CAUSE: NOTED ON DAF  
NAIL HOLES NOT FILLED AND BLENDED AT BUILD

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: PAINT FADED ACROSS THE TOP OF BENCH SEATING

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: KITCHEN CABINETS ABOVE THE SINK DON'T SHUT ALL THE WAY ON ONE SIDE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST HINGE ON DOOR TO OPEN AND CLOSE CORRECTLY  
LABOR .30

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: BROWN STAINS ON THE CEILING AS YOU ENTER THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: CLEAN SPOTS AND COLOR BLEND IF NEEDED  
LABOR .30

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: HALL VALANCE IS LOOSE ON THE WALL IN HALL WAY AREA

CAUSE: NOTED ON DAF

CORRECTION: RESECURE VALANCE BACK IN PLACE CORRECTLY  
LABOR .10

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: STILE ABOVE BEDROOM DOOR HAS A CHIPPED SPOT

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND TO MATCH  
LABOR .20

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: BEDROOM DOOR IS DAMAGED AT THE TOP IN 2 PLACES

CAUSE: NOTED ON DAF  
DAMAGED AT FACTORY INSTALL

CORRECTION: REPLACE THE BEDROOM DOOR  
LABOR .50

Subtotal for Job #8: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 04 Jun 2026



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

