

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66066
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52148 - RANDALL DAVIS
Address: 705 E SCOTT ST. OLNEY, IL

62450

Phone: 618-302-1311

Stock Number: 10956 - 2022 SPIRIT 2557RB 5ZT2SBRBXNS042799

VIN: 5ZT2SBRBXNS042799 HIN: SER#: 5ZT2SBRBXNS042799

Mileage: 0 Work Order Comp: 15 DEC 21

Auth. No: Dealer #:

Warr. Date: 14 DEC 21 Work Order Date: 07 DEC 21 Inv #: 371408

WO # Job # Description JOB INFORMATION

66066 1 THE REFRIGERATOR DOOR IS HITTING THE ENTERTAINMENT CENTER. NOTED
ON DELIVERY
THE REFRIGERATOR DOOR IS HITTING THE ENTERTAINMENT CENTER (NOTED
AT DELIVERY)
When refrigerator door hits the entertainment when opening and
will not open all the way. Removed bottom grille on
refrigerator. Removed lower mounting screws. Tried to move
bottom of refrigerator away from entertainment door. Moved a
little. Reattached bottom of vrefrig. with screws. Reinstalled
bottom grille. Refrig door still scrapes entertainment door a
little. Adjusted bottom hinge on refrig bottom door to clear
entertainment door.

66066 2 THE RECLINERS ARE NOT SECURED TOGETHER. NOTED ON DELIVERY
THE RECLINERS ARE NOT SECURED TOGETHER. (NOTED ON DELIVERY).
The recliners and center arm rest are not connected together.
Recliners will not lock to center arm rest. Removed recliners
from slideout and turned over on back. Front bracket on left
recliner not mounted in alignment with bracket on center arm
rest. Removed front bracket on left recliner and repositioned to
match center arm rest bracket. Reattached bracket. Turned
recliners back on feet and slid into position. Attached both
recliners to center arm rest.

66066 3 THE STAPLE HOLES ARE NOT FILLED BEHIND THE BEDROOM SLIDING DOOR.
THIS IS MARKED WITH RED TAPE FROM THE FACTORY.

Claim : 66066

 WO # Job # Description JOB INFORMATION

 THE STAPLE HOLES ARE NOT FILLED BEHIND THE BEDROOM SLIDING DOOR.
 All staple holes marked with red tape from factory. Removed red
 tape. Filled all staple holes with matching putty.

 66066 4 THE SEAM TAPE IS PEELING ON THE UNDER BELLY. THIS WAS NOTED ON
 DELIVERY.
 THE SEAM TAPE IS PEELING ON THE UNDER BELLY. (NOTED ON
 DELIVERY).
 Several places outer medh material is hanging on underbelly. Cut
 off these areas. Applied underbelly tape to these areas to seal.

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 130.00 65.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 130.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.40 130.00 52.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 130.00 39.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.50 130.00 65.00

 Parts Total: 0.00
 Labour Total: 221.00
 Sublet Total: 0.00
 Extras Total: 0.00

 >>>>> Claim Total: 221.00

Customer Signature: _____

Date: _____