


RE: 10670 - 2021 TT RIVERSIDE RV INTREPID 279RBC Ser#: 59CCC3628ML003956

Warranty @Riverside RV <warranty@goriversiderv.com>

Wed 12/22/2021 7:53 AM

To: Ben Hoffman <bhoffman@americanrvcenter.com>

122221-2 - .2



Thank you and have a good day,

Connie Wilfong

Warranty Manager

Riverside RV

1775 E US 20

Lagrange, IN 46761

260-499-4578

Ext. 110

From: Ben Hoffman <bhoffman@americanrvcenter.com>

Sent: Tuesday, December 21, 2021 4:52 PM

To: Warranty @Riverside RV <warranty@goriversiderv.com>

Subject: 10670 - 2021 TT RIVERSIDE RV INTREPID 279RBC Ser#: 59CCC3628ML003956

1. THERE IS TRIM ON THE CHAIRS IT GOES ON THE MIDDLE OF THE SLIDE WHERE THE TWO ROOF PANELS MEET ABOVE THE DINETT AND RECLINERS

a. restapled the trim back up and used putty as filler

i. LABOR .3

BEN HOFFMAN

SERVICE EXPERT

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012