

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106  
BASDEN RV CENTER INC  
DBA AMERICAN RV CENTER  
600 E BASELINE ROAD  
EVANSVILLE, IN 47725  
USA

Labor rate: \$130.00  
OWNER INFORMATION

CLAIM STATUS Authorized  
CLAIM 876024  
CLAIM ORIGIN WEB  
ORIGINAL CLAIM ID  
VIN 5ZT2CARB6NU039765  
CHASSIS VIN  
MILEAGE 0  
SITE/WAREHOUSE 103 / 103  
ITEM # CAT263BHSCKLE  
DEALER RO # 66099  
CLAIM START DATE 12/20/2021  
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

**Labor**  
Line# 1      **Operation Code**      **Operational Description**  
70-469-02-00-004029      Door Latch or Catch - Appliances/Refrigerator (Furrion)/Adjust/No Tread Code

**Complaint, Cause, Correction**  
Original Note : bhoffman@americanrvcenter.com, 2021-12-20 14:12:07 :: FREEZER DOOR WILL NOT SHUT took off freezer door and added a shim and put back together.

<b>Model #</b>	GPV10FSNBSB	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$26.00
<b>Serial #</b>	RR562697	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$13.00

**Notes**  
EXCESSIVE AMOUNT REQUESTED ADJUSTED TO FLAT RATE

**Labor**  
Line# 2      **Operation Code**      **Operational Description**  
30-100-02-00-001044      Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code

**Complaint, Cause, Correction**  
Original Note : bhoffman@americanrvcenter.com, 2021-12-20 14:17:28 :: 2ND DRAWER IN TO RIGHT OF THE SINK IN KITCHEN, BRACE CAME APART. put drawer guide back in place and installed longer screws.

<b>Model #</b>		<b>Dlr Sub Hrs</b>	0.40	<b>Sub Labor Amt</b>	\$52.00
<b>Serial #</b>		<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$26.00

**Notes**  
EXCESSIVE AMOUNT REQUESTED

**Submitted**

Labor Amt	\$78.00
Parts & Freight	\$0.00
Total	\$78.00

**Approved**

Labor Amt	\$39.00
Parts & Freight	\$0.00
Total	\$39.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
SIGNATURE

All repairs described have been inspected and are satisfactory.