

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	880380
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CARB9NU039758
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	103 / 103
Labor rate:	\$130.00	ITEM #	CAT263BHCKLE
OWNER INFORMATION		DEALER RO #	66100
		CLAIM START DATE	12/27/2021
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-46-19-00-000721 Window - Exterior/Windows/Reseal/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2021-12-27 13:26:21 :: SILICONE ON WINDOWS & DOOR ON PASSANGER SIDE SILICONE ON WINDOW AND DOOR. REMOVED WITH ADHESIVE REMOVER
 Model # **Dlr Sub Hrs** 0.50 **Sub Labor Amt** \$65.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$26.00

Notes

Excessive time requested per repair description

Labor

Line# 2 **Operation Code** **Operational Description**
 20-68-01-17-000694 Patio Door Lock, Handle - Exterior/Patio Doors/Replace/Latch
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2021-12-27 13:30:16 :: BEDROOM CLOSET DOOR WONT LATCH closet door wont latch removed latch and sanded hole where latch goes into the frame so i could adjust it. installed latch
 Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$52.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$26.00

Notes

excessive time requested per repair description

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-24-00-001046 Cabinet Door - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2021-12-27 13:32:26 :: CABINET DOOR ABOVE BED & (DOORLATCH) NEEDS ADJ latch for cabinet is off center removed latch and moved it down so it would catch. filled original holes with putty
 Model # **Dlr Sub Hrs** 0.50 **Sub Labor Amt** \$65.00
 Serial # **Appr Hrs** 0.30 **Appr Labor Amt** \$39.00

Notes

excessive time requested per repair description

Labor

Line# 4 **Operation Code** **Operational Description**
 60-138-01-00-001537 Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2021-12-27 13:33:24 :: CHECK VALVE FOR THE BLACK

TANK FLUSH IS BROKEN NEED REPLACED check valve leaking and water line was kincked. replaced check valve and installed a 90 degree hose fitting

Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$52.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$39.00

Notes
excessive time requested per repair description

Submitted	Labor Amt	\$234.00	Approved	Labor Amt	\$130.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$234.00		Total	\$130.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.