



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72707  
 Promised Date:  
 26 MAY 26



WO #: 72707 (Appointment Date: 24 NOV 2025 - Time: 12:30pm)  
 Customer Name: 60727 - MARTINO, MELISSA ANN  
 Completed Date: 28 MAY 26  
 Invoice#: Author: ADVISOR  
 Stock Desc: 9546 2026 R-POD RP-197  
 Serial#: 4X4TRPV2XTB034617  
 Chassis#: 4X4TRPV2XTB034617 Date In: 24 NOV 25  
 Miles/Hrs: Time In:  
 Tag#: 7227  
 Purchased Date: 18 OCT 25  
 Warranty Date: 18 OCT 25

**Job #1 - Warranty**

COMPLAINT: CUSTOMER STATES THE SCREEN AND THE MAIN DOOR LATCH IS NOT OPENING TOGETHER. KM

CAUSE: Screen door latch screws are pulled out of door causing screen door not to open.

CORRECTION: Reinstalled screws to hold latch in place.

**Labor**

Job #	Description	Total
1	LATCH SCREEN & MAIN DOOR	47.50

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

**Subtotal for Job #1: 47.50**

**Job #2 - Warranty**

COMPLAINT: CUSTOMER STATES WHEN YOU LOCK THE ENTRY DOOR IT COMES OPEN IN TRANSIT, STATES YOU HAVE TO SLAM IT TO CATCH. KMM

CAUSE: Door latch needs to be adjusted so door closes properly.

CORRECTION: Adjusted door latch.

**Labor**

Job #	Description	Total
2	ENTRY DOOR LATCH	47.50

**Subtotal for Job #2: 47.50**

**Job #3 - External**

COMPLAINT: Transferred to RV\*72707-1 on 02 APR 26

Estimate amount was 0.00

CUSTOMER REQUESTS INSTALL LATCH, ON MURPHY BED, WHEN LOOKING AT BED INSTALL IT ON THE LEFT SIDE, HAS ONE ON THE RIGHT SIDE. KM PARTS ARE IN - CUSTOMER ALREADY PAID FOR LATCH

CAUSE: Install bed latch for customer.

CORRECTION: Latch has been installed.

Customer #: 60727  
 MARTINO, MELISSA ANN





<b>Labor</b>		
Job #	Description	Total
3	INSTALL BED LATCH	N/C
<b>Subtotal for Job #3:</b>		<b>0.00</b>

**Job #4 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES CAULKING AROUND BATHROOM SINK COMING OFF

CAUSE: Caulking on bathroom sink is peeling.

CORRECTION: Resealed sealant around bathroom sink.

<b>Labor</b>		
Job #	Description	Total
4	COUNTERTOP CAULK AROUND (ALL)	47.50
<b>Subtotal for Job #4:</b>		<b>47.50</b>

**Job #5 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES UNDER FRONT WINDOW, TOWARDS DOOR SIDE, THERE IS A DIPPLE...DELAM?? \*\*IT'S HARD TO SEE\*\*

CAUSE: Front cap has a Imperfection when running hand over it. Possible delam.

CORRECTION: Manufacture suggestions on how to fix the situation.

<b>Labor</b>		
Job #	Description	Total
5	DIMPLEV/DELAM	1,520.00

**Parts**

Part #	Description	Qty	Price	Total
15108	3M 1/4" BODY TAPE	6.00	1.73	10.38
18956	FRONT SKIN - R-POD	1.00	287.50	287.50
40006	PUTTY TAPE 1/8 X 1	1.00	8.49	8.49
40170	SILICONE TUBE-CLEAR	1.00	12.88	12.88
F100330823	SEAL, WINDOW, FLEXIBLE PVC 1" (COMES IN 13' PIECE)	1.00	166.51	166.51
F100586727	DECAL, 20A R-POD NAME-FRONT - 2025 DECAL	1.00	7.80	7.80
F100586761	DECAL, 12A FRONT FADE STRIPE 2025 DECAL	1.00	22.24	22.24
F100587283	28A WINDOW BLACK 24" R-POD NAME - 2025	1.00	26.54	26.54
F100595204	DECAL, 38A HOOD RIVER 2025/2026 DECAL	1.00	5.69	5.69
F100600228	3A - FOREST RIVER LOGO SHIELD/BADGE - 2025	1.00	6.81	6.81
F100702891	SEAL, RUBBER WINDOW SEAL 1-7/16"	13.00	2.38	30.94

**Other Services**

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	404.02	404.02
FRT	SHIPPING & HANDLING CHARGES	1.00	16.83	16.83

**Subtotal for Job #5: 2,526.63**

**Job #6 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES CABINET DIVIDER BELOW KITCHEN SINK IS BUBBLING





CAUSE: Cabinet center trim piece is bubbling covering is coming off.

CORRECTION: Cabinet will have to be taken apart to remove and install new trim piece.  
 Part needs to be ordered.

<b>Labor</b>		
Job #	Description	Total
6	DOOR, CABINET DIAGNOSE	380.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
40172	SILICONE TUBE-WHITE	1.00	12.02	12.02
F100426073	STILE - BRIGHTON WHITE 3/4" X 2"	1.00	7.07	7.07

**Subtotal for Job #6: 399.09**

**Job #7 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES SHADE ABOVE KITCHEN SINK WILL NOT STAY DOWN & WILL NOT ROLL UP PROPERLY

CAUSE: Kitchen shade will not roll up at times spring is pretty weak.

CORRECTION: Remove and replace window shade with new one. Part needs to be ordered.

<b>Labor</b>		
Job #	Description	Total
7	KITCHEN SHADE	95.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100426770	ROLLER SHADE, 44" X 32" BASELINE - BLACK (47072)	1.00	54.65	54.65

**Subtotal for Job #7: 149.65**

**Job #8 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES ON THE ENTRY DOOR THERE IS A BROKEN CLIP

CAUSE: Entry door window inner trim has a broken tab.

CORRECTION: Remove and replace inner window trim with new one. Need to order part.

<b>Labor</b>		
Job #	Description	Total
8	ENTRY DOOR SHADE	57.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100244610	ENTRY DOOR PART: TOP/BOTTOM INTERIOR WINDOW BEZEL	1.00	8.12	8.12

**Subtotal for Job #8: 65.12**

**Job #9 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES TIRE PRESSURE MONITORS ARE MISSING ON THE PASS. SIDE - AIR COVERS

CAUSE: Valve stem caps are missing on curb side.

CORRECTION: Replaced valve stem caps.

<b>Labor</b>		
Job #	Description	Total
9	TIRE PRESSURE MONITORING SYSTEM	19.00





**Subtotal for Job #9: 19.00**

**Job #10 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES INSIDE SHOWER HEAD LEAKING

CAUSE: Shower head leaks when water system is pressurized

CORRECTION: Replace shower head with new one.  
 Part needs to be ordered.

**Labor**

Job #	Description	Total
10	SHOWER HEAD LEAKING	19.00

**Subtotal for Job #10: 19.00**

**Job #11 - Warranty**

COMPLAINT: JOB ADDED: CUSTOMER STATES WHEN DRIVING SLOWLY AXLES ARE MAKING A HORRIBLE SQUEAKING SOUND WHEN BACKING UP & GOING FORWARD

CAUSE: Suspension makes noise when flexing while being moved around.

CORRECTION: Lubricated spring Shackles and bolts.

**Labor**

Job #	Description	Total
11	BRAKESVAXLE ADJUST	57.00

**Subtotal for Job #11: 57.00**

**Job #12 - Internal**

COMPLAINT: Transferred to RV\*72707-1 on 02 APR 26  
 Estimate amount was 0.00

JOB ADDED: CUSTOMER STATES SMOKE DETECTOR KEEPS GOING OFF WHEN USING STOVE OR MICROWAVE

CAUSE: Ran stove and microwave for several minutes with no problems. Smoke Detector never went off.

CORRECTION: Cannot duplicate problem.

**Labor**

Job #	Description	Total
12	SMOKE DETECTOR R&R	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS-1	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C

**Subtotal for Job #12: 0.00**

**Job #13 - Internal**

COMPLAINT: Transferred to RV\*72707-1 on 02 APR 26  
 Estimate amount was 0.00

JOB ADDED: CUSTOMER STATES WHEN FURNACE IS ON AUTO COLD ARE COMES OUT THE AC VENT

CAUSE: A/C fan is on when furnace is running to Circulate air inside in coach.

CORRECTION: System is functioning properly.

**Labor**

Job #	Description	Total
13	FURNACEVAC	N/C



Subtotal for Job #13: 0.00

Job #14 - External

COMPLAINT: Transferred to RV\*72707-1 on 02 APR 26  
Estimate amount was 0.00  
03.31.26: CUSTOMER REQUESTS DE-WINTERIZE

CAUSE:  
1001 CUSTOMER REQUESTED we dewinterize The unit

CORRECTION:  
De winterized the unit.Filled up fresh tank emptied the gray and black tanks ran a copious amount of water through all water systems.Check tire pressure make sure water pump was pumping correctly all was good

Labor		
Job #	Description	Total
14	DEWINTERIZEVFLUSH	N/C
<b>Subtotal for Job #14:</b>		<b>0.00</b>

Job #WIN-STD - External

COMPLAINT: Transferred to RV\*72707-1 on 02 APR 26  
Estimate amount was 0.00  
WINTERIZE STANDARD

CAUSE: Winterize RV basic

CORRECTION: Completed

Labor				
Job #	Description	Total		
WIN-STD	WINTERIZE RV - BASIC	N/C		
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
<b>Subtotal for Job #WIN-STD:</b>				<b>0.00</b>

Parts Total: 667.64  
 Labour Total: 2,289.50  
 Sublet Total: 0.00  
 Extras Total: 420.85  
**WORK ORDER TOTAL: 3,377.99**

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : \_\_\_\_\_

Date: 28 May 2026

W/O: 72707  
Promised Date: 26 MAY 26

Customer #: 60727  
MARTINO, MELISSA ANN

