

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66108

Completed : 21 JAN 22 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10073 Description : 2019 SPRINGDALE 280BH
Tag : Date In : 14 DEC 21 Mileage :
Author : BJW Promised : 29 JAN 22
Location : 0201 CHECK WORK Date Sched :
Serial# : 4YDT28021K3100341 Chassis# : 4YDT28021K3100341
Warr. Date : 23 MAR 19 Cust PO# :
Print Date : 21 JAN 22

Job # Description JOB INFORMATION Type Bill To

DAMA DAMAGE NOTES - ROOF MEMBRANE IS TORN ON ROADSIDE, W 1013 KEYST
 MIDDLE/FRONT. WATER ENTRY HAS CAUSED INTERIOR
 DAMAGE.
ROOF COMPLAINT: REPLACE COMPLETE ROOF MEMBRANE WITH NEW W 1013 KEYST
 UNDERLAYMENT AND DECKING IF NEEDED.
 CAUSE: helped bret lay roof
 CORRECTION: REMOVED GUTTERS ON BOTH SIDES AND
 AWNING. REMOVED FRONT AND REAR TRIM.
 REMOVED TWO VENTS AND TWO PIPE VENTS.
 REMOVED SKYLIGHT. REMOVED AIRCON.
 REEMOVED RUBBER ROOF. GLUE AND STAPLE
 DOWN NEW 1/4'' UNDER LAYMENT. TAPE OFF
 SEAMS AND EDGES. GLUE DOWN NEW RUBBER
 ROOF. PUT BACK GUTTERS AND AWNING. PUT ON
 NEW FRONT AND REAR TRIM. PUT BACK VENTS
 AND TWO NEW PIPE VENTS. PUT BACK
 SKYLIGHT. DICOR WHERE NEEDED. AND
 SILICONE WHERE NEEDED. REMOVE AIRCON
 SEAL AND PUT A NEW ONE ON. MOUNT AIRCON
 AND RUN TO MAKE SURE IT WORKS. REMOVE
 DOOR FRAME TO BEDROOM. REMOVE FACE
 PLATES ON SLIDEROOM. REMOVE RUBBER SEAL
 ON INSIDE OF SLIDEROOM. REMOVE WINDOW IN
 BEDROOM. REMOVE DAMAGED WALLS AND
 STAPLES. CUT AND INSTALL NEW PANELS.
 ROUTER OUT WINDOW. RE INSTALL WINDOW.
 PUT SEAL BACK AND INSIDE TRIM. PUTTY
 WHERE NEEDED.

Job # Part No Description PARTS Bill to Qty Price Total

ROOF PUTTY PUTTY TAPE - ROLL W-1013 3 5.41 16.23
ROOF BRV320481 A/C GASKET PACKAGE 14"X 14" W-1013 0 15.25 0.00

Continued on page 2

Work Order : 66108

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
ROOF	520357	1/4" UNDERLAYMENT		W-1013	8	32.20	257.60
ROOF	31-8490	40033 REPLACE ALL PLUMBING		W-1013	0	1.07	0.00
ROOF	220849	CONSTRUCTION ADHES		W-1013	10	3.43	34.30
ROOF	4713	48" X 96" TWEED PANEL		W-1013	0	47.17	0.00
ROOF	12246	WOOD DECKING		W-1013	0	43.84	0.00
ROOF	376374	Adhesive - Roof -		W-1013	2	59.55	119.10
ROOF	238454	Sealant - Self Lev		W-1013	12	6.87	82.44
ROOF	396327	Roof - Membrane -		W-1013	1	386.53	386.53
ROOF	541120	Seam - Tape - 1" -		W-1013	1	22.52	22.52
ROOF	40138	REPLACE-ALL PLUMB VENT - BL		W-1013	2	3.84	7.68
ROOF	E469	E469 BLACK HD 1" x 100' INS		W-1013	1	19.56	19.56
ROOF	20-6908	Flat Trim Type; 1-		W-1013	1	16.16	16.16
ROOF	13-1287	NON SELF LEVELING DICOR		W-1013	2	6.12	12.24
ROOF	219088	SILICONE II BLACK		W-1013	1	8.04	8.04
ROOF	500627	SILICONE - N PLUS - CLEAR		W-1013	1	7.73	7.73
ROOF	568579	PANEL -5/32" x 48"		W-1013	3	39.57	118.71

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
AMAGE	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.00	130.00	0.00
AMAGE	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.00	130.00	0.00
AMAGE	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.00	130.00	0.00
AMAGE	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.00	130.00	0.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	1.00	130.00	130.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.00	150.00	0.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	5.99	150.00	898.50
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.06	150.00	9.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	0.24	150.00	36.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	3.11	150.00	466.50
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	4.21	150.00	631.50
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	2.16	130.00	280.80
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	2.97	130.00	386.10
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	4.18	130.00	543.40
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	4.04	130.00	525.20
ROOF	Z990	MISCELLANEOUS REPAIR	SAR		W-1013	1.00	130.00	130.00
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	4.06	130.00	527.80
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	3.99	130.00	518.70
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	1.09	130.00	141.70
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	2.89	130.00	375.70
ROOF	Z990	MISCELLANEOUS REPAIR	BB		W-1013	4.01	130.00	521.30

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
ROOF	SS	SHOP SUPPLIES		W-1013	0.00	35.00	0.00
ROOF	FRT	FREIGHT		W-1013	1.00	250.00	250.00
ROOF	EDF	ENVIROMENTAL DISPOSAL FEES		W-1013	0.00	150.00	0.00
ROOF	FRT	FREIGHT & CRATE - PANELING		W-1013	1.00	134.36	134.36

Continued on page 3

Work Order : 66108

CUSTOMER COMMENTS*****
PANELING IN SHOP 1A 1-17-22....CAM
ROOF MEMBRANE HERE 12-20-21. IN 1A.
ROOF ADHESIVE AND LAP SEALANT ARRIVED 12-17-21
SEAM TAPE ARRIVED 12-16-21
PARTS ORDERED PER BEN. 12-14-21
BH TALKED WITH JOHN GURL ABOUT APPROVEL
KEYSTONE IS ALLOWING 45 HRS ONLY*****
BILLINGS SUMMARY*****
Type Bill Id Parts Labour Sublet Extras Tax Total

W 1013 1108.84 6122.20 0.00 384.36 0.00 7,615.40

 Totals 1108.84 6122.20 0.00 384.36 0.00 7,615.40