

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66115

Completed : 21 FEB 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10479 Description : 2021 TT FOREST RIVER CHEROKEE 306MM
Tag : Date In : 14 DEC 21 Mileage : 0
Author : BJW Promised : 29 JAN 22
Location : 0223 SEE IF BEN HAS Date Sched :
Serial# : 4X4TCKG20MX148051 Chassis# : 4X4TCKG20MX148051
Warr. Date : 02 JAN 21 Cust PO# :
Print Date : 21 FEB 22

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: SLIDE IS LEAKING WHEN IT IS OUT E 42536 Dunca
CORRECTION: FOUND THAT ALL OF THE SLIDE SEALS WERE
DRY. SPRYED ALL OF THE SLIDE ROOM SEALS
WITH SEAL SAVER. THE SEALS ON THE OFF
DOOR SIDE HAD PINE NEEDLES UNDER THE
SEALS AND THE SEALS WERE GETTING STUCK
FLIPPED IN. I CLAENED THE SLIDE ROOM
ROOFS. I SPRAYED THE INSIDE AND OUTSIDE
OF THE UPPER SEALS TO GET THEM TO SOFTEN
UP AND FLIP OUT LIKE THEY SHOULD. THE
SMALL MARK UNDER THE SLIDE ROOM WAS FROM
THE CABLE ARM UNDER THE SLIDE ROOM. I
PATCHED THE HOLE AND ADDED A SMALL
PLASTIC PLATE UNDER THE UNDER BELLY TAPE
TO PREVENT THE HOLE FROM COMING BACK.
2 COMPLAINT: NON DOORSIDE SLIDE OUT HAS CRACK FRONT W 10024 FORES
CORRECTION: SEALED UP THE RUBBER TRIM AT THE BASE OF
THE SLIDE ROOM OPENING
3 COMPLAINT: CUSTOMER STATES THAT THE BATTERY DOES W 10024 FORES
NOT CHARGE WHEN HOOKED OT SHORE POWER.
CORRECTION: FOUND THAT THE CONVERTER WAS BAD AND I
ORDERED A NEW ONE. INSTALLED THE NEW
CONVERTER AND TESTED.
4 COMPLAINT: CUSTOMER STATES THAT THERE IS A STRONG W 10024 FORES
ODOR FROM THE BLACK TANK IN THE BATHROOM
CORRECTION: USED BLACK TANK FLUSH AND THE ODOR IN
THE BATHROOM GOT BAD. THE TOILET HAD
WATER IN IT AND I COULD STILL SMELL THE
ODOR. I CHANGED THE SEAL UNDER THE
TOILET AND USED THE BLACK TANK FLUSH
AGAIN. THE ODOR DID NOT COME BACK.
5 COMPLAINT: WE DID A REPAIR TO THE DOOR SIDE FRONT I SEP SERVI
SLIDE ROOM EARLIER IN THE YEAR. NOW WHEN

Continued on page 2

Work Order : 66115

 Job # Description JOB INFORMATION Type Bill To

THE SLIDES ARE OUT, IT IS NOTICABLE THAT
 THE ROOM IS TIPPING IN TOWARDS THE
 CAMPER. THIS IS EASIER TO NOTICE IF YOU
 RUN THE ROOM OUT AND GET BACK AWAY FROM
 THE CAMPER.

CORRECTION: ALL OF THE SLIDE ROOMS HAVE A TILT TO
 THEM. THAT IS THE WAY THEY ARE MADE. THE
 ROOF OF THE SLIDE IN QUESTION IS SQUARE
 WITH THE FLOOR AS IT SHOULD BE. ALL OF
 THE TRIM INSIDE THE CAMPER FITS THE WALL
 AS IT SHOULD. I DO NOT SEE ANYTHING
 WRONG WITH IT.

 Job # Part No Description PARTS Bill to Qty Price Total

1	13-3008	3X - CHEMISTRY SLIDE SEAL S	E-42536	1	14.99	14.99
3	40E12194A	CONVERTER, CHARGER	W-10024	1	186.01	186.01
4	44-0963	THETFORD BOLT PACKAGE	W-10024	1	9.33	9.33

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

1	Z990	MISC LABOUR CODE (EXTE GAH	E-42536	0.00	130.00	0.00
1	Z990	MISC LABOUR CODE (EXTE GAH	E-42536	0.73	130.00	94.90
1	Z990	MISC LABOUR CODE (EXTE GAH	E-42536	0.27	130.00	35.10
2	Z990	MISC LABOUR CODE (EXTE GAH	W-10024	0.00	130.00	0.00
2	Z990	MISC LABOUR CODE (EXTE GAH	W-10024	0.50	130.00	65.00
3	Z990	MISC LABOUR CODE (EXTE GAH	W-10024	0.50	130.00	65.00
3	Z990	MISC LABOUR CODE (EXTE GAH	W-10024	0.00	130.00	0.00
3	Z990	MISC LABOUR CODE (EXTE	W-10024	0.00	150.00	0.00
4	Z990	MISC LABOUR CODE (EXTE GAH	W-10024	0.50	130.00	65.00
5	Z990	MISC LABOUR CODE (EXTE GAH	I-SEP	0.80	25.00	20.00

 Job # Excode Description EXTRAS bill to Qty Price Total

1	SS	SHOP SUPPLIES	E-42536	1.00	13.00	13.00
3	FRT	UPS-CONVERTER	W-10024	1.00	15.68	15.68

 CUSTOMER COMMENTS

 ASSIGNED TO GRED. DH

CONVERTER ARRIVED IN BACKROOM 2-17-22...CAM
 EMAILED FOR STATUS OF THE CONVERTER 2-15-22...CAM
 OLD CONVERTER ON WARRANTY SHELF. MATT TAGGED.
 CONVERTER ORDERED PER BJ. 12-29-21

Continued on page 3

Work Order : 66115

BH SENT IN PREAUTH FOR JOB 2/4
 BH SENT IN PREAUTH FOR JOB 3

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	42536	14.99	130.00	0.00	13.00	1.96	159.95
I	SEP	0.00	20.00	0.00	0.00	0.00	20.00
W	10024	195.34	195.00	0.00	15.68	0.00	406.02
	Totals	210.33	345.00	0.00	28.68	1.96	585.97