

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66124

Completed : 25 FEB 22
Licence # :
Stock No :
Tag :
Author : BJW
Location : 0228 SEE IF CUSTOMER
Serial# : 4YDF36827K2510179
Warr. Date : 12 AUG 19
Print Date : 25 FEB 22
Customer : 1013 - KEYSTONE RV CO -
Invoice # :
Description : 2019 5W KEYSTONE COUGAR 368MBI
Date In : 15 DEC 21
Promised : 28 FEB 22
Mileage : 0
Date Sched :
Chassis# : 4YDF36827K2510179
Cust PO# :

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: FURNANCE WONT RUN LONGER THAN 5 OR 6 E 49171 FOSTE
MINUTES OWNER SEES NO OBSTRUCTION
CORRECTION: HELPED SHAWN REMOVE BURNER AND CLEAN AND
PUT BACK TOGETHER AND THEN WE FOUND THAT
THE VOLTAGE WAS DROPPING OUT SO WE
REMOVED THE BREAKER AND INSTALLED A 15
AMP FUSE.
2 COMPLAINT: RECALL FOR THE ANTENNA 20-381 W 1013 KEYST
CORRECTION: CHECK PICTURES REMOVED RECALLED PART AND
INSTALL NEW PART AS REQUESTED FOR RECALL
3 COMPLAINT: RECALL FOR FRAME BRACE IS 21-411 W 1013 KEYST
CAUSE: INSTALLED THE FRAME RECALL KIT COULD NOT
INSTALL THE GUSSET THAT THEY PROVIDED DO
TO IT WAS ALREADY INSTALL FROM FACTORY
4 COMPLAINT: TOILET WONT HOLD WATER THE CUSTOMER WAS E 49171 FOSTE
WANTING TO ADD SPRAY NOSLE FOR SPRAYING
AROUND THE TOILET BOWL. BUT WANTS PRICE
TO DO THIS FIRST.
CAUSE: TOOK PICTURES PUT IN PO FOR HOSE
CORRECTION: GAVE CUSTOMER PRICE OF APPROX \$275.00 TO
INSTALL TOILET SPRAYER. CUSTOMER
DECLINED TOILET SPRAYER AT THIS TIME

Job # Part No Description PARTS Bill to Qty Price Total

2 612341 Antenna - TV - Air 360 - UH W-1013 1 26.17 26.17
2 558355 Radio - Antenna Cord - For W-1013 1 13.11 13.11
2 13-1320 PW HAPS FREE SELF-LEVELING W-1013 1 6.03 6.03
3 681711 FRAME -KS-AXLE BRA W-1013 3 50.11 150.33
3 501127 FRAME - OUTRIGGER W-1013 1 16.68 16.68
3 682401 BOLT - #13-1/2"x1- W-1013 12 0.37 4.44
3 163795 NUT - 13 - 1/2" - W-1013 12 0.16 1.92
4 385319054 VACUUM BREAKER/SEALAND W/SP E-49171 0 0.00 0.00

Continued on page 2

Work Order : 66124

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs      Rate      Total
*****
  1  Z990      MISC LABOUR CODE (EXTE SAR    E-49171      0.17      150.00      25.50
  1  Z990      MISC LABOUR CODE (EXTE SAR    E-49171      0.83      150.00     124.50
  1  Z990      MISCELLANEOUS REPAIR    BRM    E-49171      1.00      150.00     150.00
  2  Z990      MISCELLANEOUS REPAIR    SAR    W-1013      0.35      150.00      52.50
  2  Z990      MISCELLANEOUS REPAIR    SAR    W-1013      0.35      150.00      52.50
  3  Z990      MISCELLANEOUS REPAIR    SAR    W-1013      0.50      150.00      75.00
  4  Z990      MISC LABOUR CODE (EXTE    E-49171      0.00      150.00       0.00
  4  Z990      MISC LABOUR CODE (EXTE SAR    E-49171      0.00      150.00       0.00
*****

```

```

*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
  1  SS        SHOP SUPPLIES      E-49171      1.00      30.00      30.00
  3  FRT        UPS-FRAME PARTS    W-1013      1.00      49.30      49.30
*****

```

CUSTOMER COMMENTS

```

*****
BW CALLED ON 02/25 @ 11:15 AM AND LEFT MESSAGE WITH CUSTOMER TO GET AUTH
TO ADD A SPRAYER TO TOILET FOR APPROX $275.00 P&L
*****

```

BH GOT APPROVAL.

BH SNET IN PREAUTH FOR BOTH RECALLS THERE IS TO 2 PREAUTHS
 FRAME PARTS IN BACKROOM 1-25-22...CAM
 ORDERED RECALL KIT 1-13-22
 UNIT NOT HERE

```

*****
BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
E    49171         0.00      300.00         0.00      30.00      2.10      332.10
W    1013        218.68      180.00         0.00      49.30      0.00      447.98

Totals          218.68      480.00         0.00      79.30      2.10      780.08
*****

```