



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 80101



CUSTOMER WORK ORDER

WO #: 80101

Customer: 56862 - FREEMAN, DAVID -
618-572-0441

Tag:

Author: BH

Location: 0609 CHECK PREAUTH

Stock #: 11721

Stock Desc: 2026 5W KEYSTONE
COUGAR HALF-TON 28RLI

Chassis #: 4YDFCGN27T2505074

Serial #: 4YDFCGN27T2505074

Mileage:

Licence:

Invoice #:

Date In: 01 JUN 26

Promised:

Date Sched:

Completed: 08 JUN 26

Warr. Date: 11 JUN 26

Job #20KPULLRITE - Internal

INSTALL 20K PULLRITE OE FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
1800	PLR1800 25K OE SERIES SUPER 5TH HITC	1.00	N/C	N/C
14-2976	95-01-9415 2-PK SOCKET PINS W/CLIPS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #20KPULLRITE: 0.00

Job #FPDINFW - Internal

FINAL PDI ON NEW FIFTH WHEELS

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINFW: 0.00

Job #1 - Warranty

COMPLAINT: THE PANTRY DOOR SCREW PULLED OUT AND NEEDS FIXED

CAUSE: Pantry door stop pulled out.

CORRECTION: I re shot the screw not so close to the edge and it works properly now.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------

Customer #: 56862
FREEMAN, DAVID



Subtotal for Job #1: 38.00

Job #2 - Warranty

COMPLAINT: INSIDE OF THE PANTRY DOOR TRIM HAS COME LOOSE

CAUSE: Pantry wall panel loose

CORRECTION: Pushing back in and shot some stapels in it and puddy up the holes

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	19.00

Subtotal for Job #2: 19.00

Job #3 - Warranty

COMPLAINT: CABINET DOORS ARE NEEIDNG TO BE ADJUSTED NEAR THE MICROWAVE

CAUSE: Cabinet door out of adjustment

CORRECTION: Adjusted the cabinet doors so they would close and not hit each other. They shut properly now

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	38.00

Subtotal for Job #3: 38.00

Customer Order Work

Parts Total: 0.00
 Labour Total: 95.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 95.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 Jun 2026

W/O: 80101



Customer #: 56862
FREEMAN, DAVID

