

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66129

Completed : 28 FEB 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10937 Description : 2021 5W FOREST RIVER SABRE 38DBQ
Tag : Date In : 17 DEC 21 Mileage : 0
Author : BJW Promised : 28 FEB 22
Location : 0307 BEN TO CLOSE Date Sched :
Serial# : 5ZT3SR3B1M6106872 Chassis# : 5ZT3SR3B1M6106872
Warr. Date : 24 APR 21 Cust PO# :
Print Date : 07 MAR 22

Job # Description JOB INFORMATION Type Bill To

1 COMPLAINT: MAIN ENTRANCE IS NOT SQUARE TO THE DOOR W 10024 FORES
 PROBLEMS LOCKING AND CLOSING. CAN NOT
 USE DEADBOLT.
 CAUSE: replace damaged door
 CORRECTION: removed plastic screw covers. removed
 top trim piece. removed mounting screws.
 removed entry steps. removed door.
 removed new door from box. installed
 foam seal to new door. installed new
 door with mounting screws. sealed
 outside with silicone installed plastic
 screw covers. installed top trim piece.
 sealed trim piece with silicone.
 adjusted door latches on both screen
 door and entry door. installed entry
 steps. cleaned up mess.
2 COMPLAINT: CUSTOMER NOTICED WHEN TAKING A SHOWER W 10024 FORES
 THE BOTTOM OF THE DOOR TO THE PAN OF THE
 SHOWER IS NOT SELING AND LEAKING ON THE
 FLOOR.
 CAUSE: noticed white "sealer" on the bottom of
 the shower surround where someone tried
 to fix the leak.
 CORRECTION: removed sealer from bottom corner of
 surround. clean up area as needed.
 applied clear silicone to both bottom
 corners of surround and along the bottom
 on the inside of shower.
ROOF COMPLAINT: Transferred to BAS*66646 on 02 MAR 22 E 49052 BLAND
 Estimate amount was 0.00 INSPECT ROOF
 AND SEAMS - FILL VOIDS TT/FW
 CAUSE: ROOF INSPECTION
 CORRECTION: APPLIED LAP SEALANT AS NEEDED.
4 COMPLAINT: THE REFER DOOR IS RUBBING THE SEAL FOR W 10024 FORES

Continued on page 2

Work Order : 66129

 Job # Description JOB INFORMATION Type Bill To

CAUSE: THE OUTSIDE KITCHEN
 seal ddamaged from fridge door. needs
 replaced.

CORRECTION: removed old seal. went and found
 replacement seal in backroom. applied
 new seal to compartment.

5 COMPLAINT: Transferred to BAS*66646 on 02 MAR 22 I SPN SALES
 Estimate amount was 0.00 BACK-UP CAMERA
 IS NOT CONNECTING

CAUSE: CUSTOMER STATES THE BACK UP CAMERA WONT
 PAIR. HOOKED UP CAMERA TO TESTER.
 CAMERA PAIRED WITH NO ISSUES. MONITOR
 PANEL IS MISSING THE ANTENNA. **NEED
 CUSTOMERS TRUCK TO MAKE SURE IT IS
 WORKING WITH TRUCK**

CORRECTION: NO CORRECTION AT THIS TIME

6 COMPLAINT: Transferred to BAS*66646 on 02 MAR 22 E 49052 BLAND
 Estimate amount was 0.00 CHECK ON THE
 TIRE PRESSURE VALVE STEM CAPS WHAT IS
 NEEDED IF THE TIRES GET LOW.

CAUSE: customer has tire pressure gauges on all
 tires.

CORRECTION: tested valve stems and caps with soapy
 water to check for leaks. no leaks were
 found.

 Job # Part No Description PARTS Bill to Qty Price Total

 1 F100293225 ENTRY DOOR, 26" X W-10024 1 307.07 307.07
 ROOFT 13-1320 PW HAPS FREE SELF-LEVELING E-49052 0 9.99 0.00
 ROOFT BRV47996 SILICONE II - WHITE E-49052 0 9.99 0.00
 4 20X68196A SEAL, WEDGE SEAL R W-10024 20 1.37 27.40

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.76 130.00 98.80
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.24 130.00 31.20
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 150.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 130.00 0.00
 ROOFT Z990 MISC LABOUR CODE (EXTE ZMS E-49052 0.00 130.00 0.00
 ROOFT Z990 MISC LABOUR CODE (EXTE ZMS E-49052 0.00 105.00 0.00
 4 Z990 MISC LABOUR CODE (EXTE ZMS W-10024 0.00 105.00 0.00
 0.00 130.00 0.00

Continued on page 3

Work Order : 66129

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs      Rate      Total
*****
  4  Z990      MISC LABOUR CODE (EXTE ZMS  W-10024      0.30     130.00     39.00
  4  Z990      MISC LABOUR CODE (EXTE ZMS  W-10024      0.00     130.00      0.00
  4  Z990      MISC LABOUR CODE (EXTE      W-10024      0.00     150.00      0.00
  4  Z990      MISC LABOUR CODE (EXTE ZMS  W-10024      0.00     130.00      0.00
  5  Z990      MISC LABOUR CODE (EXTE ZMS  I-SPN        0.00      25.00      0.00
  6  Z990      MISC LABOUR CODE (EXTE ZMS  E-49052      0.00     130.00      0.00
*****

```

```

*****
Job #  Excode  Description      EXTRAS      bill to      Qty      Price      Total
*****
  1  FRT      CEVA FREIGHT - ENTRY DOOR  W-10024      1.00     135.00     135.00
ROOFT  SS      SHOP SUPPLIES              E-49052      0.00      0.00      0.00
  4  FRT      UPS-SEAL                    W-10024      1.00      13.02     13.02
*****

```

CUSTOMER COMMENTS

CUSTOMER PICKED UP UNIT 3/5/22

BW SPOKE WITH ZS. ZACH IS PLANNING ON HAVING THIS UNIT COPLETED
EARLY THE WEEK OF 02/28
CUSTOMER CALLED AND SPOKE WITH BW ON 02/23 @ 9:30 TO CHECK
STATUS. BW TOLD CUSTOMER THAT, UNLESS SOMETHING UNFORSEEN COMES
UP, WE SHOULD HAVE UNIT COMPLETED BY END OF WEEK OF 03/04/22
PARTS MOVED TO RED TRAILER 1-18-22...CAM

ENTRY DOOR IN SHOP 1A 1-7-22...CAM
SEAL IN BACKROOM 1-4-22...CAM
SEAL AND DOOR ORDERED. 12-28-21
BH GAVE PARTS SHEET TO MATT
BH GOT APPROVAL FOR JOBS 1/2/4
BH SENT IN PREAUTH FOR JOB 1/2/4
FOREST RIVER DENIED JOB 2 PURCHASING CUSTOMER ALSO NEED TO CHECK
SEALANTS EVERY 6 MONTHS AND IS CONSIDERED MAINTENANCE.

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      10024      334.47      169.00      0.00      148.02      0.00      651.49
Totals      334.47      169.00      0.00      148.02      0.00      651.49
*****

```