

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	886549
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CAZB4NX024356
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	205 / 205
Labor rate:	\$130.00	ITEM #	ACAT343BHTSLE
OWNER INFORMATION		DEALER RO #	66171
AMANDA S LYNCH		CLAIM START DATE	01/04/2022
2013 CO RD 1020 N		CLAIM END DATE	01/01/1900
Fairfield, IL 62837			
USA			
Retail Date of Purchase	12/23/2021	WARRANTY EXPIRATION DATE	12/23/2022

Claim Line Details

Labor
Line# 1

Operation Code
70-306-01-11-002742

Operational Description
EverChill, Cannon Refrigerator -12 Volt - complete - Appliances/
Refrigerator (Everchill, Cannon)/Replace/Electrical

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:18:14 :: FREEZER DOOR WONT SHUT took
ref out 6 inches and took freezer door off and found plastic spacer was on the other side of door, switched
spacer to other side and put back together and adjusted door and all is good.

Model #
Serial #

GPV10FSNBSB
ZR569754

Dlr Sub Hrs
Appr Hrs

0.75
0.50

Sub Labor Amt
Appr Labor Amt

\$97.50
\$65.00

Notes
excessive time requested per repair description

Labor
Line# 2

Operation Code
40-112-24-11-001350

Operational Description
Monitor Panel Wiring or Harness - Electrical/Monitor Panel/Repair/
Electrical

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:22:27 :: GREY ONE TANK FULL SHOWS
EMPTY found ground wire was no good ,ran new ground wire and it works.

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.60
0.30

Sub Labor Amt
Appr Labor Amt

\$78.00
\$39.00

Notes
excessive time requested per repair description

Labor
Line# 3

Operation Code
40-112-24-11-001350

Operational Description
Monitor Panel Wiring or Harness - Electrical/Monitor Panel/Repair/
Electrical

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:23:32 :: GREY TWO TANK FULL SHOWS
EMPTY cut underbelly to get to tank and wires checked wiring and found ground was bad,added new ground
and it works,taped up underbelly.

Model #
Serial #

Dlr Sub Hrs
Appr Hrs

0.60
0.30

Sub Labor Amt
Appr Labor Amt

\$78.00
\$39.00

Notes
excessive time requested per repair description

Labor
Line# 4

Operation Code
30-100-02-00-003062

Operational Description
Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:24:06 :: BUNK BED WONT RAISE UP AND LATCH HAD TO TIGHTEN UP SCREWS IN WALL.

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$26.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$13.00

Notes
excessive time requested per repair description

Labor
Line# 5

Operation Code
10-12-15-00-000256

Operational Description
Slide Out Gears - Frame & Chassis/Slide Out System - Lippert/Repair or Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:25:17 :: FRONT SLIDE WONT COME IN AT THE BOTTOM LOOSEENED BELL ON SLIDE AND ADJUSTED.

Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$52.00
Serial #	Appr Hrs	0.40	Appr Labor Amt	\$52.00

Notes

Labor
Line# 6

Operation Code
10-12-15-00-000256

Operational Description
Slide Out Gears - Frame & Chassis/Slide Out System - Lippert/Repair or Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2022-01-04 17:26:51 :: REAR SLIDE WONT COME IN AT THE BOTTOM lossened bell out and adjusted,room comes in now.

Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$52.00
Serial #	Appr Hrs	0.40	Appr Labor Amt	\$52.00

Notes

Submitted

Labor Amt	\$383.50
Parts & Freight	\$0.00
Total	\$383.50

Approved

Labor Amt	\$260.00
Parts & Freight	\$0.00
Total	\$260.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.