

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66171

Completed : 30 DEC 21 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10942 Description : 2022 TT COACHMEN CATALINA 343BH7SLE
Tag : Date In : 23 DEC 21 Mileage :
Author : BH Promised : 28 DEC 21
Location : 0108 CHECK PREAUTH Date Sched :
Serial# : 5ZT2CAZB4NX024356 Chassis# : 5ZT2CAZB4NX024356
Warr. Date : 28 DEC 21 Cust PO# :
Print Date : 05 JAN 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: PDI - NEW TRAVEL TRAILER I PDI PRE-D
CORRECTION: PDI DONE.
FPDI COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS I PDI PRE-D
CORRECTION: FINAL DONE.
EQUA COMPLAINT: INSTALL 1400# EQUALIZER HITCH I DO DEALE
CORRECTION: SET UP HITCH ON TRUCK.
DELU DELUXE STARTER KIT I DO DEALE
WALK COMPLAINT: WALK THRU I PDI PRE-D
CAUSE: walk through
CORRECTION: walk through went good
1 COMPLAINT: FREEZER DOOR WONT SHUT W 10024 FORES
CORRECTION: took ref out 6 inches and took freezer
door off and found plastic spacer was on
the other side of door,switched spacer
to other side and put back together and
adjusted door and all is good.
2 COMPLAINT: GREY ONE TANK FULL SHOWS EMPTY W 10024 FORES
CORRECTION: found ground wire was no good ,ran new
ground wire and it works.
3 COMPLAINT: GREY TWO TANK FULL SHOWS EMPTY W 10024 FORES
CORRECTION: cut underbelly to get to tank and wires
checked wiring and found ground was
bad,added new ground and it works,taped
up underbelly.
4 COMPLAINT: BUNK BED WONT RAISE UP AND LATCH W 10024 FORES
CORRECTION: HAD TO TIGHTEN UP SCREWS IN WALL.
5 COMPLAINT: FRONT SLIDE WONT COME IN AT THE BOTTOM W 10024 FORES
CORRECTION: LOOSENED BELL ON SLIDE AND ADJUSTED.
6 COMPLAINT: REAR SLIDE WONT COME IN AT THE BOTTOM W 10024 FORES
CORRECTION: lossened bell out and adjusted,room
comes in now.

Continued on page 2

Work Order : 66171

Job #	Part No	Description	PARTS	Bill to	Qty	Price

						Total
PDINT	13034	55362 STD BATTERY		I-PDI	1	10.95
FPDIN	DC-24	ADVANCE GROUP 24 D		I-PDI	1	126.99
FPDIN	5516	A10-3050FHVP 30M-5		I-PDI	1	23.99
FPDIN	24181	-50 RV ANTI-FREEZE		I-PDI	2	4.99
EQUAL	14-2969	14,000lb EQUALIZER		I-DO	1	697.95
EQUAL	14-8627	2-5/16" 14K HITCH		I-DO	1	28.99
EQUAL	14-2931	90-02-4300 EQUALIZ		I-DO	1	152.99
DELUX	44722	DELUXE STARTER KIT		I-DO	1	137.99

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate

							Total
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		1.49	130.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		0.62	130.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		2.46	130.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		0.35	130.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		0.50	130.00
DINTT	Z991	MISC LABOUR CODE (INTE DGH		I-PDI		0.58	130.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL DGH		I-PDI		1.26	130.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL DGH		I-PDI		0.74	130.00
LIZER	Z990	MISC LABOUR CODE (EXTE DGH		I-DO		0.29	85.00
LIZER	Z990	MISC LABOUR CODE (EXTE DGH		I-DO		0.22	85.00
LIZER	Z990	MISC LABOUR CODE (EXTE DGH		I-DO		0.74	85.00
WALK	Z990	MISC LABOUR CODE (EXTE BAP		I-PDI		1.50	130.00
1	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.50	130.00
2	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.30	130.00
3	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.30	130.00
4	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.10	130.00
5	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.40	130.00
6	Z990	MISC LABOUR CODE (EXTE DGH		W-10024		0.40	130.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price

						Total
DINTT	SS	SHOP SUPPLIES		I-PDI	1.00	35.00
DINTT	LPGI	LP - UNIT SALES		I-PDI	8.00	3.99

CUSTOMER COMMENTS

BH SENT IN PREAUTH

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	DO	1017.92	106.25	0.00	0.00	0.00	1,124.17
I	PDI	171.91	1235.00	0.00	66.92	0.00	1,473.83
W	10024	0.00	260.00	0.00	0.00	0.00	260.00

Continued on page 3

Work Order : 66171

BILLINGS SUMMARY						
Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total

Totals	1189.83	1601.25	0.00	66.92	0.00	2,858.00