

DEALER ACCOUNT #	0009497	CLAIM STATUS	Paid
GREENEWAY INC		CLAIM	2556621
DBA GREENEWAY RV SALES & SERVICE		CLAIM ORIGIN	WEB
8220 STATE HWY 13 SOUTH		ORIGINAL CLAIM ID	
WISCONSIN RAPIDS, WI 54494		VIN	5ZT2PUEC5T4026247
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	425 / 425
Labor rate:	\$140.00	ITEM #	PUT16QBCE-1
OWNER INFORMATION		DEALER RO #	13189B
		CLAIM START DATE	01/20/2026
		CLAIM END DATE	05/29/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor		Operational Description	
Line#	Operation Code	Operational Description	
1	20-66-02-00-000678	Screen Door - Exterior/Entry Doors/Adjust/No Tread Code	
Complaint, Cause, Correction			
Original Note : greeneway@dealer-advisors.com, 2026-01-20 12:55:08 :: Complaint: The screen door will not close all of the way. The hinges on door are as adjusted as they can be and bottoming out so I cannot adjust them any further. Hole for entrance not cut correctly, possibly too small. Cause: Screen door catches bad. Frame is not installed correctly. Correction: Tightened the screws in the frame and used longer screws in screen door latch to suck frame in and filled the catches lip and now the door is clearing.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$28.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$28.00
Notes			

Line# 1	Item #	Description				
	USERPART	shop supplies - screws				
	Model #	Serial #			Part tag	
	Sub Qty 1.00	Sub Dlr Price \$1.40			Sub Freight	\$0.00
	Appr Qty 1.00	Appr Dlr Price \$1.40			Appr Freight	\$0.00
	Notes					

Line# 2	Operation Code		Operational Description	
	70-150-01-11-002780		Greystone Microwave - Appliances/Microwave/Replace/Electrical	
	Complaint, Cause, Correction			
	Original Note : greeneway@dealer-advisors.com, 2026-01-20 12:56:16 :: Complaint: The microwave push open button does not work. Cause: Faulty microwave push button. Correction: Replace microwave. M# GSMW09B			
	Serial number on back of microwave.			
Model#	1	Dlr Sub Hrs	0.50	Sub Labor Amt \$70.00
Serial#	1	Appr Hrs	0.30	Appr Labor Amt \$42.00
Notes				
pending photo of model/serial number data tag and cord cut from defective microwave				

Line# 1	Item #		Description			
	F100792490		TRIM KIT, FOR MICROWAVE WEIL BLACK 0.9CF GSMW09B (GRAYSTONE) LIPPERT			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.03	Sub Freight	\$5.00
	Appr Qty	1.00	Appr Dlr Price	\$0.03	Appr Freight	\$5.00

Notes

Line# 2

Item #	Description	
F100786781	MICROWAVE, GREYSTONE 0.9 CU FT, BLACK	
Model #	Serial #	Part tag
Sub Qty 1.00	Sub Dlr Price \$107.22	Sub Freight \$62.17
Appr Qty 1.00	Appr Dlr Price \$107.22	Appr Freight \$62.17

Notes**Labor**

Line# 3

Operation Code	Operational Description	
70-306-01-00-001800	Refrigerator Door - Appliances/Refrigerator (Everchill, Cannon)/Replace/No Tread Code	
Complaint, Cause, Correction		
Original Note : greeneway@dealer-advisors.com, 2026-01-20 12:57:36 :: Complaint: The refer door has a dent in the face of it. Cause: Dent in door from manufacturer. Correction: Replace door.		
Model# 1	Dlr Sub Hrs 1.20	Sub Labor Amt \$168.00
Serial# 1	Appr Hrs 0.00	Appr Labor Amt \$0.00

Notes

not noted on DAF
unit invoiced 10/30/2025
dealer goodwill part only
this must be ordered through parts department referencing this claim#

Part

Line# 1

Item #	Description	
F100548021	BOTTOM DOOR ONLY, FOR REFRIGERATOR, SS, 4.5 CU/FT, LH	
Model #	Serial #	Part tag
Sub Qty 1.00	Sub Dlr Price \$159.19	Sub Freight \$19.93
Appr Qty 1.00	Appr Dlr Price \$159.19	Appr Freight \$19.93

Notes

Submitted	Labor Amt	\$266.00	Approved	Labor Amt	\$70.00
	Parts & Freight	\$354.94		Parts & Freight	\$354.94
	Total	\$620.94		Total	\$424.94

DEALER
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

DATE

CUSTOMER
SIGNATURE
All repairs described have been inspected and are satisfactory.

DATE