

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12476B

Date In: 28 AUG 25 Author: MGRAY
Promised Date: 31 DEC 26 Stock No: 11434
: Year: 2026
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: IMAGINE
: WISCONSIN RAPIDS, WI Model: 2670MK
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 8/29 PART INQUIRY:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TE3222T6655639 :

Job #	Description	JOB INFORMATION	Type	Bill To
WARR	COMPLAINT: WARRANTY REPAIR 1 - screen door not latching		W	1020 GRAND
	CAUSE: The catch did not stick far enough out			
	CORRECTION: Cut a shim and put behind catch			
	REQUEST: .50 HOURS OF LABOR WARRANTY			
	AUTH: .30 HOURS OF LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 2 - 2 bubbles in the dicor		W	1020 GRAND
	CAUSE: Bubbles in dicor			
	CORRECTION: Cleaned areas then put dicor in and over the 2 areas	REQUEST .40 HOURS OF LABOR		
	WARRNATY AUTH: .40 HOURS OF LABOR			
WARR	COMPLAINT: WARRANTY REPAIR 3 - trim above windows in slide above dining area the finish is bubbled		W	1020 GRAND
	CAUSE: Trim in slide out ceiling is delaming on ods slide. Needs inside corner. Pics uploaded. Finish on trim is coming off			
	Please order small corner trim 1 stick but if you want to order more for stock it would be good this is a new pattern..			
	Close up pic taken for reference			
	CORRECTION: Installed inside corner trim above dinette slide.			
WARR	COMPLAINT: WARRANTY REPAIR 4 - to the right of entrance door trim along floor is scuffed finish coming off		W	1020 GRAND
	CAUSE: Scuffed			

Continued on page 2

Work Order : 12476B

 Job # Description JOB INFORMATION Type Bill To

 CORRECTION: Used putty to fill REQUEST .15 HOURS OF
 LABOR WARRANTY AUTH: .10 HOURS OF LABOR

WARR COMPLAINT: WARRANTY REPAIR 5 - deep staple holes W 1020 GRAND
 throughout unit
 CAUSE: Holes from staples
 CORRECTION: Filled with putty REQUEST: .15 HOURS OF
 LABOR WARRANTY AUTH: .10

 Job # Part No Description PARTS Bill to Qty Price Total

 WARR0 822011682 TRIM 5/16 X 5/8 X 8 HAVEN L W-1020 1 8.23 8.23

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 ARR01 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.50 140.00 70.00
 ARR02 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 140.00 14.00
 ARR03 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.11 140.00 15.40
 ARR03 WARR MANUFACTURER WARRANTY TD W-1020 0.09 140.00 12.60
 ARR03 WARR MANUFACTURER WARRANTY TD W-1020 0.00 140.00 0.00
 ARR03 WARR MANUFACTURER WARRANTY TD W-1020 0.01 140.00 1.40
 ARR04 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 140.00 14.00
 ARR05 Z992 MISC LABOUR CODE (WARR HOD W-1020 0.10 140.00 14.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 ARR01 SSE SHOP SUPPLIES - EXTERNAL W-1020 1.00 0.00 0.00
 ARR03 FRT FREIGHT W-1020 1.00 34.00 34.00
 ARR03 FRT FREIGHT W-1020 1.00 143.63 143.63

 BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1020	8.23	141.40	0.00	177.63	0.00	327.26
	Totals	8.23	141.40	0.00	177.63	0.00	327.26

&k2S
 &k0S