

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66173
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10668 - 2022 RETRO 179 59CCC201XNL004876
VIN: 59CCC201XNL004876 HIN: SER#: 59CCC201XNL004876
Mileage: 0 Work Order Comp: 25 JAN 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 27 DEC 21 Inv #: 372364

WO # Job # Description JOB INFORMATION

66173 2 SHOWER PAN NOT DRAINING
shower drain line set 1 3/4 in too high and 1 inch out of
position with no trap, will have to replumb drain to get too work
pull shower pan out and found drain set 1 3/4 inches high, and no
water less trap was installed at he factory,
66173 4 INSTALL WATERLESS TRAP THAT WAS NOT INSTALLED FROM THE FACTORY
REMOVE SHOWER PAN, PULL FREASH WATER LINES AWAY FROM DRAIN LINES,
CUT OUT DRAIN LINE AND CUT TOO FIT NEW DRAIN LINE TO FIT, DRY FIT
TOGETHER, REMOVE DRY FIT AND GLUE IN LINES, WITH A WATER LESS
TRAP, INSTALL SHOWER BASE, WATER TEST, SEAL WITH SILACONE AROUND
BASE AND WALLS,
66173 9 THE TOP LINE INTO THE WATER HEATER IS LEAKING WHEN WATER HEATER
IS ON
plastic fitting craked
plastic fitting craked and came apart, had to heat alen wrench
and stick in to melt platic fitting to unscrew, install metal
fitting and line
66173 10 THE BOTTOM LINE OF THE WATER HEATER IS LEAKING WHEN WATER HEATER
IS ON
plastic fitting craked
plastic fitting craked and came apart, had to heat alen wrench
and stick in to melt platic fitting to unscrew, install metal
fitting and line, test

Claim : 66173

 WO # Job # Description JOB INFORMATION

66173	1	DINNET SEAT THE BOARD ARE NOT CUT RIGHT AND NOT FITTING boards not cut right mark and cut to fit
66173	3	DINNET BASES NOT SET RIGHT bases not set right, off by 1 1/2 in remove table and rest bases on table top to mach floor bases
66173	5	WATER LEAK IN THE BATH ROOM SINK HOT SIDE bad crimp on band leaking water, cut crimp band off and put on new band test for leak
66173	6	WATER LEAK IN THE BATH ROOM SINK COLD SIDE leaking at crimp band, bad crimp test, for leak cut band and install new crimp band, test for leak
66173	7	WATER LEAK IN THE BATH ROOM SINK AT THE DRAIN DRAIN LINE NOT POSITIONED RIGHT TO GET P TRAP TOO LINE UP REPOITION DRAIN LINE AS CUTTING AND FIXING SHOWER SO P TRAP LINES UP
66173	8	FURANCE VENTS DO NOT LINE UP holes in wall drilled too high and too close together pull furnace, cut board to rais furnace so top vent lines up with hole on wall, cut bottom hole down by 34 of in to line up bottom hole with air in tube remount furnace and vent, cap seal vent, test and run drop test for leaks
66173	11	NO 12V POWER INSIDE ON BATTERY BUT THE UNIT HAS VOLTAGE WHEN PLUGGED INTO SHORE POWER. LOOSE WIRE CONNETION AS I PULL CONVERTER FOM CABNET LIGHTS STAT FLASHING ON AND OFF, FIND LOOSE WIRE CONETION IN WIREING BEHIND CONVTER REPAIR CONEION INSTALL CONVERTER,

 Part No Job# Description PARTS Qty Price Total

55-5222	2	94175 PW 2" TUB ST		1.00	10.94	10.94
121970	2	Fitting - Abs - Ad		1.00	1.66	1.66
3673	2	1.5" FERNCO COUPLE		1.00	4.93	4.93
11-0071	2	D50-2876 90 DEG EL		1.00	1.66	1.66
11-1054	2	TEE (T-4) 1 1/2"		1.00	1.81	1.81
BRV47996	2	SILICONE II - WHIT		1.00	8.04	8.04
72-9319	4	WATERLESS TRAP		1.00	41.99	41.99

Claim : 66173

```

*****
Part No      Job#  Description          PARTS          Qty      Price      Total
*****
72-0818      9    1/2" MPT TO 1/2" P          1.00      2.40      2.40
72-0818     10    1/2" MPT TO 1/2" P          1.00      2.40      2.40

```

```

*****
Lab Code Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      2.00     150.00     300.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.50     150.00     75.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      4    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      9    MISC LABOUR CODE (EXTERNAL)      0.30     150.00     45.00
Z990     10    MISC LABOUR CODE (EXTERNAL)      0.30     150.00     45.00
Z990      1    MISC LABOUR CODE (EXTERNAL)      0.20     150.00     30.00
Z990      3    MISC LABOUR CODE (EXTERNAL)      0.30     150.00     45.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.20     150.00     30.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.20     150.00     30.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.20     150.00     30.00
Z990      8    MISC LABOUR CODE (EXTERNAL)      1.00     150.00    150.00
Z990     11    MISC LABOUR CODE (EXTERNAL)      0.50     150.00     75.00

```

```

Parts Total:      75.83
Labour Total:     855.00
Sublet Total:      0.00
Extras Total:      0.00

```

>>>> Claim Total: 930.83

Customer Signature: _____

Date: _____