

WORK ORDER # 66173

```
Completed : 25 JAN 22      Customer : 49672 - RIVERSIDE RV - 260-499-4578
Licence # :                Invoice # :
Stock No : 10668          Description : 2022 TT RIVERSIDE RV RETRO 179
Tag :                      Date In : 27 DEC 21      Mileage : 0
Author : BH                Promised :
Location : 0130 CHECK PREAUTH Date Sched :
Serial# : 59CCC201XNL004876 Chassis# : 59CCC201XNL004876
Warr. Date :              Cust PO# :
Print Date : 25 JAN 22
```

Job #	Description	JOB INFORMATION	Type	Bill To	
BUNK	PRE DELIVERY INSPECTION NEW BUNKHOUSE		I	PDI	PRE-D
1	COMPLAINT: DINNET SEAT THE BOARD ARE NOT CUT RIGHT AND NOT FITTING		W	49672	RIVER
	CAUSE: boards not cut right				
	CORRECTION: mark and cut to fit				
2	COMPLAINT: SHOWER PAN NOT DRAINING		W	49672	RIVER
	CAUSE: shower drain line set 1 3/4 in too high and 1 inch out of position with no trap, will have to replumb drain to get too work				
	CORRECTION: pull shower pan out and found drain set 1 3/4 inches high, and no water less trap was installed at he factory,				
3	COMPLAINT: DINNET BASES NOT SET RIGHT		W	49672	RIVER
	CAUSE: bases not set right, off by 1 1/2 in				
	CORRECTION: remove table and rest bases on table top to mach floor bases				
4	COMPLAINT: INSTALL WATERLESS TRAP THAT WAS NOT INSTALLED FROM THE FACTORY		W	49672	RIVER
	CORRECTION: REMOVE SHOWER PAN, PULL FREASH WATER LINES AWAY FROM DRAIN LINES, CUT OUT DRAIN LINE AND CUT TOO FIT NEW DRAIN LINE TO FIT, DRY FIT TOGETHER, REMOVE DRY FIT AND GLUE IN LINES, WITH A WATER LESS TRAP, INSTALL SHOWER BASE, WATER TEST, SEAL WITH SILACONE AROUND BASE AND WALLS,				
5	COMPLAINT: WATER LEAK IN THE BATH ROOM SINK HOT SIDE		W	49672	RIVER
	CAUSE: bad crimp on band leaking water,				
	CORRECTION: cut crimp band off and put on new band test for leak				
6	COMPLAINT: WATER LEAK IN THE BATH ROOM SINK COLD SIDE		W	49672	RIVER

Work Order : 66173

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
      CAUSE:      leaking at crimp band, bad crimp
      CORRECTION: test, for leak cut band and install new
                    crimp band, test for leak
7      COMPLAINT: WATER LEAK IN THE BATH ROOM SINK AT THE   W      49672  RIVER
                    DRAIN
      CAUSE:      DRAIN LINE NOT POSITIONED RIGHT TO GET P
                    TRAP TOO LINE UP
      CORRECTION: REPOSITION DRAIN LINE AS CUTTING AND
                    FIXING SHOWER SO P TRAP LINES UP
8      COMPLAINT: FURANCE VENTS DO NOT LINE UP              W      49672  RIVER
      CAUSE:      holes in wall drilled too high and too
                    close together
      CORRECTION: pull furnace, cut board to rais furnace
                    so top vent lines up with hole on wall,
                    cut bottom hole down by 34 of in to line
                    up bottom hole with air in tube remount
                    furnace and vent, cap seal vent, test
                    and run drop test for leaks
9      COMPLAINT: THE TOP LINE INTO THE WATER HEATER IS      W      49672  RIVER
                    LEAKING WHEN WATER HEATER IS ON
      CAUSE:      plastic fitting craked
      CORRECTION: plastic fitting craked and came apart,
                    had to heat alen wrench and stick in to
                    melt platc fitting to unscrew, install
                    metal fitting and line
10     COMPLAINT: THE BOTTOM LINE OF THE WATER HEATER IS      W      49672  RIVER
                    LEAKING WHEN WATER HEATER IS ON
      CAUSE:      plastic fitting craked
      CORRECTION: plastic fitting craked and came apart,
                    had to heat alen wrench and stick in to
                    melt platc fitting to unscrew, install
                    metal fitting and line, test
11     COMPLAINT: NO 12V POWER INSIDE ON BATTERY BUT THE      W      49672  RIVER
                    UNIT HAS VOLTAGE WHEN PLUGGED INTO SHORE
                    POWER.
      CAUSE:      LOOSE WIRE CONNETION
      CORRECTION: AS I PULL CONVERTER FOM CABNET LIGHTS
                    STAT FLASHING ON AND OFF, FIND LOOSE
                    WIRE CONETION IN WIREING BEHIND CONVTER
                    REPAIR CONEION INSTALL CONVERTER,

```

```

*****
Job # Part No Description                PARTS                Bill to Qty Price Total
*****
BUNKH 13034 55362 STD BATTERY                I-PDI 1 13.99 13.99
BUNKH 24181 -50 RV ANTI-FREEZE                I-PDI 2 4.99 9.98
2 5547 94175 PW 2" TUB ST                W-49672 1 10.94 10.94
2 121970 Fitting - Abs - Ad                W-49672 1 1.66 1.66
2 3673 1.5" FERNCO COUPLE                W-49672 1 4.93 4.93

```

Continued on page 3

Work Order : 66173

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
2 11-0071 D50-2876 90 DEG EL W-49672 1 1.66 1.66
2 89-8095 TEE (T-4) 1 1/2" W-49672 1 1.81 1.81
2 BRV47996 SILICONE II - WHIT W-49672 1 8.04 8.04
4 72-9319 WATERLESS TRAP W-49672 1 41.99 41.99
9 72-0818 1/2" MPT TO 1/2" P W-49672 1 2.40 2.40
10 72-0818 1/2" MPT TO 1/2" P W-49672 1 2.40 2.40
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.00 150.00 0.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 3.70 150.00 555.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.30 150.00 45.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.00 150.00 0.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.00 150.00 0.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.00 150.00 0.00
HOUSE Z990 MISC LABOUR CODE (EXTE JP I-PDI 0.00 150.00 0.00
1 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.20 150.00 30.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 2.00 150.00 300.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
2 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
3 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.30 150.00 45.00
4 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
4 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.50 150.00 75.00
4 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
4 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
5 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.20 150.00 30.00
5 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.00 150.00 0.00
6 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.20 150.00 30.00
7 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.20 150.00 30.00
8 Z990 MISC LABOUR CODE (EXTE JP W-49672 1.00 150.00 150.00
9 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.30 150.00 45.00
10 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.30 150.00 45.00
11 Z990 MISC LABOUR CODE (EXTE JP W-49672 0.50 150.00 75.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
HOUSE SS SHOP SUPPLIES I-PDI 1.00 0.00 0.00
HOUSE LP20 20 LB. LP CYLINDER I-PDI 2.00 14.00 28.00
*****
```

CUSTOMER COMMENTS

BH SENT IN PREAUTH
WATERLESS TRAP ARRIVED IN BACKROOM 1-17-22...CAM

Continued on page 4

Work Order : 66173

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I      PDI          23.97      600.00      0.00      28.00      0.00      651.97
W      49672        75.83      855.00      0.00      0.00      0.00      930.83

      Totals        99.80      1455.00      0.00      28.00      0.00      1,582.80

```