

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13528

Date In:	18 MAY 26	Author:	KOTT
Promised Date:	27 MAY 26	Stock No:	11107
:	:	Year:	2024
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA TT
:	: CHICAGO, IL	Model:	25BHS
Postal/Zip:	60673-1218	Miles/Hrs:	:
Phone#(res):	219-534-3167	Exterior Color:	:
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:	:	License#:	:
Email:	NONE	Tag#:	:
Purchased Date:	24 MAY 25	:	:
Delivery Date:	05 JUN 25	:	:
InService Date:	:	:	:
Serial#:	5ZT2PUPB6R4020714	:	:

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To \*\*\*\*\*  
1 COMPLAINT: CUSTOMER STATES THAT THERE IS A VERY W 1021 FORES  
WEIRD NOISE COMING FROM THE TIRES WHEN  
THEY ARE MOVING THE UNIT- CUSTOMER  
TALKED TO DUSTIN AND DUSTIN RECOMMENDED  
BRINGING IN THE UNIT TO BE LOOKED AT- IT  
SOUNDS LIKE THERE IS SOMETHING  
RATTLING/MOVING AROUND BY THE BRAKE  
PADS- NEEDS TO BE DIAGNOSED- ODS REAR  
TIRE IS THE ONE NOTICED  
CAUSE: The hub cap fell off. We have had  
multiple issues with this style hub cap  
and all four need to be replaced. I can  
see sand in the grease so I took the hub  
apart, took it to the parts cleaner and  
completely cleaned it out. I re packed  
the bearings and put the hub back  
together. We only have two replacement  
hub caps so I replaced both on the ODS.  
Dave is ordering more so we can replace  
the DS when they come in.  
CORRECTION: ... REQUEST: 3.0 HR  
2 COMPLAINT: THERE IS A DRIP COMING THROUGH ON TYOP W 1021 FORES  
OF THE SLIDE OUT INSTEAD OF THE GUTTER.  
LOOKS LIKE TWO PIECES MEET THERE AND  
NEED TO BE SEALED OR SOMETHING. DRIP  
COMES OUT RIGHT ON TOP OF THE SLIDE  
TOWARD THE MIDDLE.  
CAUSE: The sealant failed at the gutter seam. I

Continued on page 2

Work Order : 13528

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        cleaned the glob of silicone and dirt
        out of the track, pulled about a foot of
        the screw cover molding out and sealed
        the entire seam.
CORRECTION: Done.  REQUEST: .5

```

```

*****
Job # Part No      Description           PARTS      Bill to   Qty   Price   Total
*****
1      711217012464 WHEEL SEAL                W-1021     1     1.60    1.60
1      82208632      AXLE PART - 2D-2: GREASE W-1021     1     2.77    2.77
1      82207603      AXLE PART - 2C-3: DUST C W-1021     1     2.51    2.51

```

```

*****
Job#  Lab Code  Description           LABOUR    Mech Bill to   Hrs   Rate   Total
*****
  1  Z990      MISC LABOUR CODE (EXTE JGK W-1021     0.00  140.00    0.00
  2  Z990      MISC LABOUR CODE (EXTE JGK W-1021     1.00  140.00   140.00
  1  Z990      MISC LABOUR CODE (EXTE JGK W-1021     1.00  140.00   140.00

```

```

*****
Job #  Excode   Description           EXTRAS      bill to   Qty   Price   Total
*****
  1  SSE        SHOP SUPPLIES - EXTERNAL W-1021     1.00    0.00    0.00

```

```

*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021      6.88     280.00     0.00     0.00     0.00    286.88
      Totals    6.88     280.00     0.00     0.00     0.00    286.88

```

&k2S  
&k0S