

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13528

Date In: 18 MAY 26 Author: KOTT  
Promised Date: 25 DEC 26 Stock No: 11107  
: Year: 2024  
Customer Name: 17725 - STEINHAUER, AN Manufacturer: FOREST RIVER  
Address: 3833 COUNTY ROAD A Brand: PUMA TT  
: ROSHOLT, WI Model: 25BHS  
Postal/Zip: 54473 Miles/Hrs:  
Phone#(res): 715-321-4281 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: NONE Tag#: DB: 5/19  
Purchased Date: 24 MAY 25 :  
Delivery Date: 05 JUN 25 :  
InService Date: :  
Serial#: 5ZT2PUPB6R4020714 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
1 COMPLAINT: CUSTOMER STATES THAT THERE IS A VERY W 1021 FORES  
WEIRD NOISE COMING FROM THE TIRES WHEN  
THEY ARE MOVING THE UNIT- CUSTOMER  
TALKED TO DUSTIN AND DUSTIN RECOMMENDED  
BRINGING IN THE UNIT TO BE LOOKED AT- IT  
SOUNDS LIKE THERE IS SOMETHING  
RATTLING/MOVING AROUND BY THE BRAKE  
PADS- NEEDS TO BE DIAGNOSED- ODS REAR  
TIRE IS THE ONE NOTICED  
CAUSE: The hub cap fell off. We have had  
multiple issues with this style hub cap  
and all four need to be replaced. I can  
see sand in the grease so I took the hub  
apart, took it to the parts cleaner and  
completely cleaned it out. I re packed  
the bearings and put the hub back  
together. We only have two replacement  
hub caps so I replaced both on the ODS.  
Dave is ordering more so we can replace  
the DS when they come in. I pulled both  
the ds tires off, replaced the caps, put  
the tires back on and torqued them to  
spec.  
CORRECTION: Done.  
2 COMPLAINT: THERE IS A DRIP COMING THROUGH ON TYOP W 1021 FORES  
OF THE SLIDE OUT INSTEAD OF THE GUTTER.  
LOOKS LIKE TWO PIECES MEET THERE AND  
NEED TO BE SEALED OR SOMETHING. DRIP

Continued on page 2

Work Order : 13528

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                COMES OUT RIGHT ON TOP OF THE SLIDE
                TOWARD THE MIDDLE.
CAUSE:   The sealant failed at the gutter seam. I
                cleaned the glob of silicone and dirt
                out of the track, pulled about a foot of
                the screw cover molding out and sealed
                the entire seam.
CORRECTION: Done.  REQUEST: .5
    
```

```

*****
Job # Part No      Description           PARTS   Bill to   Qty   Price   Total
*****
1      711217012464 WHEEL SEAL           W-1021   1     1.60    1.60
1      82208632        AXLE PART - 2D-2: GREASE W-1021   4     2.77   11.08
1      82207603        AXLE PART - 2C-3: DUST C W-1021   1     2.51    2.51
1      137847          RUBBERPLUGFORDUSTCAP W-1021   2     0.94    1.88
    
```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 Z990 MISC LABOUR CODE (EXTE JGK W-1021 0.00 140.00 0.00
1 Z990 MISC LABOUR CODE (EXTE JGK W-1021 1.00 140.00 140.00
1 WARR MANUFACTURER WARRANTY JGK W-1021 0.50 140.00 70.00
2 Z990 MISC LABOUR CODE (EXTE JGK W-1021 1.00 140.00 140.00
    
```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
1 SSE SHOP SUPPLIES - EXTERNAL W-1021 1.00 0.00 0.00
1 FRT FREIGHT FOR JOB 1 W-1021 1.00 20.17 20.17
    
```

```

*****
                BILLINGS SUMMARY
Type Bill Id      Parts   Labour   Sublet   Extras   Tax   Total
*****
W 1021            17.07   350.00   0.00    20.17   0.00  387.24
                Totals    17.07   350.00   0.00    20.17   0.00  387.24
    
```

&k2S  
&k0S