

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66178

Completed : 18 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10826 Description : 2022 TT FOREST RIVER CHEROKEE 274BR
Tag : Date In : 27 DEC 21 Mileage : 0
Author : BH Promised :
Location : 0115 CHECK WORK Date Sched :
Serial# : 4X4TCKC27NX155487 Chassis# : 4X4TCKC27NX155487
Warr. Date : Cust PO# :
Print Date : 18 JAN 22

Job # Description JOB INFORMATION Type Bill To

PDIN Transferred to BAS*66235 on 04 JAN 22 Estimate I PDI PRE-D
 amount was 0.00 PDI - NEW TRAVEL TRAILER
1 COMPLAINT: MAIN ENTRANCE DOOR IS BOWED W 10024 FORES
 CAUSE: DOOR IS BOWED
 CORRECTION: TOOK A PIECE OF WOOD AND TAPED IT TO THE
 TOP AND BOTTOM OF THE DOOR WHERE IT
 MAKES CONTACT WITH THE FRAME AND PUSHED
 THE CENTER OF THE DOOR TO HELP
 STRAIGHTEN OUT.
2 COMPLAINT: MAIN ENTRANCE DOOR SCREEN IS HITTING W 10024 FORES
 DOOR LATCH
 CAUSE: screen door hitting latch
 CORRECTION: moved latch over with block of wood and
 a hammer.
3 COMPLAINT: REAR ENTRANCE DOOR SCREEN HITTING LATCH. W 10024 FORES
 CAUSE: latch hitting screen door
 CORRECTION: moved door latch with a block of wood
 and a hammer
4 COMPLAINT: COMPARTMENT DOOR HOLDBACK NOT W 10024 FORES
 INSTALLED...NOTED AT CHECK-IN
 CAUSE: door latch not installed
 CORRECTION: installed door latch
5 COMPLAINT: DRIVER SIDE REAR COMP DOOR FRAME BENT. W 10024 FORES
 NOTED ON DEL SHEET
 CAUSE: SCREW ON RIGHT SIDE OF WHERE THE FRAME
 ENDS WAS IN TOO FAR. CAUSING A GAP.
 CORRECTION: ADDED ANOTHER SCREW TO THE LEFT SIDE AND
 APPLIED SILICONE TO THE GAP IN THE
 MIDDLE.
6 COMPLAINT: OUTSIDE STOVE WILL NOT PULL OUT W 10024 FORES
 CAUSE: SCREW THAT HELD THE ICE MAKER IN PLACE
 WAS HITTING THE BURNER
 CORRECTION: MOVED SCREW OVER TO AVOID CONTACT WITH
 THE BURNER

Continued on page 2

Work Order : 66178

```

*****
Job # Part No Description          PARTS          Bill to  Qty    Price    Total
*****
PDINT 13034    55362 STD BATTERY BOX          I-PDI      0     10.95     0.00
4      E210     E210 2-pk BLK ROUN          W-10024    1      6.54      6.54

```

```

*****
Job#  Lab Code Description          LABOUR    Mech Bill to  Hrs    Rate    Total
*****
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      0.00   130.00     0.00
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      0.00   130.00     0.00
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      0.00   130.00     0.00
  1 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.30   130.00    39.00
  2 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.10   130.00    13.00
  3 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.10   130.00    13.00
  4 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.20   130.00    26.00
  5 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.44   130.00    57.20
  5 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.06   130.00     7.80
  6 Z990     MISC LABOUR CODE (EXTE ZMS  W-10024    0.20   130.00    26.00

```

```

*****
Job #  Excode Description          EXTRAS          bill to  Qty    Price    Total
*****
DINTT  SS      SHOP SUPPLIES          I-PDI      0.00   35.00     0.00
DINTT  LPGI     LP - UNIT SALES          I-PDI      0.00     0.00     0.00

```

```

*****
                          CUSTOMER COMMENTS
*****
BH SENT IN PREAUTH

```

```

*****
                          BILLINGS SUMMARY
Type Bill Id          Parts    Labour    Sublet    Extras    Tax    Total
*****
W      10024          6.54    182.00     0.00     0.00     0.00    188.54
      Totals          6.54    182.00     0.00     0.00     0.00    188.54

```