

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66180

Completed : 07 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
 Licence # : Invoice # :
 Stock No : 10856 Description : 2022 TT FOREST RIVER CHEROKEE WOLF
 Tag : Date In : 27 DEC 21 Mileage : 0
 Author : BH Promised :
 Location : 0120 CHECK PREAUTH Date Sched :
 Serial# : 5ZT2CKGC1NY021748 Chassis# : 5ZT2CKGC1NY021748
 Warr. Date : Cust PO# :
 Print Date : 07 JAN 22

```

*****
Job #   Description                               JOB INFORMATION                               Type Bill To
*****
BUNK   COMPLAINT:  PRE DELIVERY INSPECTION NEW BUNKHOUSE   I   PDI   PRE-D
      CAUSE:      pdi
      CORRECTION: checked brakes, tire pressure, torqued
                  lug nuts, filled lp. tanks. ran lp leak
                  test, tested water and plumbing,
                  electrical system, all appliances, all
                  lights, drained all tanks, winterized.
                  took pictures of appliances and
                  completed paperwork, moved unit to lot.
1      COMPLAINT:  OUTSIDE FLANGE OF WATER HEATER IS NOT   W   10024  FORES
      CAUSE:      water heater flange needs sealed
      CORRECTION: sealed with silicone as needed.
2      COMPLAINT:  SCREEN DOOR IS CATCHING LATCH           W   10024  FORES
      CAUSE:      screen door is hitting the latch for the
                  main door, the latch for the screen door
                  and the door frame at the top left
                  corner.
      CORRECTION: pushed both latches in with a small
                  block of wood and a hammer. pushed in
                  the door frame where it was hitting the
                  door with block of wood and hammer. door
                  is clearing latches and frame.
3      COMPLAINT:  LEATHER PIECE ABOVE DOOR IS BOWED OUT   W   10024  FORES
      CAUSE:      need to straighten the piece out.
      CORRECTION: removed screw covers. removed piece of
                  trim. put piece on work bench and pushed
                  the opposite way of the bend. took screws
                  and re installed piece. installed screw
                  covers with hammer.
4      COMPLAINT:  OUTSIDE KITCHEN DOOR WONT OPEN         W   10024  FORES
      CAUSE:      couldnt get lock to open. tried to
                  lubricate mechanism but couldnt get it
                  to move at all.
  
```

Continued on page 2

Work Order : 66180

```
*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: drilled out center of lock until the
            inside of the lock broke and i could
            move the latch, replaced with a new
            lock.
5      COMPLAINT: TOP OF MAIN ENTRY DOOR NEEDS SILICONE      W      10024  FORES
      CAUSE:      silicone missing above door
      CORRECTION: applied silicone as needed.
6      COMPLAINT: REAR WALL NEEDS SILICONE                    W      10024  FORES
      CAUSE:      rear wall missing silicone
      CORRECTION: applied silicone as needed
7      COMPLAINT: STAIN ON BACK OF DINNETTE "TRIM"            W      10024  FORES
      CAUSE:      stain on trim.
      CORRECTION: cleaned with mineral spirits
8      COMPLAINT: DOOR HOLDER NOT INSTALLED ON FRONT          W      10024  FORES
            COMPARTMENT
      CAUSE:      door holder needs to be installed.
      CORRECTION: installed door holder on front door side
            compartment
9      FRIDGE IS NOT GETTING COLD                              W      10024  FORES
*****
```

```
*****
Job # Part No Description          PARTS          Bill to  Qty   Price   Total
*****
BUNKH 13034  55362 STD BATTERY BOX          I-PDI      0    13.99    0.00
4      L428    L428 1-1/8" KEYED              W-10024    1     4.24    4.24
8      E210    E210 2-pk BLK ROUN              W-10024    1     6.54    6.54
*****
```

```
*****
Job# Lab Code Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
HOUSE Z990  MISC LABOUR CODE (EXTE ZMS I-PDI      0.00  130.00    0.00
HOUSE Z990  MISC LABOUR CODE (EXTE ZMS I-PDI      1.51  130.00  196.30
HOUSE Z990  MISC LABOUR CODE (EXTE ZMS I-PDI      1.59  130.00  206.70
HOUSE Z990  MISC LABOUR CODE (EXTE ZMS I-PDI      0.90  130.00  117.00
  1 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.00  130.00    0.00
  2 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.20  130.00   26.00
  3 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.20  130.00   26.00
  4 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.10  130.00   13.00
  5 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.20  130.00   26.00
  6 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.30  130.00   39.00
  7 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.10  130.00   13.00
  8 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.10  130.00   13.00
  9 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.00  150.00    0.00
  9 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.00  150.00    0.00
  9 Z990  MISC LABOUR CODE (EXTE ZMS W-10024    0.00  150.00    0.00
*****
```

Work Order : 66180

```
*****
Job #  Excode   Description  EXTRAS      bill to      Qty      Price      Total
*****
HOUSE  LPG       LP GAS           I-PDI        4.00       3.99       15.96
HOUSE  SS        SHOP SUPPLIES   I-PDI        1.00       35.00       35.00
*****
```

CUSTOMER COMMENTS

```
*****
BH SENT IN PREAUTH WAITING TO HEAR BACK 1-4
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts   Labour   Sublet   Extras   Tax      Total
*****
I    PDI           0.00    520.00   0.00    50.96    0.00    570.96
W    10024         10.78   156.00   0.00     0.00    0.00    166.78

Totals           10.78   676.00   0.00    50.96    0.00    737.74
*****
```