



# RECREATIONAL VEHICLES

Claim CLAIM5925 (KZ0042867)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre- auth Dealer	Repairing dealer name	Labor rate	Changed		Date of Purchase
								warranty rate	Type	
CLAIM5925 (KZ0042867)	27267	6/5/2026	1/1/0001	4EZFS2925R5100646	CUST-002602	TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Standard	6/7/2024

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Base		Status
						Sublet Qty	Hours	
	4465_01_B	R/R 30 Amp Inlets (Furrion Brand) - Damaged - Replace <b>Complaint</b> Customer has no 12 volt in unit <b>Cause</b> 30 amp breaker has internally failed <b>Correction</b> replace 30 amp breaker	0.5	0.5	87.5	0	1 0.3	Approved

<b>Submitted parts &amp; subLet</b>	0.00	<b>Approved parts &amp; subLet</b>	0.00
<b>Submitted labor &amp; subLet</b>	87.50	<b>Approved labor &amp; subLet</b>	87.50
<b>Submitted freight</b>	0.00	<b>Approved freight</b>	0.00
<b>Total Submitted</b>	<u>87.50</u>	<b>Total approved</b>	<u>87.50</u>