

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66181
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 10872 - 2022 CHEROKEE 304RK 4X4TCKF20NX156198
VIN: 4X4TCKF20NX156198 HIN: SER#: 4X4TCKF20NX156198
Mileage: 0 Work Order Comp: 12 MAR 22
Auth. No: Dealer #:
Warr. Date: Work Order Date: 27 DEC 21 Inv #: 373817

WO # Job # Description JOB INFORMATION

66181 6 ENTRY STEPS HAVE A PAINT DEFECT ON THE RIGHT HAND SIDE
paint on steps is flaking off and steps are starting to rust.
need to replace steps. pics on onedrive

66181 1 CLEAN BLACK SILICONE ON ALL WINDOWS INSIDE AND OUT FROM INSTALL
10 WINDOWS TOTAL
SILICONE ALL OVER THE INSIDE AND OUTSIDE OF ALL THE WINDOWS.
TOOK WINDOW CLEANER, STEEL WOOL AND A SQUEEGY TO ALL WINDOWS
INSIDE AND OUT ON THE CAMPER.

66181 7 FURANCE IS NOT IGNITING
need to pull furnace to inspect. fan was coming on but ignitor
and gas valve were not funtioning.
shut off gas. removed gas line. removed wires going to control
board. removed back panel of furnace. removed mounting screws
that hold furnace. pulled furnace. hooked up to bench tester.
moved sail switch up and down to make sure it wasnt stuck closed.
turn furnace on and furnace is igniting. sail switch was stuck
and not telling the furnace to ask for fuel and ignition.
installed furnace, hooked up gas lines and wires to control
board. installed exhaust. secured to floor. installed rear acess
cover. tested furnace. sealed exhaust

66181 8 BEDROOM DOOR IS HITTING THE DOOR FRAME
door is hitting the frame at the top of the door and where the
latch is sitting.

Claim : 66181

 WO # Job # Description JOB INFORMATION

 removed the "plastic" frame and the latch. removed 2 pieces of
 trim that go around plastic frame. took a hand planer and removed
 some of the 2x4 so i could get the frame away from the door.
 installed plastic frame and latch. had to cut down trim piece
 that goes around plastic frame. "cut trim on the table saw"
 installed trim with stapler. cleaned up mess.

66181 9 LATCH FOR SCREEN DOOR NEEDS SHIMS
 latch is too far away from door.
 took some putty tape and 2 washers and placed them behind the
 latch. secured latch to the door frame.

 Part No Job# Description PARTS Qty Price Total

 F100222187 6 STEP, FOLD UP QUAD 1.00 379.39 379.39

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 1.00 150.00 150.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.25 150.00 37.50
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 6 FREIGHT-STEPS 1.00 200.00 200.00

Parts Total: 379.39
 Labour Total: 277.50
 Sublet Total: 0.00
 Extras Total: 200.00

>>>> Claim Total: 856.89

Customer Signature: _____

Date: _____