

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66181

Completed : 12 MAR 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10872 Description : 2022 TT FOREST RIVER CHEROKEE 304RK
Tag : Date In : 27 DEC 21 Mileage : 0
Author : BH Promised : 26 MAR 22
Location : 0314 SEE IF SAR IS Date Sched :
Serial# : 4X4TCKF20NX156198 Chassis# : 4X4TCKF20NX156198
Warr. Date : Cust PO# :
Print Date : 12 MAR 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: Transferred to BAS*66397 on 27 JAN 22 I PDI PRE-D
Estimate amount was 0.00 PDI - NEW
TRAVEL TRAILER
CAUSE: PDI
CORRECTION: CHECKED BRAKES ,TIRE PRESSURE, LUG
NUTS,AFTER,PLUMBING,ELECTRICAL,APPLIANCE
,LIGHTS, HOLDING TANKS, FILLED LP. RAN
LEAK TEST, DRAINED TANKS, NOTED MODEL
AND SERIAL NUMBERS,
1 COMPLAINT: CLEAN BLACK SILICONE ON ALL WINDOWS W 10024 FORES
INSIDE AND OUT FROM INSTALL 10 WINDOWS
TOTAL
CAUSE: SILICONE ALL OVER THE INSIDE AND OUTSIDE
OF ALL THE WINDOWS.
CORRECTION: TOOK WINDOW CLEANER, STEEL WOOL AND A
SQUEEGY TO ALL WINDOWS INSIDE AND OUT ON
THE CAMPER.
2 COMPLAINT: SILICONE ON OUTDOOR KITCHEN DOOR I SPN SALES
CAUSE: silicone on door
CORRECTION: removed with mineral spirits
3 SILICONE ON AWNING ARM I SPN SALES
4 COMPLAINT: SILICONE ON SLIDE OUT I SPN SALES
CAUSE: silicone on slide out
CORRECTION: removed with mineral spirits
5 COMPLAINT: FLANGE FOR WATER HEATER NEED TO BE I SPN SALES
SEALED
CAUSE: outdoor flange for water heater needs
sealed
CORRECTION: sealed with silicone
6 COMPLAINT: ENTRY STEPS HAVE A PAINT DEFECT ON THE W 10024 FORES
RIGHT HAND SIDE
CAUSE: paint on steps is flaking off and steps
are starting to rust. need to replace
steps. pics on onedrive

Continued on page 2

Work Order : 66181

 Job # Description JOB INFORMATION Type Bill To

7 COMPLAINT: FURANCE IS NOT IGNITING W 10024 FORES
 CAUSE: need to pull furnace to inspect. fan was
 coming on but ignitor and gas valve were
 not funtioning.

CORRECTION: shut off gas. removed gas line. removed
 wires going to control board. removed
 back panel of furnace. removed mounting
 screws that hold furnace. pulled
 furnace. hooked up to bench tester.
 moved sail switch up and down to make
 sure it wasnt stuck closed. turn furnace
 on and furnace is igniting. sail switch
 was stuck and not telling the furnace to
 ask for fuel and ignition. installed
 furnace, hooked up gas lines and wires
 to control board. installed exhaust.
 secured to floor. installed rear acess
 cover. tested furnace. sealed exhaust

8 COMPLAINT: BEDROOM DOOR IS HITTING THE DOOR FRAME W 10024 FORES
 CAUSE: door is hitting the frame at the top of
 the door and where the latch is sitting.

CORRECTION: removed the "plastic" frame and the
 latch. removed 2 pieces of trim that go
 around plastic frame. took a hand planer
 and removed some of the 2x4 so i could
 get the frame away from the door.
 installed plastic frame and latch. had
 to cut down trim piece that goes around
 plastic frame. "cut trim on the table
 saw" installed trim with stapler.
 cleaned up mess.

9 COMPLAINT: LATCH FOR SCREEN DOOR NEEDS SHIMS W 10024 FORES
 CAUSE: latch is too far away from door.

CORRECTION: took some putty tape and 2 washers and
 placed them behind the latch. secured
 latch to the door frame.

 Job # Part No Description PARTS Bill to Qty Price Total

 PDINT 13034 55362 STD BATTERY BOX I-PDI 0 10.95 0.00
 6 F100222187 STEP, FOLD UP QUAD W-10024 1 379.39 379.39

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 DINTT Z991 MISC LABOUR CODE (INTE ZMS I-PDI 0.00 130.00 0.00
 DINTT Z991 MISC LABOUR CODE (INTE ZMS I-PDI 0.00 130.00 0.00
 DINTT Z991 MISC LABOUR CODE (INTE ZMS I-PDI 0.00 130.00 0.00

Continued on page 3

Work Order : 66181

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI 0.00 130.00 0.00
DINTT Z991      MISC LABOUR CODE (INTE ZMS I-PDI 0.00 130.00 0.00
  1 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 1.00 150.00 150.00
  2 Z990      MISC LABOUR CODE (EXTE ZMS I-SPN 0.20 25.00 5.00
  3 Z990      MISC LABOUR CODE (EXTE ZMS I-SPN 0.20 25.00 5.00
  4 Z990      MISC LABOUR CODE (EXTE ZMS I-SPN 0.20 25.00 5.00
  5 Z990      MISC LABOUR CODE (EXTE ZMS I-SPN 0.20 25.00 5.00
  6 Z990      MISC LABOUR CODE (EXTE W-10024 0.00 150.00 0.00
  6 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.00 150.00 0.00
  6 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.30 150.00 45.00
  7 Z990      MISC LABOUR CODE (EXTE SAR W-10024 0.00 150.00 0.00
  7 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.00 150.00 0.00
  7 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.00 150.00 0.00
  8 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.25 150.00 37.50
  8 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.00 150.00 0.00
  9 Z990      MISC LABOUR CODE (EXTE ZMS W-10024 0.20 150.00 30.00
          MISC LABOUR CODE (EXTE ZMS W-10024 0.10 150.00 15.00

```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
DINTT  SS      SHOP SUPPLIES  I-PDI  0.00  35.00  0.00
DINTT  LP20     20 LB. LP CYLINDER  I-PDI  0.00  14.00  0.00
  6 FRT      FREIGHT-STEPS  W-10024 1.00  200.00  200.00

```

CUSTOMER COMMENTS

```

*****
RECEIVED BILLING 3-10-22...CAM
RE-ORDERED STEP ARRIVED (WITHOUT BILLING) 3-2-22 IN
BACKROOM...CAM
PER CHEROKEE...END OF MONTH BEFORE PARTS COME IN TO THEM
(EMAIL)...CAM 2-21-22
DH EMAILED CAM 2/21
STEPS CAME IN WRONG...ORDERED CORRECT, SENT WRONG ONE, EMAILED
WITH PICTURES FOR RESOLVE 1-27-22....CAM
STEPS IN RED TRAILER 1-21-22...CAM
STEPS ORDERED 1-11-22...CAM
GAVE PART SHEET TO MATT1-10
BH GOT APPROVEL
BH SENT IN FOR PREAUTH 01-8

```

BILLINGS SUMMARY

```

*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I   SPN       0.00   20.00   0.00   0.00   0.00   20.00
W   10024     379.39  277.50   0.00  200.00   0.00  856.89

```

Continued on page 4

Work Order : 66181

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
Totals           379.39      297.50        0.00      200.00        0.00      876.89
```