

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2682596
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAVBXTX035655
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT303RKDSLE
DONALD R HARTLEY		DEALER RO #	79961
1782 E PRIVATE RD 485 N		CLAIM START DATE	05/20/2026
Petersburg, IN 47567		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/24/2026	WARRANTY EXPIRATION DATE	04/24/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	10-11-24-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-20 13:49:41 :: CUSTOMER CAN SEE DAYLIGHT IN BOTTOM LEFT CORNER OF THE BEDROOM SLIDE ROOM WHEN ROOM IS OUT Not enough foam to seal slide Installed foam to seal slide			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$39.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$39.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	70-178-01-00-002137	Burner - Oven - Appliances/Range (Suburban)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-20 15:39:51 :: CUSTOMER CAN'T GET THE OVEN TO LIGHT. THE BURNERS WILL LIGHT, BUT THE OVEN WON'T LIGHT. Igniter is not arcing properly to light the pilot Adjusted igniter located and tested. Oven lights properly			
	Model# NAPLD617RW1SS	Dlr Sub Hrs	0.25	Sub Labor Amt \$48.75
	Serial# FA100058G	Appr Hrs	0.25	Appr Labor Amt \$48.75
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	70-469-02-00-004029	Door Latch or Catch - Appliances/Refrigerator (Furrion)/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2026-05-20 15:41:10 :: CUSTOMER ADVISES THAT THE LATCH THAT HOLDS THE REFRIGERATOR CLOSED IN TRAVEL IS NOT HOLDING. CUSTOMER'S SODA CANS FELL OUT IN TRAVEL. Latch hinge loose ATightened latch by squeezing metal together			
	Model# PPV10R5YBRSS	Dlr Sub Hrs	0.10	Sub Labor Amt \$19.50
	Serial# FA572590	Appr Hrs	0.10	Appr Labor Amt \$19.50
	Notes			

Submitted	Labor Amt	\$107.25	Approved	Labor Amt	\$107.25
	Parts & Freight	\$0.00		Parts & Freight	\$0.00

Total

\$107.25

Total

\$107.25

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.