

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	892820
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CKEC5NY021187
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	017 / 017D
Labor rate:	\$130.00	ITEM #	CKTR16BHS-D
OWNER INFORMATION		DEALER RO #	66182
		CLAIM START DATE	01/11/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line#	Operation Code	Operational Description			
1	20-46-19-00-000721	Window - Exterior/Windows/Reseal/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-01-11 10:40:03 :: EXCESS SILICONE AROUND WINDOWS, ON WINDOWS & ON COMPARTMENT DOOR need to remove excess silicone applied mineral spirits and removed silicone from windows, around windows and compartment doors 5 WINDOWS AND COMPARTMENT DOORS				
	Model #	Dlr Sub Hrs	1.00	Sub Labor Amt	\$130.00
	Serial #	Appr Hrs	0.50	Appr Labor Amt	\$65.00

Notes

Labor

Line#	Operation Code	Operational Description			
2	70-167-19-00-001999	Water Heater - Appliances/Water Heater (Suburban)/Reseal/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-01-11 10:42:22 :: WATER HEATER FLANGE NEEDS SEALED flange on water heater was not sealed with silicone. applied silicone to flange				
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$39.00
	Serial #	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

plant doesnt seal due to having backer

Labor

Line#	Operation Code	Operational Description			
3	20-69-02-00-000705	Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2022-01-11 10:43:12 :: COMPARTMENT DOOR FOR THE OUTSIDE FRIDGE IS HITTING DOOR FRAME door is hitting frame took a block of wood with a hammer and moved thr frame "up" away from the door as much as i could. then took block of wood and moved the door "down" away from the frame.				
	Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$52.00
	Serial #	Appr Hrs	0.20	Appr Labor Amt	\$26.00

Notes

Submitted	Labor Amt	\$221.00	Approved	Labor Amt	\$91.00
-----------	-----------	----------	----------	-----------	---------

Parts & Freight	\$0.00
Total	\$221.00

Parts & Freight	\$0.00
Total	\$91.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.