

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD

EVANSVILLE, IN 47725
 USA

Labor rate: \$130.00
 OWNER INFORMATION

CLAIM STATUS Authorized
 CLAIM 886786
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2CAGC4NK003399
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 203 / 203
 ITEM # BCAT184BHS
 DEALER RO # 66183
 CLAIM START DATE 01/05/2022
 CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
 Line# 1 **Operation Code** **Operational Description**
 30-101-02-00-001076 Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-05 09:22:34 :: THE BATHROOM DOOR NEEDS TO BE ADJUSTED READJUSTED THE BATHROOM DOOR
 Model # **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$39.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$26.00

Notes
 excessive time requested per repair description.

Labor
 Line# 2 **Operation Code** **Operational Description**
 30-102-12-00-001096 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-05 09:23:56 :: THERE ARE STAPLES HANGING OUT ABOVE THE MASTER BED. USED PUTTY FOR TOUCH UP
 Model # **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$26.00
 Serial # **Appr Hrs** 0.10 **Appr Labor Amt** \$13.00

Notes
 excessive time requested per repair description.

Labor
 Line# 3 **Operation Code** **Operational Description**
 40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-05 09:25:14 :: THERE IS A WIRE HANGING OUT BELOW THE SLIDEOUT TIED THE WIRE UP OUT OF SIGHT
 Model # **Dlr Sub Hrs** 0.90 **Sub Labor Amt** \$117.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$26.00

Notes
 excessive time requested per repair description.

Labor
 Line# 4 **Operation Code** **Operational Description**
 20-69-01-00-000703 Hold Back Latch, Catch, or Magnet - Exterior/Compartment Doors/ Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-05 09:26:23 :: COMPARTMENT DOOR MAGNET COMING OUT OF THE WALL SCREWED MAGNET IN NEW SPOT

Model #	Dir Sub Hrs	0.20	Sub Labor Amt	\$26.00
Serial #	Appr Hrs	0.10	Appr Labor Amt	\$13.00

Notes

excessive time requested per repair description.

Submitted	Labor Amt	\$208.00	Approved	Labor Amt	\$78.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$208.00		Total	\$78.00

DEALER _____ **DATE**

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE**

SIGNATURE

All repairs described have been inspected and are satisfactory.