

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2668548
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKD2XTK099988
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$195.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT28RRTS-94
		DEALER RO #	79784
		CLAIM START DATE	05/07/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-100-02-00-003062 Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-07 15:58:59 :: ALL OF THE CABINET DOORS RUB
 THERE ARE 3 SETS Doors installed too close from factory Spaced doors out

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt \$48.75
Serial#	Appr Hrs	0.25	Appr Labor Amt \$48.75

Notes
 Please adjust cabinet doors. Thank you

Labor

Line# 2 **Operation Code** **Operational Description**
 30-101-01-00-001078 Sliding, Pocket Door - Interior/Interior Doors/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-07 15:59:47 :: BATHROOM SLIDING DOOR RUBS AND
 IS SEVERELY SCRATCHED Door installed too close to the wall and scratched from factory Adjusted rail but no
 wood putty will mask scratches. Remove and replace door

Model#	Dlr Sub Hrs	0.80	Sub Labor Amt \$156.00
Serial#	Appr Hrs	0.80	Appr Labor Amt \$156.00

Notes
 please replace sliding pocket door. thank you

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-01-00-001042 Mirror or Glass From Cabinet Door Frame - Interior/Cabinetry/Replace/No Tread
 Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2026-05-07 16:01:07 :: THE BATHROOM MIRROR IS SCRATCH
 AND THE WOOD AROUND IT IS ASWELL Damaged from factory Remove and replace mirror

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$78.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$78.00

Notes
 Please attach the following before sending claim to processing: Identifying marks, tags, labels,
 stamps - or location - or model/serial numbers
 Thank you
 Please replace mirror

Labor

Line# 4 **Operation Code** **Operational Description**
 20-66-02-00-000678 Screen Door - Exterior/Entry Doors/Adjust/No Tread Code
Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-05-07 16:07:27 :: THE MAIN SCREEN DOOR LATCH NEEDS ADJUSTED Latch on door was grabbing screen door handle Adjusted latch up

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$39.00

Serial# Appr Hrs 0.20 Appr Labor Amt \$39.00

Notes

Labor

Line# 5

Operation Code

70-674-24-00-002001

Operational Description

Water Heater Door - Appliances/Water Heater - Tankless (Furrion)/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-05-07 16:08:10 :: THE WATER HEATER DOOR IS HARD TO CLOSE Door frame not properly Adjusted Adjusted door frame. Door latches properly

Model# na Dlr Sub Hrs 0.20 Sub Labor Amt \$39.00

Serial# na Appr Hrs 0.20 Appr Labor Amt \$39.00

Notes

After review please attach pictures of the water heater door not closing properly. Thank you
PHOTO ADDED
please adjust water heater door thank you

Labor

Line# 6

Operation Code

30-100-24-00-001046

Operational Description

Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2026-05-07 16:08:52 :: THE CABINET DOOR ABOVE THE BED HAS SCRATCHES Door scratched from factory Remove and replace door

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$58.50

Serial# Appr Hrs 0.30 Appr Labor Amt \$58.50

Notes

Submitted

Labor Amt \$419.25
Parts & Freight \$0.00
Total \$419.25

Approved

Labor Amt \$419.25
Parts & Freight \$0.00
Total \$419.25

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.