

Pre-Authorization

Pre-Authorization number PA03015391 Reference no: 66185 Status: Approved Approved by flins Approved date 1/5/2022
 Servicing Name Address VIN Retail sold on Dealer

1194	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDTSGGL25N3104418							
Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction	
1	3201808A	Decorative Wood	0.00	0.20	0.10		1	0.10	Complaint:scratch is below the refer on the cabinet Cause:scratch is below the refer on the cabinet Correction:touched up the scratch check pictures KRV – Labor time approved in accordance with Keystone RV's flat rate manual.	
2	2203114B	Power Roof Vents	0.00	0.10	0.10		1	0.30	Complaint:HANDLE ON VENT IN MASTER BEDROOM NOT INSTALLED Cause:FOUND VENT ON THE FLOOR Correction:reinstalled the turn knob back on the vent in the master bed check pictures	
3	5114306B	Receptacle - 12V	0.00	0.50	0.30		1	0.30	Complaint:USB PORT IN THE TOP BUNK DOES NOT WORK Cause:check the usb plug it didnt charge my led light will inspect the plug check pictures plug is burnt out Correction:put in PO for new usb port plug KRV – Labor time approved in accordance with Keystone RV's flat rate manual. INSTALL NEW USB	
4	6109524B	Holding Tank Flus	0.00	0.10	0.10		1	0.30	Complaint:UNIT HAS SPRAY PORT BUT NO SPRAY PORT HOSE Cause:FAILED TO INSTALL SPRAY PORT Correction:PUT SPRAY PORT IN CAMPER	
5			0.00				1			
Pre-Authorization number PA03015391					0.60					

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company