

Pre-Authorization

Pre-Authorization number PA03019705 Reference no: 66187 Status: Approved Approved by steic Approved date 1/10/2022
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDFM0S20N4701454
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	3201816A	Decorative Wood	0.00	0.30	0.30		1	0.10	Complaint:CEILING TRIM HANGING DOWN ON DINETTE SLIDEOUT Cause:CEILING TRIM HANGING DOWN ON DINETTE SLIDEOUT. Correction:Flat Ceiling trim too long and bowed. Trimmed end of flat trim and reattached to ceiling with brad nails
2	6200924B	Manifold - Iron Pip	0.00	0.75			1	0.30	Complaint:TRAILER DOES NOT HAVE A OUTSIDE LP QUICK CONNECT Cause:TRAILER DOES NOT HAVE A OUTSIDE LP QUICK CONNECT. Correction:Unit does not have quick connect for outside grille. Lp line is there but has plug in end of line. Can not do a LP drop test. Made up fittings and quick connect and installed on end of LP line. Checked all fitting s for leaks. All OK. KRV – Unit built in accordance with current manufacturing specifications.

Pre-Authorization number PA03019705 0.30

For paper claims only use one pre-authorization number per warranty claim for
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
 form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the
 amount authorized on the pre-authorization form and return toKeystone RV Company