

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080  
TRI AM RV CENTER OF EAST TN  
1202 IDELL ROAD (I-81 EXIT 23)  
BULLS GAP, TN 37711  
USA

CLAIM STATUS Authorized  
CLAIM 2705601  
CLAIM ORIGIN WEB  
ORIGINAL CLAIM ID  
VIN 5ZT3CH2B1RA331015  
CHASSIS VIN  
MILEAGE 0  
SITE/WAREHOUSE 110 / 110  
ITEM # CHF367BH  
DEALER RO # 27291  
CLAIM START DATE 06/10/2026  
CLAIM END DATE 01/01/1900

Labor rate: \$175.00

## OWNER INFORMATION

BRAD RICE  
1900 Meadow Springs Ct  
Russellville, TN 37860  
USA

Retail Date of Purchase 08/16/2025

WARRANTY EXPIRATION DATE

08/16/2026

## Claim Line Details

### Labor

Line#	Operation Code	Operational Description
1	70-159-01-11-001898	Dometic Duotherm AC Blower Fan Motor - Appliances/Roof AC (Dometic, Duo-Therm)/Replace/Electrical

### Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2026-06-10 12:13:47 :: Complaint: Water heater throwing E-5 code  
Cause: Tech called LCI tech support and went over the issue. Case #6846252. It was determined blower motor failure was the issue after board was reaplaced. Correction: Replace blower motor on water heater and test

Model# 1	Dlr Sub Hrs 0.50	Sub Labor Amt \$87.50
Serial# 1	Appr Hrs 0.50	Appr Labor Amt \$87.50

### Notes

<b>Submitted</b>	Labor Amt	\$87.50
	Parts & Freight	\$0.00
	Total	\$87.50

<b>Approved</b>	Labor Amt	\$87.50
	Parts & Freight	\$0.00
	Total	\$87.50

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

### SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

### SIGNATURE

All repairs described have been inspected and are satisfactory.