



RECREATIONAL VEHICLES

Claim CLAIM6196 (KZ0043122)

Last Modified By

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty		Date of Purchase
									rate	Type	
CLAIM6196 (KZ0043122)	27288	6/9/2026	1/1/0001	4EZTK1310V5053307	CUST-002602		TRI-AM RV CENTER OF EAST TENNESSEE, INC. 1202 IDELL ROAD BULLS GAP, TN 37711	175.00	175.00	Pre-delivery	1/1/0001

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	3325_07_A	R/R Surround on Tub (ALL SIZES) - Gaps / Voids - Repair/adjust/tighten Complaint Shower wall is stained Cause Noted on DAF Correction Clean and color blend	0.2	0.2	35	0	1	1	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5540_01_A	Repair, General, Putty, Clean, Sand, Etc. - Damaged - Repair/adjust/tighten Complaint Stain on wall at entry door Cause Noted on DAF Correction Clean and color blend area	0.2	0.2	35	0	1	0.1	Approved

Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	5546_03_A	R/R Door(s), Swinging - All - Improperly Installed - Repair/adjust/tighten Complaint Bathroom door is not closing evenly, door sticks out at the top Cause Noted on DAF Correction Remove and reinstall hinge to adjust the door to close correctly	0.4	0.3	52.5	0	1	0.3	Approved

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	140.00	Approved labor & subLet	122.50
Submitted freight	0.00	Approved freight	0.00
Total Submitted	140.00	Total approved	122.50