

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66190

Completed : 31 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
 Licence # : Invoice # :
 Stock No : 11028 Description : 2022 TT COACHMEN CATALINA SUMMIT SE
 Tag : Date In : 27 DEC 21 Mileage : 0
 Author : BH Promised :
 Location : 0130 CHECKWORK Date Sched :
 Serial# : 5ZT2CAGC7NK003803 Chassis# : 5ZT2CAGC7NK003803
 Warr. Date : Cust PO# :
 Print Date : 01 FEB 22

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
BUNK COMPLAINT: PRE DELIVERY INSPECTION NEW BUNKHOUSE I PDI PRE-D
CORRECTION: pdi done.
1 COMPLAINT: T HANDLE IS BROKE ON BLACK TANK VALVE W 10024 FORES
CORRECTION: replaced t handle
2 COMPLAINT: ROOM WONT COME OUT LEFT BOTTOM GEAR IS W 10024 FORES
NOT MOVING
CORRECTION: TOOK RIGHT SIDE TRACK AND MOTOR OUT AND
FOUND BOTTOM TRACK IS BAD AND SHOE IR
BROKEN,waiting on pre oth.
3 COMPLAINT: RIGHT REAR MARKER LIGHT DOES NOT WORK W 10024 FORES
CORRECTION: TOOK SIDE LIGHT OUT AND REAR LIGHT OUT
AND FOUND GROUND WIRE WAS NOT HOOKED
UP,HOOKED UP WIRES AND PUT LIGHTS BACK
IN AND SEALED.
4 COMPLAINT: THE LEFT SIDE TOP SIDE ROOM HAS A HOLE W 10024 FORES
THAT GOES ALL THE WAY THROUGH
CORRECTION: TOOK PICTURES AND MEASUREMENTS,WAITING
ON PRE OTH.
5 COMPLAINT: VENT BROKE ON PLENUM W 10024 FORES
CAUSE: VENT HAD TAPE ON IT CUT THE TAPE AND THE
VENT FELL
CORRECTION: INSTALL NEW VENT
6 HELP INSTALL ROOM I PDI PRE-D
*****
```

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
BUNKH 13034 55362 STD BATTERY I-PDI 1 13.99 13.99
BUNKH 24181 -50 RV ANTI-FREEZE I-PDI 2 4.99 9.98
2 366158 Inverted Dual Rack W-10024 1 305.00 305.00
2 20X48346A SLIDE OUT, BULB "D W-10024 8 0.79 6.32
4 20X71769A SEAL 2 7/8" SINGLE W-10024 9 1.94 17.46
5 F100238138 A/C, GE MECHANICAL W-10024 1 79.70 79.70
*****
```

Continued on page 2

Work Order : 66190

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
HOUSE Z990      MISC LABOUR CODE (EXTE DGH I-PDI 0.73 150.00 109.50
HOUSE Z990      MISC LABOUR CODE (EXTE DGH I-PDI 0.72 150.00 108.00
HOUSE Z990      MISC LABOUR CODE (EXTE DGH I-PDI 0.26 150.00 39.00
HOUSE Z990      MISC LABOUR CODE (EXTE DGH I-PDI 1.05 150.00 157.50
HOUSE Z990      MISC LABOUR CODE (EXTE DGH I-PDI 1.24 150.00 186.00
    1 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.20 150.00 30.00
    2 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.00 150.00 0.00
    2 Z990      MISC LABOUR CODE (EXTE DGH W-10024 1.21 150.00 181.50
    2 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.00 150.00 0.00
    2 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.29 150.00 43.50
    3 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.20 150.00 30.00
    4 Z990      MISC LABOUR CODE (EXTE DGH W-10024 1.95 150.00 292.50
    4 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.05 150.00 7.50
    6 Z990      MISC LABOUR CODE (EXTE BRM I-PDI 0.01 150.00 1.50
    6 Z990      MISC LABOUR CODE (EXTE BRM I-PDI 0.99 150.00 148.50
    5 Z990      MISC LABOUR CODE (EXTE DGH W-10024 0.50 150.00 75.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
HOUSE LPG      LP GAS      I-PDI 4.00 3.99 15.96
HOUSE SS      SHOP SUPPLIES I-PDI 1.00 0.00 0.00
    2 FRT      UPS-ROOM REPAIR KIT W-10024 1.00 8.37 8.37
    5 FRT      UPS-PLENUM W-10024 1.00 20.91 20.91
*****
```

CUSTOMER COMMENTS

```
*****
ROOM REPAIR KIT ARRIVED IN BACKROOM 1-18-22...CAM
CEILING ASSEMBLY IN BACKROOM 1-18-22...CAM
ORDERED SLIDE REPAIR KIT FROM LIPPERT. 1-7-22
WAITING FOR DECKER @ FOREST RIVER TO SEE IF THEY ARE SENDING THE
SLIDE STIFF
BH SENT IN PREAUTH
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I  PDI  23.97  750.00  0.00  15.96  0.00  789.93
W  10024 408.48  660.00  0.00  29.28  0.00  1,097.76
Totals 432.45 1410.00 0.00 45.24 0.00 1,887.69
*****
```