

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 13082B

Date In: 04 MAR 26	Author: MGRAY
Promised Date: 17 APR 26	Stock No: 11412
:	Year: 2026
Customer Name: 1021 - FOREST RIVER	Manufacturer: FOREST RIVER
Address: 21815 NETWORK PLACE	Brand: PUMA DESTINATION
: CHICAGO, IL	Model: 38RLB
Postal/Zip: 60673-1218	Miles/Hrs: 0
Phone#(res): 219-534-3167	Exterior Color:
Phone#(bus): 219-534-3167	Unit Type: TT-TRAVEL TRAILER
Cell Phone:	License#:
Email: NONE	Tag#: DB: 3/4
Purchased Date: 29 OCT 25	:
Delivery Date: 17 APR 26	:
InService Date:	:
Serial#: 4X4TPUP20TP106347	:

```

*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
4      COMPLAINT:  CAULK AROUND BACKSLPASH IN SHOWER WHERE I   SAP   POLIC
      CAUSE:        This is not a warranty issue the bottom
      CORRECTION:  I used air nozzle to blow and clean the
      REQUEST:     .3
WARR   COMPLAINT:  WARRANTY REPAIR 1 - The slide ods rug      W   1021  FORES
      CAUSE:        has stains
      CORRECTION:  Stained from mfg
      REQUEST:     .1
WARR   COMPLAINT:  WARRANTY REPAIR 2 -The DS rug has stains W   1021  FORES
      CAUSE:        Stained floor covering from mfg
      CORRECTION:  Used quick solve to remove the stains
      REQUEST:     .2
WARR   COMPLAINT:  WARRANTY REPAIR 21. The dark wood has      W   1021  FORES
      CAUSE:        light colored something smeared in spots
      CORRECTION:  Doors and slide fascia have something
      REQUEST:     smeared on them
      CORRECTION:  I used thick solution of murpheys oil
      REQUEST:     soap sprayed and scrubbed doors down
  
```

Continued on page 2

Work Order : 13082B

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
well the finish now looks as it should
no longer any discoloration happening
REQUEST: .5
WARR    COMPLAINT:  WARRANTY REPAIR 3 -Bottom of the bath    W    1021    FORES
        CAUSE:      I finished edge
        CORRECTION: Took fine sand paper and sanded off the
                    sharp edge  REQUEST:.1
WARR    COMPLAINT:  WARRANTY REPAIR 4 - all corner trim in    W    1021    FORES
        bunk room needs holes filled with putty
        excessive large holes
        CAUSE:      Large staple holes unfilled
        CORRECTION: Used putty to fill  REQUEST: .7
WARR    COMPLAINT:  WARRANTY REPAIR 5 -Recliner chairs have    W    1021    FORES
        marks on them
        CAUSE:      White marks on recliners
        CORRECTION: Used quick solve to remove the spots
                    REQUEST: .2
WARR    COMPLAINT:  WARRANTY REPAIR 6 - bottom drawer under    W    1021    FORES
        microwave has a chip out of top edge
        CAUSE:      Small chip
        CORRECTION: Used a touch of putty to fill the little
                    chipped area  REQUEST:.1
WARR    COMPLAINT:  WARRANTY REPAIR 20 the dining chairs        W    1021    FORES
        have little dings and chips
        CAUSE:      Chips in wood of chairs . One dining
                    chair has a crack photos of tag is for
                    cracked one  ORDER ONE NEW DINING CHAIR
        CORRECTION: .....  REQUEST: .2
    
```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
4 WARR  MANUFACTURER WARRANTY  HOD  I-SAP  0.50  70.00  35.00
ARR01 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR02 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR21 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR03 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR04 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR05 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR06 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
ARR20 Z992  MISC LABOUR CODE (WARR HOD W-1021  0.50  140.00  70.00
    
```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01  SSE      SHOP SUPPLIES - EXTERNAL  W-1021  1.00  0.00  0.00
    
```

Continued on page 3

Work Order : 13082B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	SAP	0.00	35.00	0.00	0.00	0.00	35.00
W	1021	0.00	560.00	0.00	0.00	0.00	560.00
	Totals	0.00	595.00	0.00	0.00	0.00	595.00

&k2S
&k0S