

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13082B

Date In: 04 MAR 26 Author: DLUCAS  
Promised Date: 31 DEC 26 Stock No: 11412  
: Year: 2026  
Customer Name: 17927 - LASSA, SUSAN Manufacturer: FOREST RIVER  
Address: 9340 S 44TH CT Brand: PUMA DESTINATION  
: FRANKLIN, WI Model: 38RLB  
Postal/Zip: 53132 Miles/Hrs: 0  
Phone#(res): 4148400858 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: tssllassall@gmail.com Tag#: DB: 3/4 part inquiry.  
Purchased Date: 29 OCT 25 :  
Delivery Date: 17 APR 26 :  
InService Date: :  
Serial#: 4X4TPUP20TP106347 :

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To  
\*\*\*\*\*  
4 COMPLAINT: CAULK AROUND BACKSLPASH IN SHOWER WHERE I SAP POLIC  
BOTTOM PAN/WALL MEET  
CAUSE: This is not a warranty issue the bottom  
pan has a 3 to 4 inch lip that goes  
behind shower wall no rot can happen....  
Customer is requesting sealing it so I  
am but IS NOT WARRANTY CUST OR SALES  
SHOULD PAY FOR THIS THANK YOU.  
CORRECTION: I used air nozzle to blow and clean the  
area customer wants sealed then I ran a  
bead of silicone around the shower stall  
where base and wall meet I had some  
leftover clear silicone so I used that  
REQUEST: .3  
WARR COMPLAINT: WARRANTY REPAIR 1 - The slide ods rug W 1021 FORES  
has stains  
CAUSE: Stained from mfg  
CORRECTION: Used quick solve to remove REQUEST: .1  
APPROVED:.5  
WARR COMPLAINT: WARRANTY REPAIR 2 -The DS rug has stains W 1021 FORES  
CAUSE: Stained floor covering from mfg  
CORRECTION: Used quick solve to remove the stains  
REQUEST: .2 APPROVED: .5  
WARR COMPLAINT: WARRANTY REPAIR 21. The dark wood has W 1021 FORES  
light colored something smeared in spots  
CAUSE: Doors and slide fascia have something  
smeared on them  
CORRECTION: I used thick solution of murpheys oil

Continued on page 2

Work Order : 13082B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                soap sprayed and scrubbed doors down
                well the finish now looks as it should
                no longer any discoloration happening
                REQUEST: .5 APPROVED: .5
WARR    COMPLAINT:  WARRANTY REPAIR 3 -Bottom of the bath   W    1021   FORES
                sink panel has very rough edge shards
                CAUSE:  I finished edge
                CORRECTION: Took fine sand paper and sanded off the
                sharp edge REQUEST:.1 APPROVED: .1
WARR    COMPLAINT:  WARRANTY REPAIR 4 - all corner trim in   W    1021   FORES
                bunk room needs holes filled with putty
                excessive large holes
                CAUSE:  Large staple holes unfilled
                CORRECTION: Used putty to fill REQUEST: .7
                APPROVED: .5
WARR    COMPLAINT:  WARRANTY REPAIR 5 -Recliner chairs have   W    1021   FORES
                marks on them
                CAUSE:  White marks on recliners
                CORRECTION: Used quick solve to remove the spots
                REQUEST: .2 APPROVED: .2
WARR    COMPLAINT:  WARRANTY REPAIR 6 - bottom drawer under   W    1021   FORES
                microwave has a chip out of top edge
                CAUSE:  Small chip
                CORRECTION: Used a touch of putty to fill the little
                chipped area REQUEST:.1 APPROVED: .1
WARR    COMPLAINT:  WARRANTY REPAIR 20 the dining chairs      W    1021   FORES
                have little dings and chips
                CAUSE:  Dinette chair replacement. Received the
                wrong chair. Need to reorder.
                CORRECTION: ..... REQUEST: .2 APPROVED: .2
    
```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR2 F100315982 CHAIR, SMALL WALDEN DINETT W-1021      1    124.75   124.75
    
```

```

*****
Job#  Lab Code  Description           LABOUR    Mech Bill to   Hrs   Rate   Total
*****
  4 WARR      MANUFACTURER WARRANTY HOD  I-SAP          0.50   70.00   35.00
ARR01 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR02 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR21 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR03 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR04 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR05 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR06 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR20 Z992    MISC LABOUR CODE (WARR HOD  W-1021        0.50  140.00   70.00
ARR20 WARR      MANUFACTURER WARRANTY JS    W-1021        0.43  140.00   60.20
    
```

Continued on page 3

Work Order : 13082B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR20 WARR      MANUFACTURER WARRANTY TD    W-1021    0.07   140.00    9.80
ARR20 WARR      MANUFACTURER WARRANTY JS    W-1021    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS    bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL W-1021    1.00    0.00    0.00
ARR20  FRT        FREIGHT      W-1021    1.00   142.36  142.36
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I      SAP          0.00     35.00     0.00     0.00     0.00     35.00
W      1021        124.75    700.00     0.00    142.36     0.00     967.11

Totals      124.75    735.00     0.00    142.36     0.00    1,002.11
*****
```

&k2S  
&k0S