

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville IN  
US  
47725  
812-867-5200

WORK ORDER # 66238

Completed : 14 JAN 22 Customer : 1013 - KEYSTONE RV CO -  
Licence # : Invoice # :  
Stock No : 11031 Description : 2021 5W KEYSTONE MONTANA 3231CK  
Tag : Date In : 04 JAN 22 Mileage :  
Author : C.ALLEN Promised : 31 JAN 22  
Location : 0115 CHECK PREAUTH Date Sched :  
Serial# : 4YDF32321M4704827 Chassis# : 4YDF32321M4704827  
Warr. Date : 28 AUG 21 Cust PO# :  
Print Date : 14 JAN 22

\*\*\*\*\*  
Job # Description JOB INFORMATION Type Bill To \*\*\*\*\*  
\*\*\*\*\*  
1 WARRANTY .WORK E 1013 KEYST  
2 COMPLAINT: THE FRONT LATCH APPEARS TO BE IN FARTHER I SPN SALES  
THAN THE LATCH AT THE REAR OF THE SAME  
COMPARTMENT DOOR.  
CORRECTION: TOOK LATCH APART TO SEE IF IT COULD BE  
MOVED, COULD NOT MOVE TO ADJUST, SHIMMED  
UP CATCH.  
3 COMPLAINT: ACCESS PANEL FOR PANTRY CABINET FOR ICE W 1013 KEYST  
MAKER IN WRONG LOCATION  
CORRECTION: TOOK OUT DRAWERS AND DOOR TO GAIN ACESS  
TO BACK WALL TO CUT HOLE BIGGER TO GAIN  
ACCESS TO SHUTOFF VALVE FOR REF. CUT HOLE  
BIGGER AND MADE BIGGER PANEL TO COVER  
HOLE.  
4 COMPLAINT: SHADE OVER DINING ROOM TABLE FELL W 1013 KEYST  
CORRECTION: TOOK OFF DECARATIVE PIECE AROUND WINDOW  
AND FOUND HANGER WAS BENT AND CROOKED  
STRAIGHTEED UP BRACKET AND BENT CATCH  
BACK AND HOOKED BLINDS BACK IN  
PLACE, INSTALLED DECARATIVE PIECE BACK IN  
PLACE.  
5 COMPLAINT: TRIM INSIDE WASHER DRYER CLOSET ON TOP W 1013 KEYST  
CAME OFF  
CORRECTION: INSTALLED TWO PICES OF TRIM.  
6 COMPLAINT: SOFT CLOSE TRASH CAN DRAWER WONT CLOSE W 1013 KEYST  
ALL THE WAY  
CORRECTION: pulled drawer out and found left side  
rod was out put rod back in place and  
installed drawer and it works fine.  
7 COMPLAINT: RIGHT REFER DOOR IS IN SET AND WILL NOT W 1013 KEYST  
STAY LATCHED FOR TRANSPORT THE BASE THAT  
THE SCREW DOWN PIECE GOES INTO IS  
FLEXING IN TURN LETTING THE REFER DOOR  
COME LOOSE.

Continued on page 2

Work Order : 66238

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
CORRECTION: CUT ROD DOWN SO IT WOULD HIT DOOR TO
                STAY SHUT.
8      COMPLAINT: DOOR SIDE MARKER LIGHT BASE IS CRACKED.  I      SPN      SALES
CORRECTION: REPLACED MARKER LIGHT I HAD EXTRA ONE.
```

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  2  Z990      MISCELLANEOUS REPAIR  DGH  I-SPN        1.00  25.00  25.00
  3  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       1.00  150.00  150.00
  4  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       0.50  150.00  75.00
  5  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       0.20  150.00  30.00
  6  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       0.00  150.00  0.00
  6  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       0.20  150.00  30.00
  7  Z990      MISCELLANEOUS REPAIR  DGH  W-1013       0.20  150.00  30.00
  8  Z990      MISCELLANEOUS REPAIR  DGH  I-SPN        0.00  25.00  0.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
  1  SS      SHOP SUPPLIES  E-1013  1.00  0.00  0.00
*****
```

CUSTOMER COMMENTS

```
*****
BH SENT IN PREAUTH 1-8
*****
```

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	SPN	0.00	25.00	0.00	0.00	0.00	25.00
W	1013	0.00	315.00	0.00	0.00	0.00	315.00
Totals		0.00	340.00	0.00	0.00	0.00	340.00