



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222
NO@GMAIL.COM
1025 WI-77
Minong, WI 54859

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550372
1 Mi In
In Service Date:
01/01/2017
Stock #: KS26-43

Service Advisor
BONNIE SEEMANN
bonnie

A. MISCELLANEOUS DEALER STATES VINYL INSERT ON REAR DRIVERS SIDE EXTRUSION HAS 1" LONG SLICE. Warranty Pay \$0.00

Job added by BONNIE SEEMANN on Wed Jun 10, 2026 | 12:16 PM

1. Damaged during install?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.01	0	0	\$0.00	\$0.00

1. Extrusion has slice approximately 1 foot long from what I would guess would be a utility knife. Recommend replacing complete vinyl insert on drivers side. Request 2.0 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$0.00	\$0.00

B. MISCELLANEOUS DEALER STATES CUPBOARD DOORS ABOVE TV OVERLAP. Warranty Pay \$82.50

Job added by BONNIE SEEMANN on Wed Jun 10, 2026 | 12:16 PM

1. Broken hinge





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARP22 TE550372	Service Advisor BONNIE SEEMANN bonnie
---	---	---	--

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50
Labor Cost: \$12.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.4	0.5	0.5	\$82.50	\$12.00

1. went back and forth trying to align cupboards, Screw on 1 hinge does not adjust. Top right, facing rear. Recommend new adjusting hinge. I have 0.5 hours in now. Request 1.5 hours to finish

Parts

Parts Total Sale Amount \$0.00
Parts Total Cost Amount \$0.00

Name	Quantity	Unit Price	Sale Price	Cost Price
adjusting hinge	1	\$0.00	\$0.00	\$0.00

Total Labor Sale \$82.50	Total Labor Cost \$12.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

C. MISCELLANEOUS	DEALER STATES TAPE ON TRIM IN THE ABOVE TV STORAGE IN MAIN ROOM IS PEELING.	Warranty Pay	\$0.00
-------------------------	--	---------------------	---------------

Job added by BONNIE SEEMANN on Wed Jun 10, 2026 | 12:16 PM

1. Peeling tape

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.1	0	0	\$0.00	\$0.00

1. tape on seam trim was peeling. Applied pressure to surface to re adhere trim tape. Looks better, still has air bubbles.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARP22 TE550372	Service Advisor BONNIE SEEMANN bonnie
---	---	---	--

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00
Labor Cost: \$0.00

Recommend replacing trim. Request 1.5 hours

Parts

Parts Total Sale Amount \$0.00
Parts Total Cost Amount \$0.00

Name	Quantity	Unit Price	Sale Price	Cost Price
Trim or tape	1	\$0.00	\$0.00	\$0.00

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

D. MISCELLANEOUS	DEALER STATES REAR DRIVERS SIDE SLIDEOUT HAS FABRIC OR PLASTIC STICKING OUT BEHIND INTERIOR FASCIA TRIM.	Warranty Pay	\$49.50
------------------	--	--------------	---------

Job added by BONNIE SEEMANN on Wed Jun 10, 2026 | 12:16 PM

1. Pinched fabric

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50
Labor Cost: \$7.20

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.11	0.3	0.3	\$49.50	\$7.20

1. fabric was pinched and extruding from original install. Cut fabric out with fresh utility blade. Looks good. Request 0.5 hours

Total Labor Sale \$49.50	Total Labor Cost \$7.20	Total Parts Sale \$0.00	Total Parts Cost \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	Billing-Customer Same as Customer	Vehicle 2026 Keystone ARCADIA 4YDFARP22 TE550372	Service Advisor BONNIE SEEMANN bonnie
---	---	---	--

E. MISCELLANEOUS	DEALER STATES THERE IS A TIRE ON RIM IN THE FRONT COMPARTMENT NEEDS TO BE TESTED FOR LEAKS BECAUSE SPARE TIRE IIN ON AXLE.	Warranty Pay	\$165.00
-------------------------	---	---------------------	-----------------

Job added by BONNIE SEEMANN on Wed Jun 10, 2026 | 12:16 PM

1. Bubble on tire

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.41	1	1	\$165.00	\$24.00

1. removed aluminum rim from front compartment, gathered tools, lifted unit, secured with jack stand, performed leak test, no evidence of leak, but discovered bubble in sidewall close to the seal. Recommend replacing tire and washing and reinstalling spare and reinstalling in front compartment. I have time in now. Request 3.0 hours to complete

Parts

Parts Total Sale Amount \$0.00

Parts Total Cost Amount \$0.00

Name	Quantity	Unit Price	Sale Price	Cost Price
tire	1	\$0.00	\$0.00	\$0.00

Total Labor Sale \$165.00	Total Labor Cost \$24.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550372

Service Advisor
BONNIE SEEMANN
bonnie

Category	Sale	Cost
Labor	\$297.00	\$43.20
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$297.00	\$43.20

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Jun 10, 2026	1:25 PM	1:25 PM	0.01 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 10, 2026	1:25 PM	1:42 PM	0.28 hrs	W	matthewl	0.5 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 10, 2026	1:42 PM	1:49 PM	0.12 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
C	MISC	Wed Jun 10, 2026	1:49 PM	1:55 PM	0.10 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$297.00

RO# : 40932 Tag# : TE550372

Check-in: Wed Jun 10, 2026 | 12:16 PM
Ready for Pickup: Thu Jun 11, 2026 | 3:12 PM
Promise Time: Mon Jun 15, 2026 | 6:00 PM

Customer
linkautomotive - 2174
PD7155200709I
Customer
1235491
+1 - (715) 466 - 2222

Billing-Customer
Same as Customer

Vehicle
2026 Keystone ARCADIA
4YDFARP22 TE550372

Service Advisor
BONNIE SEEMANN
bonnie

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	Wed Jun 10, 2026	1:55 PM	2:02 PM	0.11 hrs	W	matthewl	0.3 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 10, 2026	2:10 PM	2:31 PM	0.36 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 10, 2026	2:31 PM	2:34 PM	0.05 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40932	LINK RV	\$297.00
57200	40932	LINK RV	-\$297.00
67200	40932	LINK RV	\$43.20
14400	matthewl	LINK RV	-\$43.20
54200	40932	LINK RV	\$0.00
64000	40932	LINK RV	\$0.00
14000	40932	LINK RV	\$0.00

