



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

**Customer**  
Michael Wester  
1238376  
+1 - (218) 391 - 9486  
mmike57@hotmail.com  
9155 East Hughes  
Avenue  
Solon Springs, WI 54873

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2022 Jayco Eagle  
1UJCJOBT6N1WT0110  
2 Mi In / 2 Mi Out  
Sold Date: 10/07/2024  
Stock #: RV22-16

**Service Advisor**  
KEVIN GOODIEL  
goodielk

<b>A. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE BATHROOM COUNTER TOP IS CRACKED</b>	<b>Warranty Pay</b>	<b>\$472.99</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. stress?

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$330.00

Labor Cost: \$82.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	2.17	2.3	2.3	\$330.00	\$82.80

1. would need new countertop requesting 2 hrs 6-8 Removed and replaced bathroom vanity countertop. Had to transfer, faucet, drain tail pipe, sink. Also had to make and install new 3/4" cleats to bottom of countertop to attach to vanity. Hooked all up and sealed back splash.

**Parts**

Parts Total Sale Amount \$142.99

Parts Total Cost Amount \$109.99

Name	Quantity	Unit Price	Sale Price	Cost Price
2026605 - TOP,LAVATORY SYMPHONY ONYX OMNOVA PRESSED 17.50X31.25X.63 .25 STRAIGHT EDGE	1	\$142.99	\$142.99	\$109.99

Total Labor Sale  
\$330.00

Total Labor Cost  
\$82.80

Total Parts Sale  
\$142.99

Total Parts Cost  
\$109.99

<b>B. MISCELLANEOUS</b>	<b>CUSTOMER STATES SHOWER SURROUND IS DROPPED DOWN AND THEY CAN FEEL SOME SORT OF LUMP BEHIND IT</b>	<b>Warranty Pay</b>	<b>\$345.45</b>
-------------------------	--	---------------------	-----------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOBT6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. White foam tape on. Back of surround came loose.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$297.00

Labor Cost: \$72.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	1.97	2	2	\$297.00	\$72.00

1. would need to remove clean reinstall and re-stick requesting 3 hr. Removed shower doors, removed glass Door lock. Cleaned old seal end off surround edge. Pulled surround out from back, short wall, and side long wall. Foam tape peeled off, there was only 3 strips down long wall and 3 on back wall. Removed what peeled off, and added more strips. Also added an extra horizontally on long and short walls. Screws for shower base at bottom were sticking out, so snugged those up also. Re-set shower surround up to sealant line where it was from factory. Re-sealed all edges, re-installed shower doors, and latch.

**Parts**

Parts Total Sale Amount \$48.45

Parts Total Cost Amount \$37.27

Name	Quantity	Unit Price	Sale Price	Cost Price
0088772 - TAPE,DBL	1	\$48.45	\$48.45	\$37.27

Total Labor Sale  
\$297.00

Total Labor Cost  
\$72.00

Total Parts Sale  
\$48.45

Total Parts Cost  
\$37.27

<b>C. MISCELLANEOUS</b>	<b>CUSTOMER STATES THERES PAINT CHIPPING ON THE VANITY DOORS TO THE BATHROOM SINK</b>	<b>Warranty Pay</b>	<b>\$235.64</b>
-------------------------	---	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. wear?





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOBT6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00  
Labor Cost: \$64.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	1.73	1.8	1.8	\$132.00	\$64.80

1. would need new doors requesting .5 hrs 6-8 Removed and replaced cabinet doors. Had to transfer all hardware, hinges, latch and handles, also had to drill holes in new doors for hinges.

Parts

Parts Total Sale Amount \$103.64  
Parts Total Cost Amount \$79.72

Name	Quantity	Unit Price	Sale Price	Cost Price
2033750 - DOOR,FLAT PANEL NAVAL BLUE 13.00X25.00 SQUARE CORNER 2.25 RAIL BEVEL WITH BUMP RO5	2	\$51.82	\$103.64	\$79.72

<b>Total Labor Sale</b> \$132.00	<b>Total Labor Cost</b> \$64.80	<b>Total Parts Sale</b> \$103.64	<b>Total Parts Cost</b> \$79.72
-------------------------------------	------------------------------------	-------------------------------------	------------------------------------

<b>D. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE SLIDING BATHROOM DOOR HAS PAINT COMING OFF OF IT</b>	<b>Warranty Pay</b>	<b>\$228.39</b>
-------------------------	---	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. wear

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00  
Labor Cost: \$28.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.62	0.8	0.8	\$132.00	\$28.80

1. would need new door requesting 1 hr 6-8.Removed and replaced bathroom pocket door, switched over hardware.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOB6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00  
Labor Cost: \$28.80

Handles, and roller sockets on top of door.

Parts

Parts Total Sale Amount \$96.39  
Parts Total Cost Amount \$74.15

Name	Quantity	Unit Price	Sale Price	Cost Price
0338930 - DOOR, INTR 23.75X72.50X 1.38	1	\$96.39	\$96.39	\$74.15

Total Labor Sale \$132.00	Total Labor Cost \$28.80	Total Parts Sale \$96.39	Total Parts Cost \$74.15
------------------------------	-----------------------------	-----------------------------	-----------------------------

<b>E. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE RECLINER CHAIR IN THE LIVING ROOM IS COMING APART WERE YOU LAY YOUR HEAD</b>	<b>Warranty Pay</b>	<b>\$3,441.44</b>
-------------------------	---	---------------------	-------------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. wear

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00  
Labor Cost: \$36.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	1.09	1	1	\$165.00	\$36.00

1. would new couch section requesting .5 hrs 6-8 Removed and replaced 3 piece recliners. Tabs that lock together were bent, had to bent back so they would slide together. New recliners 4" wider than old ones, so they stick out past stub wall some. Could not slide over any farther as they would hit slide facia when trying to recline.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOB6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00  
Labor Cost: \$36.00

Parts

Parts Total Sale Amount \$3,276.44  
Parts Total Cost Amount \$2,520.34

Name	Quantity	Unit Price	Sale Price	Cost Price
2041028 - SOFA,THTR 60" HRNSH BENTLEY W/CSL 270 GRA STCH	1	\$3,276.44	\$3,276.44	\$2,520.34

<b>Total Labor Sale</b> \$165.00	<b>Total Labor Cost</b> \$36.00	<b>Total Parts Sale</b> \$3,276.44	<b>Total Parts Cost</b> \$2,520.34
-------------------------------------	------------------------------------	---------------------------------------	---------------------------------------

<b>F. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE EXTERIOR WATER PUMP SWITCH DOES DOES NOT WORK IN THE BASEMENT</b>	<b>Warranty Pay</b>	<b>\$0.00</b>
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. Pump switch in water compartment would not work.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.19	0	0	\$0.00	\$0.00

1. Took switch out, found only 1 wire on back, pulled panel in basement area, found blue wire and re-connected to switch, switch works, and pump comes on as should.

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOBT6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

<b>G. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE WATER CONNECTION ON EXTERIOR BYE THE MAIN DOOR DOES NOT CONNECT</b>	<b>Warranty Pay</b>	<b>\$99.00</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. Outside sprayer by door would not connect.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00

Labor Cost: \$21.60

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.53	0.6	0.6	\$99.00	\$21.60

1. Sometimes those outside sprayers get stuck from non use. Used small screw driver, pushed in to free it up, Then hose connects as should, tested with water, no leaks.

<b>Total Labor Sale</b> \$99.00	<b>Total Labor Cost</b> \$21.60	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>H. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE RIGHT REAR JACK DOES NOT GO DOWN all the time</b>	<b>Warranty Pay</b>	<b>\$1,130.00</b>
-------------------------	--	---------------------	-------------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. Right rear jack. Does. Not work sometimes.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$577.50

Labor Cost: \$126.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	3.34	3.5	3.5	\$577.50	\$126.00

1. Right rear (Door side) jack does not work properly. When you try to run separate, jack will not operate, and says "Excessive slope",but when you run auto level, jack extends as should. Took under belly access down to check controller on frame. All plugs good, screws in place, as should, mounted as should be. Tried leveling, and "Homing" jacks, extending down more than 6" and then retracting all. None of that worked to fix issue. Found control board in





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM

Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM

Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOBT6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$577.50

Labor Cost: \$126.00

front storage compt, Swapped Right Rear plugs with Right Front plugs. Issue stayed on Right rear connection on control board. Would say bad control board. Removed and replaced control board, Operated Jacks, re-set Zero point, and re-homed jacks, All worked as should, no issues, no error codes. Right rear jacks works with auto level, and seperatly now, with no issues.

Parts

Parts Total Sale Amount \$552.50

Parts Total Cost Amount \$425.00

Name	Quantity	Unit Price	Sale Price	Cost Price
803280 - LEVELING BOARD	1	\$552.50	\$552.50	\$425.00

Total Labor Sale  
\$577.50

Total Labor Cost  
\$126.00

Total Parts Sale  
\$552.50

Total Parts Cost  
\$425.00

I. MISCELLANEOUS	CUSTOMER STATES REFRIDGERATOR WAS PINNED IN BETWEEN THE BRACKET THAT WE INSTALLED	Warranty Pay	\$495.00
------------------	---	--------------	----------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. Fridge Moved during travel, and was wedged in bracket tape was installed.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$495.00

Labor Cost: \$108.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	2.78	3	3	\$495.00	\$108.00

1. Checked fridge, found it to be tipped forward in the hole. Checked back found 3 screws, took screws out, and fridge tipped down in back, now sitting flat in the hole. Re-installed screws. On inside, metal bracket was held on by a 1x2 screwed to a 3/4" cleat to the ceiling in fridge compartment, above doors. Removed small 1x2 stile. Removed the whole thing, Cut and installed a 1x4, screwed multiple spots to ceiling, then screwed bracket to another 1x4, set in place, pushed bracket tight against fridge, and screwed the 1x4,s together. Made bracket way more sturdy, as the 1x's do not





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOBT6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$495.00  
Labor Cost: \$108.00

teeter on one another when fridge moves. Much more secure than it was previously.

<b>Total Labor Sale</b> \$495.00	<b>Total Labor Cost</b> \$108.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	-------------------------------------	-----------------------------------	-----------------------------------

<b>J. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE BLACK WATER TANK ALWAYS READS FULL. THEY SAY THEY HAVE NEVER PUT TOILET PAPER IN IT</b>	<b>Warranty Pay</b>	<b>\$214.50</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. Black tank always reads full.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$214.50  
Labor Cost: \$46.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	1.3	1.3	1.3	\$214.50	\$46.80

1. Filled twice, dumped and flushed black tank, got black tank to read 2/3. So sensors are working, Recommend adding some sort of chemical, or maybe bag of ice and driving, to clean sensors. All tanks empty.

<b>Total Labor Sale</b> \$214.50	<b>Total Labor Cost</b> \$46.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>K. MISCELLANEOUS</b>	<b>CUSTOMER STATES THE DINETTE TABLE EDGES SEEMS THE WRAPPING IS COMING UNDONE</b>	<b>Warranty Pay</b>	<b>\$310.21</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Fri May 1, 2026 | 2:13 PM

1. unknown





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOB6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50  
Labor Cost: \$36.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.91	1	1	\$82.50	\$36.00

1. would need new table top requesting .5hrs 6-8. Removed and replace table top, had to transfer 3/4" staple cleat to new table top,

Parts

Parts Total Sale Amount \$227.71  
Parts Total Cost Amount \$175.16

Name	Quantity	Unit Price	Sale Price	Cost Price
2037031 - TOP,DINETTE PRESSED CHARRED NIGHT OAK 25.00X47.00	1	\$227.71	\$227.71	\$175.16

<b>Total Labor Sale</b> \$82.50	<b>Total Labor Cost</b> \$36.00	<b>Total Parts Sale</b> \$227.71	<b>Total Parts Cost</b> \$175.16
------------------------------------	------------------------------------	-------------------------------------	-------------------------------------

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

**Customer**  
Michael Wester  
1238376  
+1 - (218) 391 - 9486

**Billing-Customer**  
Same as Customer

**Vehicle**  
2022 Jayco Eagle  
1UJCJOB6N1WT0110

**Service Advisor**  
KEVIN GOODIEL  
goodielk

Category	Sale	Cost
Labor	\$2,524.50	\$622.80
Parts	\$4,448.12	\$3,421.63
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$6,972.62</b>	<b>\$4,044.43</b>

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
G	MISC	Fri Jun 5, 2026	3:48 PM	4:19 PM	0.53 hrs	W	turnerl	0.6 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Mon Jun 8, 2026	8:11 AM	9:55 AM	1.73 hrs	W	turnerl	1.8 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Mon Jun 8, 2026	9:55 AM	12:06 PM	2.17 hrs	W	turnerl	2.3 hrs
Tag: Regular Hour			Reason: -					
D	MISC	Mon Jun 8, 2026	1:18 PM	1:55 PM	0.62 hrs	W	turnerl	0.8 hrs
Tag: Regular Hour			Reason: -					
K	MISC	Mon Jun 8, 2026	2:00 PM	2:54 PM	0.91 hrs	W	turnerl	1 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM  
Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM  
Promise Time: Wed May 6, 2026 | 6:00 PM

<b>Customer</b> Michael Wester 1238376 +1 - (218) 391 - 9486	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2022 Jayco Eagle 1UJCJOB6N1WT0110	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
E	MISC	Mon Jun 8, 2026	2:54 PM	3:59 PM	1.09 hrs	W	turnerl	1 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Mon Jun 8, 2026	4:16 PM	4:27 PM	0.19 hrs	W	turnerl	0 hrs
Tag: Regular Hour			Reason: -					
I	MISC	Tue Jun 9, 2026	8:15 AM	11:01 AM	2.78 hrs	W	turnerl	3 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Jun 9, 2026	11:02 AM	12:07 PM	1.07 hrs	W	turnerl	2 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Jun 9, 2026	12:50 PM	1:44 PM	0.90 hrs	W	turnerl	-
Tag: Regular Hour			Reason: -					
H	MISC	Tue Jun 9, 2026	1:47 PM	4:30 PM	2.71 hrs	W	turnerl	3.5 hrs
Tag: Regular Hour			Reason: -					
H	MISC	Wed Jun 10, 2026	8:06 AM	8:43 AM	0.63 hrs	W	turnerl	-
Tag: Regular Hour			Reason: -					
J	MISC	Wed Jun 10, 2026	8:44 AM	10:01 AM	1.30 hrs	W	turnerl	1.3 hrs
Tag: Regular Hour			Reason: -					

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40555	LINK RV	\$6,972.62
57200	40555	LINK RV	-\$2,524.50
67200	40555	LINK RV	\$622.80
14400	turnerl	LINK RV	-\$622.80





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$6,972.62

RO# : 40555 Tag# : N1WT0110

Check-in: Fri May 1, 2026 | 2:13 PM

Ready for Pickup: Thu Jun 11, 2026 | 11:53 AM

Promise Time: Wed May 6, 2026 | 6:00 PM

**Customer**  
Michael Wester  
1238376  
+1 - (218) 391 - 9486

**Billing-Customer**  
Same as Customer

**Vehicle**  
2022 Jayco Eagle  
1UJCJOB6N1WT0110

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
54200	40555	LINK RV	-\$4,448.12
64000	40555	LINK RV	\$3,421.63
14000	40555	LINK RV	-\$3,421.63

