

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 889136
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2CXSB1NS042985
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 220 / 220A
 ITEM # APTT265RBSS
 DEALER RO # 66239
 CLAIM START DATE 01/06/2022
 CLAIM END DATE 01/01/1900

Labor rate: \$130.00
 OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-43-01-00-000835 BBQ Grill - Exterior/Exterior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-06 15:21:15 :: WHEN OPENING THE OUTSIDE GRILL THE LID FELL OFF OPENED THE GRILL THE LID FELL OFF NEED TO INSTALL NEW GRILL
 Model # **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$26.00
 Serial # **Appr Hrs** 0.10 **Appr Labor Amt** \$13.00

Notes
 reduced to flat rate

Labor

Line# 2 **Operation Code** **Operational Description**
 20-66-01-17-000671 Lock Cylinder & Keys - Exterior/Entry Doors/Replace/Latch
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-06 15:23:27 :: MISSING LOCK ON OUTSIDE DOOR FOR BACK OF REF PART MISSING DO I INSTALL A 751 KEY OR A DOOR KEY PLEASE ADVISE
 Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$52.00
 Serial # **Appr Hrs** 0.20 **Appr Labor Amt** \$26.00

Notes
 reduced to flat rate

Labor

Line# 3 **Operation Code** **Operational Description**
 30-100-24-00-001046 Cabinet Door - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-06 15:24:54 :: LEFT DOOR ABOVE BED NEEDS ADJ WONT SHUT ADJUSTED DOOR UP.
 Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$52.00
 Serial # **Appr Hrs** 0.30 **Appr Labor Amt** \$39.00

Notes
 reduced to flat rate

Labor

Line# 4 **Operation Code** **Operational Description**
 30-100-24-00-001046 Cabinet Door - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2022-01-06 15:32:29 :: LEFT DOOR BELOW TV NEEDS ADJ ADJUSTED DOOR AND LATCH.
 Model # **Dlr Sub Hrs** 0.40 **Sub Labor Amt** \$52.00
 Serial # **Appr Hrs** 0.30 **Appr Labor Amt** \$39.00

Labor
Line# 5

Notes
reduced to flat rate

Operation Code
70-173-01-00-002112

Operational Description
Furnace Duct - Boxed - Appliances/Furnace (Dometic, Atwood)/Replace/
No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-01-06 15:33:43 :: FURANCE TUBE IS OFF
LOOSEENED CLAMP UP AND INSTALLED ON FURNANCE AND TIGHTENED AND REINSTALLED COVER.

Model #	Dir Sub Hrs	0.40	Sub Labor Amt	\$52.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$39.00

Notes
reduced to flat rate

Submitted	Labor Amt	\$234.00	Approved	Labor Amt	\$156.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$234.00		Total	\$156.00

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.