

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville IN  
US  
47725  
812-867-5200

WORK ORDER # 66241

Completed : 21 JAN 22                      Customer : 10024 - FOREST RIVER TRAVEL TRAILER  
Licence # :                                  Invoice # :  
Stock No : 11050                            Description : 2022 TT COACHMEN FREEDOM EXPRESS 32  
Tag :                                        Date In : 04 JAN 22                      Mileage : 0  
Author : BH                                  Promised :  
Location : 0131 CHECK PREAUTHD            Date Sched :  
Serial# : 5ZT2FEYB2NW022384              Chassis# : 5ZT2FEYB2NW022384  
Warr. Date : 15 JAN 22                      Cust PO# :  
Print Date : 21 JAN 22

\*\*\*\*\*  
Job #    Description                      JOB INFORMATION                      Type Bill To  
\*\*\*\*\*  
PDIN    COMPLAINT:    PDI - NEW TRAVEL TRAILER                      I    PDI    PRE-D  
         CAUSE:                      PDINTT - PDI NEW TRAVEL TRAILER.  
         CORRECTION: Moved unit into shop from sales lot.  
   Purged and filled LP tanks. Installed  
   new battery box. Installed new battery.  
   Checked all exterior lights and brakes.  
   Checked lug nuts and set tire pressure  
   at 80 psi. Recorded all tire serial  
   numbers. Operated power jacks. Checked  
   roof and both awnings. Checked  
   entrance door and all compartment doors.  
   Checked power cord. Checked converter  
   output. Checked all interior lights.  
   Checked all windows and blinds. Checked  
   all cabinets and drawers. Checked all  
   electrical outlets and GFCI outlets.  
   Checked all USB outlets. Removed all  
   packing from all appliances. Filled  
   fresh water tank and flushed antifreeze  
   from all water lines and faucets.  
   Opened by-pass on water heater and  
   filled. Purged all air from water  
   system. Checked all water lines and  
   faucets for leaks. Performed LP drop  
   test and set LP pressure at 11 in.wc.  
   Operated all appliances. Assembled  
   outside grille and checked operation.  
   Filled all holding tanks and checked  
   monitor panel. Front bathroom toilet  
   new reading on monitor panel. Rear  
   bathroom sink drains into rear toilet  
   holding tank. Outside kitchen sink  
   drains into rear grey tank. Checked  
   operation of TV Antenna, TV, Radio and

Work Order : 66241

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
FPDI    COMPLAINT:  Fireplace.
        CAUSE:      FINAL PDI ON NEW TRAVEL TRAILERS                I    PDI    PRE-D
        CORRECTION: FPDINTT - FINAL PDI ON NEW TRAVEL
                    TRAILER.
                    By-passed water heater.  Blew out all
                    water lines and faucets.  Added
                    antifreeze to all water lines and
                    faucets , including outside kitchen and
                    shower.  Poured antifreeze in all drain
                    traps.  Drained all holding tanks,
                    including water heater..  Retracted all
                    electric jacks.  Applied all company
                    decals.  Moved unit to wash bay area.

WALK    COMPLAINT:  WALK THRU                I    PDI    PRE-D
        CAUSE:      WALK THROUGH
        CORRECTION: WALK THROUGH WENT GOOD, PICKING UP ON
                    MONDAY.

1       COMPLAINT:  2nd BATHROOM DOOR HITTING DOOR                W    10024  FORES
        CAUSE:      FRAME...NOTED AT DELIVERY
                    2ND BATHROOM DOOR HITTING DOOR
                    FRAME.....NOTED AT DELIVERY.
        CORRECTION: Checked operation of rear bathroom
                    door.  Latch side of door hitting door
                    frame at top corner and at latch plate.
                    Tightened mounting screws in latch
                    plate.  Tightened all hinge mounting
                    screws.  Door now closes without hitting
                    door frame.

2       COMPLAINT:  FRONT TOILET TANK NOT READING ON MONITOR W    10024  FORES
        CAUSE:      FRONT TOILET TANK NOT READING ON
                    MONITOR.
        CORRECTION: Front black holding tank is full and not
                    reading on monitor panel.  Located area
                    under rear black tank.  Removed two
                    screw nails holding underbelly in place.
                    Cut underbelly for access to monitor
                    wires.  Found ground wire laying down on
                    underbelly and not connected to ground
                    probe on tank.  Screw is missing on
                    ground probe on tank.  Could not find
                    missing screw.  Had to make a small
                    screw to fit.  Had to cut another access
                    hole below ground probe location to get
                    screw replace.  Reattached ground wire
                    to ground probe.  Checked monitor panel
                    operation.  Rear black tank now reading
                    full.  Applied underbelly tape to both
                    access holes and replaced screw nails
                    that were removed.
    
```

Continued on page 3

Work Order : 66241

3 COMPLAINT: SCREWS IN OUTSIDE KITCHEN DOOR ACCESS AT W 10024 FORES  
 BOTTOM ARE LEAKING WATER  
 CAUSE: SCREWS IN OUTSIDE KITCHEN DOOR ACCESS AT  
 BOTTOM ARE LEAKING WATER.  
 CORRECTION: Bottom screws securing outside kitchen  
 door frame to opening were pulled  
 tightough frame. Removed all bottom  
 mounting screws. Applied black silicone  
 to holes. Reinstalled mounting screws.  
 Covered screw heads with black silicone  
 also.

```
*****
Job # Part No Description          PARTS          Bill to Qty Price Total
*****
PDINT 13034 55362 STD BATTERY          I-PDI 1 10.95 10.95
FPDIN DC-24 ADVANCE GROUP 24 D I-PDI 1 131.99 131.99
FPDIN 5516 A10-3050FHVP 30M-5 I-PDI 1 23.99 23.99
FPDIN 24181 -50 RV ANTI-FREEZE I-PDI 3 4.99 14.97
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
DINTT Z991 MISC LABOUR CODE (INTE DKM I-PDI 0.00 150.00 0.00
DINTT Z991 MISC LABOUR CODE (INTE DKM I-PDI 0.59 150.00 88.50
DINTT Z991 MISC LABOUR CODE (INTE DKM I-PDI 4.08 150.00 612.00
DINTT Z991 MISC LABOUR CODE (INTE DKM I-PDI 1.33 150.00 199.50
DINTT Z991 MISC LABOUR CODE (INTE DKM I-PDI 0.00 150.00 0.00
DINTT PDINTT PDI - NEW TRAVEL TRAIL DKM I-PDI 2.00 150.00 300.00
WALK Z990 MISC LABOUR CODE (EXTE BAP I-PDI 1.50 130.00 195.00
1 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.30 150.00 45.00
2 Z990 MISC LABOUR CODE (EXTE DKM W-10024 1.00 150.00 150.00
2 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.00 150.00 0.00
3 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.20 150.00 30.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
DINTT SS SHOP SUPPLIES I-PDI 1.00 35.00 35.00
DINTT LP20 20 LB. LP CYLINDER I-PDI 2.00 14.00 28.00
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I PDI 181.90 1395.00 0.00 63.00 0.00 1,639.90
W 10024 0.00 225.00 0.00 0.00 0.00 225.00
Totals 181.90 1620.00 0.00 63.00 0.00 1,864.90
*****
```

Continued on page 4

Work Order : 66241