

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2678561
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRPB8TB526881
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT248RE
		DEALER RO #	72837-1
		CLAIM START DATE	05/18/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-91-01-00-002284 Flip or Storage Sofa - Hinged Bottom or Back Cushion - Interior/Living Quarters, Sofa, Chair/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-18 09:26:51 :: Complaint: Storage container under the bed has a white stain Cause: Material defect and/or contamination during manufacturing or handling resulting in a permanent discoloration Correction: Order replacement upholstered lid assembly and remove existing lid. Installed new lid.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00

Notes
 Authed as requested

Labor

Line# 2 **Operation Code** **Operational Description**
 30-91-24-00-000923 Furniture - Sofa or Chairs - Interior/Living Quarters, Sofa, Chair/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-18 09:31:04 :: Complaint: Left side recliner does not recline Cause: Failure of factory installed recliner mechanism and/or internal linkage component resulting in loss of function Correction: Remove recliner assembly to access mechanism. Inspect linkage, actuator/release components and track system. Repair or replace defective recliner mechanism components. Reinstall and properly secure recliner assy. Adjust mechanism for proper alignment and operation. Function test multiple cycles to ensure smooth operation in full extension/retraction. Inspect adjacent components to ensure no additional issues. Estimate one hour for diag. removal, repair/replacement, reinstallation and testing

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00
Serial#	Appr Hrs	0.00	Appr Labor Amt \$0.00

Notes
 Need pictures of entire recliner. Is this the right hand facing or the left hand facing? Need pictures of all tags and law tags on the underside of the recliner to be able to file a claim with the vendor.
 Forest River requested the following information: Need pictures of entire recliner. Is this the right hand facing or the left hand facing? Need pictures of all tags and law tags on the underside of the recliner to be able to file a claim with the vendor. The Dealer has failed to provide it within 14 days. The repair line has now been denied as recommended by The Forest River Way guidelines.

Submitted	Labor Amt	\$228.00	Approved	Labor Amt	\$38.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$228.00		Total	\$38.00

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.