

Steven Black's RM2451 refrigerator

3 messages

CustomerSupportCenter <customersupportcenter@dometic.com>  
To: "ashlee@dealer-advisors.com" <ashlee@dealer-advisors.com>

Wed, May 27, 2026 at 2:09 PM

Hello Ashlee:

I had spoken with Cole who provided your email address to reach out regarding Mr. Steven Black's refrigerator model # RM2451 w/sn# MB74501204.

We have received the Refrigerator Performance check list for warranty coverage form (shown below) submitted on 5/20/26.

**DOMETIC**  
Refrigerator Performance Check-List for Warranty Coverage

Once Completed - Email to techservice@dometic.com  
*\*Incomplete or inaccurate information will delay processing.\**  
*\*Replacement parts/product will be sent at no charge unless prior approval has taken place.\**

Dealer Name: Triam RV Center Dealer Account # \_\_\_\_\_  
 Dealer Phone: 423-235-1147 Dealer Fax: \_\_\_\_\_  
 Dealer Contact: Stephanie Dealer PO # / Ref # \_\_\_\_\_  
 Dealer Email: trwarranty@triamrv.com

Customer Date of Purchase - or - Stock Unit: 1-6-24  
 Customer Name: Steve Black  
 RV Manufacturer: Xtreme Outdoors Year of Coach: 2024  
 Complete RV VIN: 7B11TT2119R1000043

Dometic Model # Rm 2451  
 Dometic Serial # MB74501204  
 Dometic Product / Mfg. # 93600011

Nature of Complaint: Fridge not cooling  
 Part Required for Repair: Replace fridge

**Diagnostic / Testing Information**

Is there is a visible leak from the cooling unit? \_\_\_\_\_  
 \*\*\*\*\* If a leak is identified, no additional testing is required. \*\*\*\*\*

Upon complaints of an absorption fridge not cooling to the customers satisfaction, often, the issue is due to poor venting. Verify the following for venting issues; NO open air space on the left, right, or top of the fridge. NO more than 1" from the cooling unit to the side wall of the RV. If installed with two side wall vents, verify there is a fan and that it is working, verify there is a baffle extension or "false wall" leading up to within 1/2" - 1/4" from the bottom of the condensing fins, and verify there is a turning vein or "deflecting shield" above the condensing fins. If the unit is installed and vented properly but not cooling, proceed with a cooling unit bypass test as follows.

Unplug the thermistor from the lower control board and run the unit like this for 8 hrs.  
**\*\*\*RM1350, RM3762, RM3962, & DMR702-D units need a spare thermistor plugged into lower control board and hanging outside lower access door with above 50 degree F outside.\*\*\***

After 8 hours of running wide open, what is the substance temperature? \_\_\_\_\_  
 12V DC: 13.45 120V AC: 122.2 Heating Element AC Amps: 1.49  
 Heating Element Ohms: \_\_\_\_\_ Thermistor Ohms (while in ice water): \_\_\_\_\_

**\*\*\* If the problem is specific to gas operation please provide the following \*\*\***  
 Gas Pressure: 11 Gas Valve Ohms: \_\_\_\_\_

If a Complete fridge replacement is deemed necessary, will the fridge fit through the RV door? \_\_\_\_\_


**NOTE:** This form is used for authorization only. This is NOT used for labor reimbursement.  
 For labor reimbursement, please submit a warranty service report to \_\_\_\_\_

We are not seeing that the bypass test was done.

# To Perform a Bypass Test of the Cooling Unit

## **Americana/Americana Plus**

Disconnect the thermistor from the control board at **P2** (with the thermistor unplugged no temperature is sensed, therefore, it will run continuously). This was designed intentionally so that if the thermistor fails the unit will get as cold as it possibly can since there are no error codes to display and warn the customer that the thermistor has failed.



We are also needing photos of the substance temperature from inside the RM2451 for review.

If you have any further information that can be submitted for review that would be appreciated.

Thank you.

Sincerely,

Consumer Satisfaction Survey!



**Kendra Vickers**  
Customer Experience Rep, Consumer Escalation Rep,  
Phone 800-544-4881

Dometic North America, 5155 Verdant Drive, 46516, Elkhart, IN, United States  
dometic.com



NOTICE: This email and any attachments are for the sole use of the intended recipient(s) and may contain confidential information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please notify the sender by reply email and destroy the original message.

---

Ashlee Olsen <ashlee@dealer-advisors.com>  
To: CustomerSupportCenter <customersupportcenter@dometic.com>

Mon, Jun 8, 2026 at 10:12 AM

Good morning Kendra,

According to the tech, this test is what was performed. I have attached the requested photo's. Please let me know if you need anything further.

Thank you,  
Ashlee

[Quoted text hidden]

--  
Ashlee Olsen  
Warranty Administrator  
iClaims Services  
icclaimsservices.com  
208.716.2887

---

**3 attachments**



**LINE 1 (7.jpg**  
223K



**LINE 1 (6.jpg**  
240K



**LINE 1 (5.jpg**  
260K

---

CustomerSupportCenter <customersupportcenter@dometic.com>  
To: "ashlee@dealer-advisors.com" <ashlee@dealer-advisors.com>

Hello Ashlee:

We are still needing the areas that are highlighted from the diagnostic form that was submitted on 6/8/26 (shown below) for review.

condensing fins. If the unit is installed and vented properly but not cooling, perform test as follows.

Unplug the thermistor from the lower control board and run the  
**\*\*\*RM1350, RM3762, RM3962, & DMR702-D units need a spare the control board and hanging outside lower access door with above**

After 8 hours of running wide open, what is the substance temperature

\* 12V DC: 13.43 120V AC: 122.2 Heating Element

Heating Element Ohms: \_\_\_\_\_ Thermistor Ohms (while in ice)

**\*\*\* If the problem is specific to gas operation please provide**

Gas Pressure: 11" Gas Valve Ohms: \_\_\_\_\_

If a Complete fridge replacement is deemed necessary, will the fridge fit through

The substance temperature would be for the freezer and refrigerator.

Thank you.

Sincerely,

Consumer Satisfaction Survey!



**Kendra Vickers**

Customer Experience Rep, Consumer Escalation Rep,

Phone 800-544-4881

Dometic North America, 5155 Verdant Drive, 46516, Elkhart, IN, United States

dometic.com



NOTICE: This email and any attachments are for the sole use of the intended recipient(s) and may contain confidential information. Any unauthorized review, use, disclosure or distribution is prohibited. If you receive this message, you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake. Contact your supervisor if you have any questions. Thank you for your attention to this matter.

**From:** Ashlee Olsen <ashlee@dealer-advisors.com>

**Sent:** Monday, June 8, 2026 12:13 PM

To: CustomerSupportCenter <customersupportcenter@dometic.com>  
Subject: Re: Steven Black's RM2451 refrigerator

[CAUTION]: This email originated from outside Dometic. Do not click links or open attachments unless you recognize the sender and know the content is safe. Please use the "Report Phishing" button to report any suspicious emails to our Security Team. Read here for more information. Unsolicited emails (newsletters, sales, etc.) should not be reported as phishing, please delete or move those the junk inbox instead.

[Quoted text hidden]

This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. P mistake and delete this e-mail from your system.

---

**3 attachments**



**LINE 1 (7.jpg)**  
223K



**LINE 1 (6.jpg)**  
240K



**LINE 1 (5.jpg)**  
260K